



CAMPAIGN INSTRUCTION

MI No. 850-2300	Date July 2001	9-3
PI No.	Distr. US	

Recall 15200: Replacement of airbag alert label

Background

The sunvisors may have a thin layer of a silicone-like substance covering their surface, which could result in the airbag alert labels not sticking properly. To comply with FMVSS 208, these airbag alert labels must not be removeable without being destroyed.

Cars affected

Saab 9-3 3D and 5D M00-M01 within VIN Serial Number ranges:
Y2008679-12038552

Saab 9-3 Viggen 3D and 5D M00-01 within VIN Serial Number ranges:
Y7001740-17014005

NOTE: No Viggen Convertible models are affected.

Symptom description

The airbag alert label may start to come loose from the sunvisor.

Owner Notification

As much as possible, owners of affected vehicles will be notified by

Saab Cars USA, Inc. No VIN Status List will be supplied for this Campaign.

Please check your IRIS On-Line Recall/Campaign Inquiry to check for open campaigns.

Material

30 15 815 Cleaner, enough for 50-70 cars
50 10 103, Sticker, 2 pcs.

During the week of July 16, Saab Cars USA, Inc. will start shipping automatically to you 25% of the airbag alert labels for vehicles wholesaled to your dealership and one bottle of the cleaner. Additional quantities of parts and cleaner should be ordered using normal ordering procedures.

Tools:

Numeral 8 punch: 02 97 713

This tool can be ordered directly from Kent-Moore at 1-800-345-2233.

Warranty/Time Information:

Submit warranty claims using the following information:

FAILED OBJECT: 15200

FAULT/REASON: 35

LOCATION: 5

WARRANTY TYPE: 05

REPAIR/ACTION: 01

RECALL ACTION CODE (RAC): 3

LABOR OPERATION: 15200

TIME: 0.3

NOTE: Add \$1.00 in sublet for the cleaner.

Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.
© 2001 Saab Automobile AB. All rights reserved.

ENG



MODIFICATION INSTRUCTION

MI No. 850-2300	Date July 2001	9-3
PI No.	Distr. US	

Recall 15200: Replacement of airbag alert label

Background

The sunvisors may have a thin layer of a silicone-like substance covering their surface, which could result in the airbag alert labels not sticking properly. To comply with FMVSS 208, these airbag alert labels must not be removeable without being destroyed.

Cars affected

Saab 9-3 3D and 5D M00-M01 within VIN Serial Number ranges:

Y2008679-12038552

Saab 9-3 Viggen 3D and 5D M00-01 within VIN Serial Number ranges:

Y7001740-17014005

NOTE: No Viggen Convertible models are affected by this Recall.

Symptom description

The airbag alert label may start to come loose from the sunvisor.

Owner Notification

As much as possible, owners of affected vehicles will be notified by Saab Cars USA, Inc. No VIN Status List will be supplied for this Campaign.

Please check your IRIS On-Line Recall/Campaign Inquiry to check for open campaigns.

Parts required

30 15 815 Cleaner, enough for 50-70 cars

50 10 103, Sticker Airbag, 2 pcs.

During the week of July 16, Saab Cars USA, Inc. will start shipping automatically to you 25% of the airbag alert labels for vehicles wholesaled to your dealership and one bottle of the cleaner. Additional quantities of parts and cleaner should be ordered using normal ordering procedures.

Tools:

Numeral 8 punch: 02 97 713

This tool can be ordered directly from Kent-Moore at 1-800-345-2233.

<p>Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.</p> <p>© 2001 Saab Automobile AB. All rights reserved.</p>	ENG
--	------------

Procedure

Before any action is taken, the modification identity plate box B3 should be checked. If the box is not filled in, continue as follows:

- 1 Remove the old sticker from the left sun visor.
- 2 Thoroughly clean the sun visor with the cleaner on a lightly dampened cloth.

Note

It is very important that 30 15 815 Cleaner is used.

- 3 Fit the new sticker on the sun visor according to the figure.



- 4 Remove the old sticker from the right sun visor.
- 5 Thoroughly clean the sun visor with the cleaner on a lightly dampened cloth.

Note

It is very important that 30 15 815 Cleaner is used.

- 6 Fit the new sticker on the sun visor according to the figure.



Stamping the campaign plate

After taking these measures, box B3 on the campaign plate must be marked. Mark the box with a numeral "8" (Saab Special Tool P/N 02 97 713). If needed, order this special tool directly from Kent-Moore at 1-800-345-2233.

Warranty/Time information

See separate information.



CAMPAIGN INSTRUCTION

MI No. 850-2299	Date July 2001	9-5
PI No.	Distr. US	

Recall 15200: Replacement of airbag alert label

Background

The sunvisors may have a thin layer of a silicone-like substance covering their surface, which could result in the airbag alert labels not sticking properly. To comply with FMVSS 208, these airbag alert labels must not be removeable without being destroyed.

Cars affected

Saab 9-5 M00-M01 within VIN Serial Number Range:
Y3009837-13037540

Symptom description

The airbag alert label may start to come loose from the sunvisor.

Owner Notification

As much as possible, owners of affected vehicles will be notified by Saab Cars USA, Inc. No VIN Status List will be supplied for this Campaign.

Please check your IRIS On-Line Recall/Campaign Inquiry to check for open campaigns.

Material

10 15 815 Cleaner, enough for 50-70 cars
50 10 103, Sticker, 2 pcs.

Tools:

Numeral 8 punch: 02 97 713

This tool can be ordered directly from Kent-Moore at 1-800-345-2233.

Warranty/Time Information:

Submit warranty claims using the following information:

FAILED OBJECT: 15200

FAULT/REASON: 35

LOCATION: 5

WARRANTY TYPE: 05

REPAIR/ACTION: 01

RECALL ACTION CODE (RAC): 3

LABOR OPERATION: 15200

TIME: 0.3

NOTE: Add \$1.00 in sublet for the cleaner.

Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.
© 2001 Saab Automobile AB. All rights reserved.

ENG



MODIFICATION INSTRUCTION

MI No. 850-2299	Date July 2001	9-5
PI No.	Distr. US	

Recall 15200: Replacement of airbag alert label

Background

The sunvisors may have a thin layer of a silicone-like substance covering their surface, which could result in the airbag alert labels not sticking properly. To comply with FMVSS 208, these airbag alert labels must not be removeable without being destroyed.

Cars affected

Saab 9-5 M00-M01 within VIN Serial Number Range:
Y3009837-13037540

Symptom description

The airbag alert label may start to come loose from the sunvisor.

Owner Notification

As much as possible, owners of affected vehicles will be notified by Saab Cars USA, Inc. No VIN Status List will be supplied for this Campaign. Please check your IRIS On-Line Recall/Campaign Inquiry to check for open campaigns.

Material

10 15 815 Cleaner, enough for 50-70 cars
50 10 103, Sticker, 2 pcs.

During the week of July 16, Saab Cars USA, Inc. will start shipping automatically to you 25% of the airbag alert labels for vehicles wholesaled to your dealership and one bottle of the cleaner. Additional quantities of parts and cleaner should be ordered using normal ordering procedures.

Tools:

Numeral 8 punch: 02 97 713
This tool can be ordered directly from Kent-Moore at 1-800-345-2233.

<p>Saab Automobile AB Bulletins are intended for use by professional Saab technicians only, NOT a "do-it-yourselfer". They are designed to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Saab trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have the condition. See your authorized Saab Dealer for information on whether your vehicle may benefit from the information.</p> <p>© 2001 Saab Automobile AB. All rights reserved.</p>	ENG
--	------------

Procedure

Before any action is taken, the modification identity plate box B3 should be checked. If the box is not filled in, continue as follows:

- 1 Remove the old sticker from the left sun visor.
- 2 Thoroughly clean the sun visor with the cleaner on a lightly dampened cloth.

Note

It is very important that 30 15 815 Cleaner is used.

- 3 Fit the new sticker on the sun visor according to the figure.



- 4 Remove the old sticker from the right sun visor.
- 5 Thoroughly clean the sun visor with the cleaner on a lightly dampened cloth.

Note

It is very important that 30 15 815 Cleaner is used.

- 6 Fit the new sticker on the sun visor according to the figure.



Stamping the campaign plate

After taking these measures, box B3 on the campaign plate must be marked. Mark the box with a numeral "8" (Saab Special Tool P/N 02 97 713). If needed, order this special tool directly from Kent-Moore at 1-800-345-2233.

Warranty/Time information

See separate information.