

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 03V-035 by the
National Highway Traffic Safety Administration

Part 573 Report Date: February 4, 2003

Date Faxed: February 11, 2003

MANUFACTURER: **DaimlerChrysler Corporation**

MANUFACTURER CONTACT: **Mr. Stephan J. Speth, Director
Vehicle Compliance & Safety Affairs**


FAX: **248-576-7321**

SUBJECT: **1,066,000 DaimlerChrysler 1998-2002 Dodge Intrepid, Chrysler Concorde, 300M and 1998-2001 LHS model vehicles manufactured from September 1, 1997 through April 27, 2002. If the seat back unexpectedly reclines while the car is being driven, it could result in loss of vehicle control. Seat back recliner bolt breakage can occur resulting in the seat back reclining unexpectedly. DaimlerChrysler Recall No. C04.**

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers as well as an estimated owner notification schedule.

If you have any questions, please call:

 Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at pwallace@nhtsa.dot.gov
Recall Management Division