



---

**NISSAN NORTH AMERICA, INC.**

Corporate Office  
18501 South Figueroa St.  
Gardena, California 90248-4500  
Mailing Address: P.O. Box 191  
Gardena, California 90248-0191  
Telephone: 310.532.3111

January 5, 2005

Mr. George Person  
Chief, Recall Analysis Division  
Office of Defects Investigation  
Safety Assurance  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W.  
Washington, D.C. 20590

Ref: 03V-455

Dear Mr. Person:

The enclosed communication is being provided pursuant to 49 CFR Part 573.6(c)(9).

Technical Compliance Department

Encl.

03V-455

**Subject: Engine Sensors Replacement Voluntary Recall Campaign**

**Attention: Dealer Principals, Parts and Service Managers**

**\*\*\*\*\* Update to earlier InfinitiNet Messages \*\*\*\*\***

The purpose of this InfinitiNet message is to provide additional information related to the parts ordering process for this campaign. See below for additional details.

**\*\*\*\*\* Parts Ordering \*\*\*\*\***

Part Number 23731-4M527 CRANKSHAFT POSITION SENSOR has been removed from parts sales restriction and can now be ordered using the normal parts ordering process:

The kit is applicable to MY 2002 Q45 and MY 2003 M45 vehicles affected by this campaign.

**Note: Please discard all copies of the Engine Sensors Replacement Parts Order Form. Effective immediately, FAX orders for this campaign will no longer be processed.**

If you have any questions or need any additional information, please contact your Infiniti Dealer Parts and Service Manager (DPSM).

Infiniti Parts and Service Operations  
12/21/04