



Mercedes-Benz
RECEIVED
NVS-215

Mercedes-Benz USA, LLC
A DaimlerChrysler Company

VIA CERTIFIED MAIL

2003 JUN 20 P 1: 23

June 16, 2003

OFFICE OF
DEFECTS INVESTIGATION

National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Recall Analysis Division
Office of Defect Investigation
Washington, D.C. 20590

Attn: George Person, Chief

Re: 49 CFR Part 573; Recall of Mercedes-Benz M-Class

Dear Mr. Person:

Pursuant to 49 CFR Part 573.5(c)(9), this letter contains 3 documents that were communicated to our dealers on the above subject and will be submitted in Mercedes-Benz USA, LLC (MBUSA) regular monthly mailing for the month of June, 2003.

Manufacturer's Campaign Identification Number
2003040006

NHTSA Recall Number
03V-121

Sincerely,

Stephen Kraitz
Senior Staff Engineer
Product Compliance and Analysis

Enclosure



Safety Recall #2003-040005

June, 2003

Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. WE SENT YOU THIS NOTICE BECAUSE WE ARE CONCERNED ABOUT YOUR SAFETY.

DaimlerChrysler AG (DCAG) has decided that a defect which relates to motor vehicle safety exists in certain Model Year 1998-2003 M-Class vehicles. Mercedes-Benz USA, LLC (MBUSA) therefore has initiated a voluntary recall of these vehicles. Our records indicate that your vehicle is included in this group.

DCAG has determined that M-Class vehicles in this group have a hose clamp used to secure the power steering fluid cooling hose to the power steering fluid cooler which may not provide sufficient clamping force for this connection and must be replaced. A loss of power steering fluid may result in diminished power assist for steering the vehicle and ultimately can also damage the power steering pump. This could result in a loss of control and a crash without warning.

Your authorized Mercedes-Benz dealer is available to provide this service, free of charge. The working time required is approximately one half hour. We are sorry to inconvenience you, BUT IT IS IMPORTANT FOR YOUR SAFETY, AND THE SAFETY OF OTHERS, TO HAVE THE WORK PERFORMED IMMEDIATELY. Please contact your authorized Mercedes-Benz dealer to schedule an appointment. Please mention this is Safety Recall # 2003-040005.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee. If you have paid to have this recall condition corrected prior to this notice you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

Please contact your authorized Mercedes-Benz dealer should you have any questions or encounter any difficulty regarding this recall. If your dealer is unable to remedy your situation please contact us at 1-(800) FOR-MERCEDES. (1-800-367-6372).

If an authorized Mercedes-Benz dealer or Mercedes-Benz USA, LLC, fails or is unable to perform this power steering service without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 888-327-4236.

Again, we apologize for any inconvenience this situation may cause you.

Klaus Ulkann
Vice President, Customer Services

T-RC-2003040005