

Jenkins & Gilchrist Parker Chapin LLP

THE CHRYSLER BUILDING
405 LEXINGTON AVENUE
NEW YORK, NEW YORK 10174

Karen F. Lederer
(212) 704-6319
klederer@jenkens.com

(212) 704-6000
FACSIMILE (212) 704-6288

www.jenkins.com

October 21, 2003


By Facsimile
Ms. Kelly Schuler
National Highway Traffic Safety Administration
400 7th Street, SW
Washington, DC 20590

Re: Intercontinental Auto Parts
Recall # 03E-045

Dear Kelly:

Enclosed please find a recall poster, which I am submitting for your approval. This poster would be sent to our customers for transmittal, in turn, to their customers which we understand are retail auto parts stores, for posting at those stores.

Very truly yours,



Karen F. Lederer

KFL:la
Encl.

ATLANTA, TEXAS
(512) 499-8800

CHICAGO, ILLINOIS
(312) 425-8900

DALLAS, TEXAS
(214) 853-4500

HOUSTON, TEXAS
(713) 961-8800

LOS ANGELES, CALIFORNIA
(818) 620-8800

PASADENA, CALIFORNIA
(626) 878-7600

SAN ANTONIO, TEXAS
(210) 346-8000

WASHINGTON, D.C.
(202) 516-1500


SAFETY RECALL OF REPLACEMENT FUEL FILTERS

Certain replacement fuel filters sold after September 17, 2002 have been recalled by the manufacturer. The recalled units were manufactured between September 17, 2002 and January 20, 2003, for use on 1995-2004 Chrysler Town & Country, Plymouth Voyager and Dodge Caravan Minivans.

- For 1995-2000 short wheelbase Chrysler Town & Country, Plymouth Voyager and Dodge Caravan minivans – the recalled fuel filters have Part Number 18232 and Date Code 0237, 0249 or 0252
- For 1995-2000 long wheelbase Chrysler Town & Country, Plymouth Voyager and Dodge Caravan minivans – the recalled fuel filters have Part Number 18230 and Date Code 0237, 0249, 0251 or 0304
- For 2001-2004 Chrysler Town & Country, Plymouth Voyager and Dodge Caravan minivans – the recalled fuel filters have Part Number 28871 and Date Code 0249

These part numbers and date codes appear on the gold-tone filter.

Original equipment factory-installed by Daimler Chrysler is not affected.



The Quick Connectors may malfunction, either blocking fuel flow to the engine or causing a fuel leak. If this condition occurs while the vehicle is in motion, the engine could stall. Also, in the presence of an ignition source, the fuel leak could result in a vehicle fire.

Owners who have had the fuel filter serviced on one of the applicable vehicles after September 17, 2002 should return their vehicle to the service facility to be inspected to see if the fuel filter that was installed is one that is involved in the recall. If so, owners should call Intercontinental Auto Parts, Inc. at 201-529-1988 to arrange for a free replacement.

Remember, the only recalled units are those replacement filters with the part numbers and date codes shown above.

If you have any questions, call the National Highway Traffic Safety Administration Auto Safety Hotline at
1-888-327-4236