

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Report¹

04V-448
(6 pages)

On September 6, 2004, Hino Motors Sales U.S.A., Inc. decided that (a defect which relates to motor vehicle safety)(a noncompliance with Federal Motor Vehicle Safety Standard No. _____) exist in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

Date this report was prepared: September 8, 2004

Furnish the manufacturer's identification code for this recall (if applicable): A3740

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Hino Motors Sales U.S.A., Inc.

25 Corporate Drive, Orangeburg, NY 10962

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

George M. Daniels

Senior National Manager, Parts & Service

Telephone Number: 845-365-1400 ext. 312 Fax No.: 845-365-1495

Name and Title of Person who prepared this report.

Eric Lannon
Warranty Manager

Signed: _____

RECEIVED
JUN SEP 20 A 10 11
OFFICE OF DEFECTS
INVESTIGATION

¹Each manufacturer must furnish a report, to the Associate Administrator for Safety Assurance, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

Make(s): Hino **Model Years Involved:** 2005 **Model(s):** NA6J,NB6J,NC6J,ND8J,NE8J,NV8J

Production Dates: Beginning: 10/1/03 **Ending:** 9/7/04

VIN Range: Beginning: JHBNA6JF351S10013 **Ending:** JHBNV8JT851S10482

Vehicle Type: CAB & CHASSIS **Bodystyle:** N/A

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

All vehicles produced during this time period are affected.

Make(s): _____ **Model Years Involved:** _____ **Model(s):** _____

Production Dates: Beginning: _____ **Ending:** _____

VIN Range: Beginning: _____ **Ending:** _____

Vehicle Type: _____ **Bodystyle:** _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Make(s): _____ **Model Years Involved:** _____ **Model(s):** _____

Production Dates: Beginning: _____ **Ending:** _____

VIN Range: Beginning: _____ **Ending:** _____

Vehicle Type: _____ **Bodystyle:** _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Widgets equipped with certain items of equipment from January 1, 1996 through April 1, 1997, then what was the percentage of the recalled Widgets of all Widgets manufactured during that time period.

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

| Model | Year | Number of Vehicles Potentially Involved |
|--------------|-------------|--|
| <u>NA6J</u> | <u>2005</u> | <u>378</u> |
| <u>NB6J</u> | <u>2005</u> | <u>258</u> |
| <u>NC6J</u> | <u>2005</u> | <u>335</u> |
| <u>ND8J</u> | <u>2005</u> | <u>92</u> |
| <u>NE8J</u> | <u>2005</u> | <u>1571</u> |
| <u>NV8J</u> | <u>2005</u> | <u>484</u> |
| <u>NJ86</u> | <u>2005</u> | <u>248</u> |

Total Number Potentially Affected by the Recall: 3366

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance: 100%

Identify and describe how the recall population was determined—in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

All vehicles 2005 conventional model trucks are affected.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

When the steering wheel is being turned the dust cover may twine with the steering shaft and could result in the steering wheel operation becoming heavy. This could result in a loss of steering control.

Describe the cause(s) of the defect or noncompliance condition.

The design of the current boot allows for the possibility off the boot to become bound to the steering shaft

Describe the consequence(s) of the defect or noncompliance condition.

This can cause the steering to become sluggish

Identify any warning which can (a) precede or (b) occur.

None

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

Not applicable

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

Not applicable

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims. One is occurred at the vehicle delivery from the dealer to the customer.

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

V. Identify the Remedy

8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

Remove the old dust cover and install the newly designed cover.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

Recalled component: No Difference

Remedy component: No Difference

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

9/20/04 - Notify Dealers

9/25/04 - Notify Customers

VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. A *DRAFT* copy of the notification documents should be submitted to this office by Fax (202-366-7882) for review prior to mailing.

Note that these documents are to be submitted separately from those provided in accordance with Part 573.8 requirements.