



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

400 Seventh Street, SW  
Washington, DC 20590

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION  
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-478** by the  
National Highway Traffic Safety Administration

Part 573 Report Date: **September 24, 2004**

Date Faxed/E-Mailed: **October 18, 2004**

MANUFACTURER: **Mitsubishi Fuso Truck of America, Inc.,**

MANUFACTURER CONTACT: **William Mohr, Director, Service Operations**

FAX: **856-467-4665**

**SUBJECT: 2,537 Mitsubishi Fuso 2003-2004 FH201, FH211, FK617, and 2005 FK61F trucks equipped with an F040T front axle. The front wheel hub outer bearing lock out may have been improperly tightened during assembly, and an insufficient amount of grease may have been applied to the outer bearing.**

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

**NOTE: Please provide us with a draft owner notification letter for our review before mailing to consumers along with an owner notification schedule.**

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [Patricia.Wallace@nhtsa.dot.gov](mailto:Patricia.Wallace@nhtsa.dot.gov)  
Recall Management Division