

04V-156

Triumph Motorcycles Notice : Fuel Connector Recall Update

Notice Information

Posted To: Service and Technical, Parts
Subject: Service/Technical
Posted Date: 9/29/2004 8:55:53 PM

Notice History

Open Date: 9/30/2004 8:05:27 PM
Read: 9/30/2004 8:06:39 PM



FUEL CONNECTOR RECALL UPDATE

Dear Service Manager,

We have had some small amount of feedback from some dealers claiming that the connector sizes referenced in the recall fuel connector service bulletins are incorrect. Notably, that a model originally fitted with (say) 2 x 10mm connectors from new, is now (according to Bulletin instructions) to be fitted with 1 x 10mm plus an 8mm.

Please note however that the above scenario does not represent an error.

It should be noted that the bulletin text also calls for dealers to trim the end of the fuel hose in all cases (to ensure the fresh area of hose pushed over the connector is compliant and will provide best fit). Though not immediately visible to the naked eye, some of the hoses fitted from new are flared (i.e.: an 8mm diameter hose, which is flared to 10mm). If the bulletin instructions are carried out correctly, the technician will be cutting off the flared end (10mm), thus providing an 8mm fresh end for connection to the 8mm aluminum connector provided via the bulletin.

We trust the above explanation is clear and will remove any existing confusion.

Kind regards

Charles Smart
Dept Head, Warranty & Customer Services