

[Next Unread Message](#)

[View Message](#)

---

Sent On 

06	07	2004
----	----	------

 Expires On 

06	30	2004
----	----	------

  
From 

Parts and Service Division
----------------------------

  
Subject 

Non-Compliance Recall Announcement
------------------------------------

DATE: June 7, 2004

TO: All Honda Sales, Service & Parts Managers

FROM: American Honda Service Division

RE: Non-Compliance Recall Announcement

Honda Motor Co., Ltd., has announced to NHTSA (National Highway Traffic Safety Administration) its intention to recall certain 2000 M/Y S2000s.

**Basic Problem:** The lens of the side marker lamp and side reflex reflector in the tail lamp assembly were manufactured with incorrect dye that, under the circumstances of use, does not retain its color over time and, therefore, does not comply with the requirements of Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment."

**Support Materials:** On June 16, 2004, American Honda will post on ISIS its Non-Compliance Recall S/B.

**Campaign Parts:** AH Parts Division will allocate a quantity of tail lamp assembly kits to every Honda Dealership on June 16, 2004.

**Repair Strategy:** The repair involves the replacement of both tail lamp assemblies on selected 2000 M/Y S2000s.

**Customer Notification:** Approximately 7,000 vehicles are affected by this Non-compliance Recall Campaign. Notifications will be mailed to all known owners (approximately July 6, 2004). You will be notified of the exact customer mailing date by IN.

© 2000-2004, American Honda Motor Co., Inc. All Rights Reserved.