



Facsimile

Arent Fox
ATTORNEYS AT LAW

Date: March 3, 2006
Pages (including cover): 8
Attorney #: 0047
Client.Matter #: 016606 00000

Lawrence F. Henneberger
202/857-6087 DIRECT
hennl@arentfox.com

PLEASE DELIVER TO:

Name/Company	Fax #	Verify #
George Person/Kelly Schuler Office of Defects Investigation	202/366-7882	202/366-5232

MESSAGE/INSTRUCTIONS

Re: Harley-Davidson Recall 04V-607; 04E-094; NVS-215kjs

George/Kelly: As I discussed with Kelly yesterday, Harley-Davidson, which has an internal policy of pursuing second notices on recalls where the Company considers the completion rate inadequate, undertook this process several weeks ago with respect to safety recall 04V-607, the fuel shut-off valve campaign involving certain 2005 carbureted Sportster, Dyna, Softail and Touring model motorcycles. Contemporaneously, Harley issued a second notice on its recall 04E-094, involving certain fuel valve parts/kits sold through its dealer network.

Because of a misunderstanding on my part regarding whether someone within Harley-Davidson or I would make the submission to NHTSA/ODI, I did not file it with you in early February when these two second notice recall document packages went out to the field. I apologize for my error in not getting them to you sooner. As you will note from the attachments, the second notice customer letter went out to owners on February 3, 2006.

I believe the fuel shut-off valve campaign second notice materials are responsive to George Person's letter of February 24, 2006, and again, emphasize that Harley-Davidson shares the position of NHTSA/ODI that supplemental efforts should be undertaken to notify affected owners in those cases where completion rates are below desired objectives.

Attachments

cc: Robert J. Brand, Esq. (w/o attachments)
Mr. Ron Mundt (w/o attachments)
Ms. Lisa Garner (w/o attachments)

PLEASE CALL OUR FAX OPERATOR AS SOON AS POSSIBLE IF TRANSMISSION IS NOT COMPLETE: 202/857-6119

This facsimile contains privileged and confidential information intended only for the use of the addressee(s) named above. If you are not the intended recipient of this facsimile, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that any dissemination or copying of this facsimile is strictly prohibited. If you have received this facsimile in error, please immediately notify us by telephone and return the original facsimile to us at the address below via the postal service.



Harley-Davidson Motor Company, 3700 West Juniper Ave., PO Box 659, Milwaukee, WI 53201 414/342-4680

January 31, 2006

SERVICE LETTER ML-410
NHTSA # - 04E-094 & 04V-607

IMPORTANT SAFETY RECALL CAMPAIGN INFORMATION!

Dear Dealer,


In a continuing effort to increase the completion rates of our safety recalls we have established a procedure to send follow-up notifications to the motorcycle owners of record who haven't had their motorcycles serviced in response to selected recalls. This communication and the attached sample Customer Letter relate to the following recall.

CODE 0118 FUEL SHUT-OFF VALVE CARB

This recall relates to certain 2005 carbureted Sportsters, Dyna, Softail and Touring model Motorcycles and in some fuel valve parts/kits. The recall was initiated in January 2005. A sample of the follow-up letter, which we are sending to all registered owners of unserviced vehicles, is attached. Also attached is an updated list of Code 0118 vehicle VINs which our records show as still being unserviced. Refer to Harley-Davidson Service Bulletin M-1167 dated January 26, 2005 for details on carrying out the requirements for this recall. Parts for this recall are currently available. Current shipment records indicate a number of kits are available in the field at the dealer level. Please check your inventory before placing any orders for parts. You may be required to provide a VIN for each recall kit ordered. Please refer to the related Service Bulletin for detailed instructions.

If a VIN appears on this list for a vehicle on which you have recently completed this recall, please disregard. DO NOT send in a duplicate service card. However, if a vehicle appears on the list that you know you have completed the recall on some time ago, please fill out a Dealer Service Card and attach a copy of your internal repair order to the card. We will use this information to update our records and issue you the appropriate amount of labor for performing the service. This information will be essential in reporting our completion rates to NHTSA, as required.

Your cooperation in this effort is appreciated.

Sincerely,

Sarah S. Ottallah
Manager, Warranty and Recall Administration
0118



Harley-Davidson Motor Company, 3700 West Juneau Ave., PO Box 683, Milwaukee, WI 53201 414/342-4680

SAFETY RECALL SECOND NOTICE

February 3, 2006

NHTSA # - 04E-094 & 04V-607

Dear Harley-Davidson Motorcycle Owner:

In January 2005, you and other registered owners were notified by the attached letters that a defect which relates to motor vehicle safety exists on certain 2005 carbureted Sportsters, Dyna, Softail and Touring model Motorcycles and in some fuel valve parts/kits. These parts/kits consist of four separate part numbers as follows: Part # 61338-02, 62169-02A, 61338-94D and 62169-95C. This is a follow-up to that earlier communication.

Our records indicate you have not responded to our recall notice. Therefore, we are sending you this second notice in order to re-emphasize the importance of having your motorcycle serviced immediately to remedy the safety issues described in our earlier letter.

Please contact your Harley-Davidson dealer immediately for an appointment to have your motorcycle serviced according to instructions contained in the letter attached.

If your dealer has already serviced your motorcycle under this recall, you are receiving this letter because we have not been notified that the work had been completed. We ask that you take the enclosed service card to your dealer, have it completed, signed by you and your dealer, and returned to us for our records as required by law. (Disregard this instruction if you have had the service completed recently, since it takes some time for mailing and our processing of information). This will assist us in accurately reporting vital information to NHTSA about your vehicle, as required by law.

If you have sold your motorcycle, please fill out and mail the enclosed Motorcycle Owner Card with the appropriate information about your purchaser. This will enable us to contact him/her and advise that person of this recall.

Sincerely,

Harley-Davidson Motor Company, Inc.
Attachments
0118