



A DaimlerChrysler Company

Freightliner LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

November 2004
FL420A
(NHTSA #04V-205)
REMINDER NOTICE

Subject: Transmission Shift Levers

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act and the Canadian Motor Vehicles Safety Act.

Freightliner LLC, on behalf of its Freightliner Trucks Division and its wholly owned subsidiary, Sterling Truck Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Freightliner Century Class S/T and Columbia vehicles manufactured between October 17, 2003, and January 31, 2004; Freightliner Business Class M2 vehicles manufactured between May 3, 2003, and January 31, 2004; and Sterling A-/L-Line and Acterra vehicles manufactured between November 23, 2003, and January 31, 2004, with manual transmissions and straight shift levers (except automated manual transmissions).

The tapered joint that attaches the shift lever to the transmission may separate, making it difficult to put the transmission into gear. If shift lever detachment occurs, the ability to accelerate or maintain speed will be lost, increasing the risk of a crash.

The shift lever will be re-secured to the transmission using threadlock and re-torquing the fastening bolt.

Our records indicate that your vehicle(s) has not yet had this recall performed. Please make arrangements to have this repair done as soon as possible. If it has been completed, please disregard this letter.

Repair kits are now available for authorized dealers to order. Contact your authorized dealer to arrange to have your vehicle(s) modified and to assure that parts are available at the dealer.

When you contact your dealer, refer to campaign number **FL420A**. Once kit(s) are received at the dealership, the modification will take approximately one hour and will be performed at no charge to you.

IMPORTANT: When the recall has been completed, please ensure that a label has been affixed to your vehicle referencing **FL420A** and the date the work was performed.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, please make sure this notification is immediately forwarded to the lessee.

If you are unable to have the defect remedied without charge and within a reasonable time after you tender the vehicle for repair, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, or the Customer Assistance Center at (800) FTL-HELP, after normal business hours. You may also wish to notify the Administrator, National Highway Traffic Safety Administration, 400 7th Street S.W., Washington, D.C. 20590, or phone (888) 327-4236. If your vehicle is involved in the Canadian portion, you may notify the Manager, Recall and Public Compliance, Road and Motor Vehicle Traffic Safety Branch, Transport Canada, Ottawa, Ontario, or phone (613) 993-9851.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

Freightliner LLC is a Member
of the Daimler-Benz Group

