

RECEIVED

R04HT

2004 JUN -2 A 11:05

OFFICE OF DEFECTS  
TRUCKS AND BUSES

04V-222

June 08, 2004

Dear Blue Bird Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Blue Bird Body Company has decided that a defect which relates to motor vehicle safety exist in certain 2004 and 2005 model year Blue Bird All American front engine school and transit buses equipped with Option 2836-01 Driver's 3-Point Seat Belt. The subject buses were manufactured at Canadian Blue Bird in Brantford, Ontario from March 03, 2003 through April 05, 2004.

The defect involves the fasteners that retain the 3-point driver's seat belt shoulder strap upper attachment. Incorrect fasteners were originally installed. Blue Bird is conducting a recall to correct this defect.

Blue Bird Body Company's evaluation of the risk to motor vehicle safety reasonably related to this defect is in the event of a crash, the shoulder strap could fail, and the driver could be injured.

Special equipment is required to install the correct fasteners. Your Blue Bird distributor will contact you to schedule a time to perform Recall R04HT.

If you have a qualified technician and the special equipment necessary you may perform this recall. Please advise your distributor that you will be performing the modification. When modifications are completed reimbursement for labor may be obtained by completing the pink request for reimbursement sheet provided and returning it to Blue Bird in the enclosed pink postage prepaid envelope. Labor time required to perform Recall R04HT is 0.5 hours (30 minutes) per bus.

Your Blue Bird bus(es) affected by recall R04HT are identified by body serial number(s) on the enclosed reply sheets. If you no longer own the subject bus(es), please complete the appropriate section of the yellow reply sheet and return to Blue Bird in the enclosed pink postage prepaid envelope.

If the modifications/repair directed by this modification was performed on your bus prior to the receipt of this recall notification, complete and sign the recall reply sheet and attached a copy of the work order/invoice. Mail the documents in the pink self-addressed postage paid envelope included with the recall notification to Blue Bird for warranty consideration. Reimbursements will be made in accordance with the requirements of the National Highway Transportation Safety Act, title 49 Code of Federal Regulations, Parts 573 and 577.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If Blue Bird Body Company should fail to or is unable to remedy this condition without charge to you, you may contact:

**ADMINISTRATOR  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
400 SEVENTH STREET, SW  
WASHINGTON, D.C. 20590**

or you may call The National Highway Traffic Safety Administration toll free at:

**1-888-327-4236**

Questions regarding this recall campaign should be directed to me at (478) 822-2242.

Thank you,

**Bill Coleman  
Recall Administrator  
BLUE BIRD BODY COMPANY**

**R04HT**

**DATE: JUNE 04, 2004**  
**TO: U.S. DISTRIBUTORS**  
**SUBJECT: RECALL R04HT INCORRECT FASTENERS IN DRIVER'S  
3-POINT SEAT BELT UPPER ATTACHMENT**

This notice is sent to you in accordance with the requirements of The National Traffic and Motor Vehicle Safety Act.

Blue Bird Body Company has determined that a defect which relates to motor vehicle safety exists in certain 2004 and 2005 model year Blue Bird All American front engine school and transit buses equipped with Option 2836-01 Driver's 3-Point Seat Belt. The subject buses were manufactured at Canadian Blue Bird in Brantford, Ontario from March 03, 2003 through April 05, 2004.

Blue Bird is conducting a recall to correct this defect. Buses with the defect must be corrected according to the instructions provided with recall R04HT, copy attached.

If our records indicate affected units were delivered in your service area, a printout identifying affected units is enclosed. Distributors should verify correct owners and that complete shipping addresses are provided for each listed vehicle. If you have in your possession or have sold a vehicle that was purchased from another distributor that may be affected by this recall, please notify me at 478-822-2242.

Due to the special tools required to perform Recall R04HT, owners are being advised they will be contacted by their distributor to schedule a time to perform this recall. Time required to perform Recall R04HT is 0.5 hours per bus.

A limited number of tools are available for this campaign. The Recall Administrator will coordinate availability of the tools with input from Blue Bird customer service.

Warranty applications may be submitted to Blue Bird VIA BBOND (use CBCLAIM in the warranty menu).

**Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.**

**Distributors are reminded of their responsibilities under section 154 of The National Traffic and Motor Vehicle Safety Act of 1991. Dealers are required to complete modifications/repairs on units in their inventory before delivering to the final owner. Reference Blue Bird Body Company Distributor Memo No. 42-92.**

**Questions regarding this recall campaign should be directed to me at (478) 822-2242.**

**Thank you,**

**Bill Coleman  
Recall Administrator**