

## Vehicle Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 1/11/2006

Calendar Quarter: 4th

Safety Recall Quarterly Report from 10/05 through 12/05

Reporting Quarter: Final

Manufacturer: Subaru of America, Inc.

Report Author: Brian DeAscentiis

Phone: (856) 488-3465

Recall Subject: Left Front Seat Slide Rail Bolt

1. NHTSA Safety Recall Campaign Number: 04V-342

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: WWT-04

2. (a) The date notification to purchasers began: 08/20/04, Second Notice: 5/27/05

(b) The date notification of purchasers was completed: 08/20/04, Second Notice: 5/27/05

3. The Total Number of Items Involved: 84,174, Second Notice: 40,240

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected and Remedied: 52,827

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0

Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3,083

Total Number Otherwise Unreachable: N/A