



2004 MAR 30 A 8:50

OFFICE OF
DEFECTS INVESTIGATION

March 29, 2004

Mr. Kenneth N. Weinstein
National Highway Traffic Safety Administration
U.S. Department of Transportation
400 Seventh Street, S.W.
Washington, DC 20590

**Subject: Recall Number 04V-130
2002-2004 Model Year Bentley Arnage R, RL, T, and LIMOUSINE
Bentley Recall Number RE04/02**

Dear Mr. Weinstein:

With regard to the above recall and our filing of part 573, please find attached the final customer and dealer information letters.

Sincerely,

David M Parker
National Manager, Quality, Parts & Service

Enc.



Parts & Service Information Letter

No: 04#08

March 15, 2004

To: Service Manager
Cc: Dealer Principal
General Manager

RE: RECALL CAMPAIGN - FUEL PIPE QUICK CONNECTORS - FEED AND RETURN - SAFETY CLIP FITMENT - REM0402

It has been determined that the potential exists, following disconnection, for the feed and return fuel line quick connectors not to be fully re-engaged. This would eventually result in loss of fuel that, in the presence of an ignition source, creates a risk of a vehicle fire. Disconnection is a requirement for some service operations.

This information letter is to initiate a recall campaign to remove the plastic quick-release collar from both the feed and return fuel line quick connectors, ensure their full re-engagement and instruct the fitment of a safety clip to each connector on certain 2002-2004 Model Year Bentley Arnage R, T, RL and Limousine cars manufactured between September 2001 and February 2004.

The attached Bulletin (04-01-31-01) and list of all affected VINS details the repair procedures to be followed. Whilst your technicians may consider themselves familiar with this joint, it is vitally important that the exact procedure is followed.

Federal law prohibits the sale of any vehicle containing a potential safety defect prior to correction. It is therefore imperative that you do not deliver an affected vehicle from your own vehicle inventory to a retail customer prior to performing the corrective repair. Bentley Motors, Inc. will notify all known owners of retailed vehicles by first class mail, on or about, March 22, 2004.

The necessary safety clips (part number PF113200PA) and a quantity of completion labels (part number PS113433PA) will need to be ordered by you according to your vehicle parc. Parts are currently available in our Crewe warehouse.

A Class E warranty claim is to be generated upon completion of the work. This claim may not contain any other warranty repairs. The Man Hour Schedule time and codes are quoted within the Bulletin. Warranty claims should be submitted promptly to enable us to monitor our performance in this Campaign. You do not require an authorization.

It is to our mutual advantage that this recall campaign goes as smoothly as possible. Should you have any questions or queries concerning this recall, please contact your ASM.

Yours sincerely

David M Parlier
National Manager - Quality, Parts & Service
Enc.

1. Bentley Bulletin (Service Managers only)
2. VIN list (Service Managers only)



BENTLEY

Bulletin 04-01-31-01

Title: Recall RE 04/02

FUEL PIPE QUICK CONNECTORS – FEED AND RETURN - SAFETY CLIP FITMENT

Applicability:

Bentley Amage R, RL, T & Limousine
For specific VIN's refer to attached list.

Market Region:

All

Description:

Whilst carrying out spark plug replacement on the above vehicles the procedure described in ASSIST requires the disconnection of the feed & return fuel line quick connectors adjacent to B3 spark plug.

On the occasion that the ASSIST procedure relating to reconnection of fuel quick connectors is not strictly adhered to a dormant failure may be produced in either of the quick connectors.

The subsequent failure of the quick connector would result in loss of fuel, which in the presence of an ignition source creates a risk of vehicle fire.

To eliminate the possibility of either quick connector suffering an unintended disconnection both quick connectors are to have their release collars removed and an additional safety clip fitted.

The following procedure must be carried out on all vehicles on the attached VIN list.

The technician carrying out this procedure must have its completion independently inspected & the workshop job card signed to verify.

Procedure:

1. Apply the foot operated parking brake and chock the front wheels
2. Raise bonnet to service position ASSIST PIN 6103
3. Remove engine cover ASSIST PIN 0950
4. Disconnect both batteries ASSIST PIN 5903
5. Remove right hand torsion strut, replace the damper retaining nuts loosely ASSIST PIN 6012

Ensure the engine is cool (if in doubt, wait approximately 30 minutes)

This procedure is to be applied to the fuel feed and fuel return line, the following operation is therefore to be carried out on both quick connectors.

Caution:

Ensure that an absorbent cloth is placed around each connector as it is released, to catch any escaping fuel

The following recommendations regarding fitting and servicing of quick connectors must be observed;

Disconnecting

Using a cloth or soft brush, wipe the external surface of the connector and male tube to remove loose dirt and road salt. Twist the connector about the tube or flush the joint with a mild penetrant such as WD 40 or CRC spray to remove any stubborn crusted contaminants.

Using an air line, blow out any accumulated dirt and road salt from the retainer area of the connector.

6. Push back the release collar and simultaneously pull the hose from the pipe fitting. Refer to figure 1.

Do not allow dirt or any foreign matter to contaminate the lines.

7. Remove and discard the release collar, using suitable pliers, from both quick connectors Refer to figure 2 & 3.

After the removal process, ensure no remaining parts of the collar are in the quick connector.

8. Position any rubber identification sleeves fitted to the tube end at least 25mm (1 inch) away from the bead.
9. Use a clean cloth and wipe the tube end.
10. Check the 'O' rings in the fuel hose and the sealing surfaces on the fuel pipe for damage .
11. Apply a coating of clean engine oil over the entire male tube end surface, up to the bead. Note petrol must not be used as a substitute as it will increase the friction.
12. Push the quick connector fitting over the tube until the retainer seats, with an audible click.

Warning:

Do not rely on an audible click to confirm that a secure connection has been made.

To ensure that a secure connection has been made and has locked in position, pull back the quick connector (between 6.8 and 13.6kgf; 15 and 30 lbf).

13. Fit a secondary retaining safety clip part number PF113200PA to the quick connector Refer to figure 4.
14. When the procedure has been carried out on both the fuel feed and fuel return quick connectors reconnect both batteries ASSIST PIN 5903.
15. Observing the relevant workshop safety procedures Refer to ASSIST PIN 00 39. Turn on the ignition and allow at least 5 seconds for the fuel system to pressurise then check the quick connectors for leaks.
16. Start engine and once again check pipe connections for leaks and if necessary rectify.
17. Refit right hand torsion strut ASSIST PIN 6012.
18. Fit label part number PS113432PA In position shown. Refer to figure 5.
19. Take bonnet out of service position refer to ASSIST PIN 8103.
20. Refit engine cover refer to ASSIST PIN 0950.

Warranty:

| Procedure | Defect Code | Repair Code | Time |
|----------------------|----------------|---------------|------|
| Fuel Hose Connectors | 31-50-41-98-00 | 31-50-41-98-S | .9 |

On completion of the work, a class E warranty claim should be submitted.

Parts Information:

| NEW PART NUMBER | DESCRIPTION | DISPLACED PART NUMBER | QUANTITY |
|-----------------|--------------------------|-----------------------|----------|
| PS113432PA | Label | N/A | 1 |
| PF113200PA | Secondary retaining clip | N/A | 2 |

Torque Specification:

| Component | Nm | Kgf m | lbf ft |
|-----------------------|-----|-------|--------|
| Bulkhead fixing – 8mm | 9.5 | 0.97 | 7 |
| Damper tower nuts | 47 | 4.8 | 34.66 |

Policy: Recall




Fig 1



Fig 2




Fig 3




Fig 4




Fig. 5

Bentley Bulletins are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to an Authorised Bentley Dealer or other qualified workshop. See your Bentley Dealer for advice on whether your vehicle may benefit from the Information contained within this document.

The information contained in the Bentley Bulletin is accurate at the date of publication. However, Bentley Motors regularly updates technical information. Please check with your Bentley Dealer that the Bulletin you intend to use contains the latest available Information.

© Bentley Motors Limited 2004 All Rights Reserved

RECALL RE04/02 AFFECTED VIN LIST

SCBLE37G83CX19182
SCBLM90A23CX19190
SCBHE31E72CH99170
SCBDR35X32CH00049
SCBLF34F72CH00150
SCBLF34F72CX08200
SCBLF34F92CX08201
SCBLF34FX2CX08286
SCBLF34F82CH08287
SCBLF34F32CX08288
SCBLF34F82CH08306
SCBLF34FX2CH08307
SCBLF34F52CX08308
SCBLF34F32CH08309
SCBLF34F32CX08310
SCBLF34F52CH08313
SCBLF34F72CH08314
SCBLF34F22CX08315
SCBLF34F02CH08316
SCBLF34F62CX08317
SCBLF34F82CX08318
SCBLF34F82CH08319
SCBLF34F22CH08320
SCBLF34F82CX08321
SCBLF34FX2CX08322
SCBLC37F22CH08323
SCBLF34F32CX08324
SCBLF34F52CX08325
SCBLF34F32CH08326
SCBLF34F92CX08327
SCBLF34F82CH08354
SCBLF34FX2CH08355
SCBLF34F12CH08356
SCBLF34F72CX08357
SCBLF34F92CX08358
SCBLF34F72CH08359
SCBLF34F72CX08360
SCBLF34F92CX08361
SCBLF34F02CX08362
SCBLF34F92CH08363
SCBLF34F02CH08364
SCBLF34F82CX08365
SCBLC37F22CX08366
SCBLF34FX2CX08367
SCBLF34F82CH08368

SCBLC37F83CX08972
SCBLC37FX3CX08973
SCBLC37F83CH08974
SCBLC37F33CX08975
SCBLF34F73CH08976
SCBLC37F73CX08977
SCBLF34F03CH08978
SCBLC37F03CX08979
SCBLC37F73CX08980
SCBLC37F93CX08981
SCBLC37F03CX08982
SCBLF34F43CH08983
SCBLF34FX3CX08984
SCBLF34F13CX08985
SCBLC37F83CX08986
SCBLC37F83CH08987
SCBLF34F33CH08988
SCBLC37F33CX08989
SCBLC37FX3CX08990
SCBLC37F13CX08991
SCBLC37FX3CH08992
SCBLC37F53CX08993
SCBLC37F73CX08994
SCBLC37F93CX08995
SCBLC37F73CH08996
SCBLC37F93CH08997
SCBLC37F43CX08998
SCBLC37F63CX08999
SCBLC37F73CX09000
SCBLF34F43CX09001
SCBLC37F03CX09002
SCBLF34F83CX09003
SCBLC37F43CX09004
SCBLC37F63CX09005
SCBLF34FX3CH09006
SCBLF34F13CH09007
SCBLF34F33CH09008
SCBLF34F53CH09009
SCBLF34F13CH09010
SCBLF34F33CH09011
SCBLF34F53CH09012
SCBLC37F13CH09013
SCBLC37F73CX09014
SCBLC37F53CH09015
SCBLF34F23CH09016

SCBLC37F13CX09512
SCBLF34F53CH09513
SCBLF34F03CX09514
SCBLC37F33CH09515
SCBLF34F43CX09516
SCBLF34F63CX09517
SCBLC37F23CX09518
SCBLF34FX3CX09519
SCBLF34F23CH09520
SCBLF34F83CX09521
SCBLF34F83CH09522
SCBLF34F13CX09523
SCBLC37F83CX09524
SCBLF34F13CH09525
SCBLF34F73CX09526
SCBLF34F93CX09527
SCBLF34F73CH09528
SCBLC37F73CX09529
SCBLF34F53CH09530
SCBLF34F03CX09531
SCBLF34F23CX09532
SCBLF34F03CH09533
SCBLC37F03CX09534
SCBLC37F23CX09535
SCBLF34FX3CX09536
SCBLF34F13CX09537
SCBLF34F33CX09538
SCBLF34F53CX09539
SCBLF34F13CX09540
SCBLF34F33CX09541
SCBLF34F53CX09542
SCBLF34F33CH09543
SCBLC37F33CX09544
SCBLF34F73CH09545
SCBLF34F23CX09546
SCBLF34F43CX09547
SCBLF34F63CX09548
SCBLC37F23CX09549
SCBLF34F43CX09550
SCBLC37F73CH09551
SCBLF34F83CX09552
SCBLC37F43CX09553
SCBLC37F63CX09554
SCBLC37F83CX09555
SCBLC37FX3CX09556

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34FX2CH08369 | SCBLF34F83CX09017 | SCBLC37F13CX09557 |
| SCBLF34FX2CX08370 | SCBLF34FX3CX09018 | SCBLC37F33CX09558 |
| SCBLF34F12CX08371 | SCBLC37F83CX09019 | SCBLF34F03CX09559 |
| SCBLF34F32CX08372 | SCBLC37F23CX09020 | SCBLF34F73CX09560 |
| SCBLF34F52CX08373 | SCBLC37F43CX09021 | SCBLC37F33CX09561 |
| SCBLF34F42CX08395 | SCBLF34F83CH09022 | SCBLC37F53CX09562 |
| SCBLF34F62CX08396 | SCBLF34FX3CH09023 | SCBLF34F23CX09563 |
| SCBLF34F82CX08397 | SCBLC37F83CH09024 | SCBLC37F93CX09564 |
| SCBLF34F62CH08398 | SCBLF34F73CX09025 | SCBLC37F03CX09565 |
| SCBLF34F82CH08399 | SCBLC37F33CX09026 | SCBLC37F23CX09566 |
| SCBLF34F02CH08400 | SCBLC37F53CX09027 | SCBLC37F43CX09567 |
| SCBLF34F22CH08401 | SCBLF34F93CH09028 | SCBLC37F63CX09568 |
| SCBLF34F82CX08402 | SCBLC37F53CH09029 | SCBLF34FX3CH09569 |
| SCBLF34FX2CX08403 | SCBLC37F13CH09030 | SCBLF34FX3CX09570 |
| SCBLF34F12CX08404 | SCBLF34F93CH09031 | SCBLF34F13CX08571 |
| SCBLF34FX2CH08405 | SCBLF34F43CX09032 | SCBLC37F83CX09572 |
| SCBLF34F12CH08406 | SCBLC37F03CX09033 | SCBLF34F13CH09573 |
| SCBLF34F72CX08407 | SCBLF34F43CH09034 | SCBLF34F33CH09574 |
| SCBLF34F92CX08408 | SCBLF34F63CH09035 | SCBLF34F53CH09575 |
| SCBLF34F72CH08409 | SCBLC37F63CX09036 | SCBLF34F73CH09576 |
| SCBLF34F72CX08410 | SCBLC37F83CX09037 | SCBLC37F73CX09577 |
| SCBLF34F92CX08411 | SCBLF34F13CH09038 | SCBLC37F53CH09578 |
| SCBLF34F72CH08412 | SCBLF34F73CX09039 | SCBLC37F73CH09579 |
| SCBLF34F22CX08413 | SCBLF34FX3CH09040 | SCBLC37F33CH09580 |
| SCBLF34F02CH08414 | SCBLF34F13CH09041 | SCBLC37F93CX09581 |
| SCBLF34F22CH08415 | SCBLC37F13CX09042 | SCBLF34F63CX09582 |
| SCBLF34F42CH08416 | SCBLF34F93CX09043 | SCBLF34F43CH09583 |
| SCBLF34FX2CX08417 | SCBLC37F13CH09044 | SCBLF34F63CH09584 |
| SCBLF34F12CX08418 | SCBLC37F73CX09045 | SCBLF34F83CH09585 |
| SCBLF34F32CX08419 | SCBLF34F43CX09046 | SCBLC37F83CX09586 |
| SCBLF34FX2CX08420 | SCBLC37F03CX09047 | SCBLC37FX3CX09587 |
| SCBLF34F12CX08421 | SCBLF34F83CX09048 | SCBLC37F13CX09588 |
| SCBLF34F32CX08422 | SCBLF34FX3CX09049 | SCBLF34F53CH09589 |
| SCBLF34F52CX08423 | SCBLC37F03CX09050 | SCBLF34F53CX09590 |
| SCBLF34F72CX08424 | SCBLC37F93CH09051 | SCBLC37F83CH09591 |
| SCBLF34F92CX08425 | SCBLC37F03CH09052 | SCBLF34F53CH09592 |
| SCBLF34F02CX08426 | SCBLC37F23CH09053 | SCBLC37F13CH09593 |
| SCBLF34F82CH08427 | SCBLC37F83CX09054 | SCBLF34F93CH09594 |
| SCBLF34F02CH08428 | SCBLC37F63CH09055 | SCBLC37F83CX09595 |
| SCBLF34F22CH08429 | SCBLF34F73CX09056 | SCBLF34F63CX09596 |
| SCBLF34F92CH08430 | SCBLC37F33CX09057 | SCBLF34F43CH09597 |
| SCBLF34F02CH08431 | SCBLF34F03CX09058 | SCBLF34FX3CX09598 |
| SCBLF34F22CH08432 | SCBLF34F93CH09059 | SCBLF34F83CH09599 |
| SCBLF34F42CH08433 | SCBLC37F33CX09060 | SCBLC37F83CX09600 |
| SCBLF34F82CH08434 | SCBLF34F73CH09061 | SCBLC37F03CX09601 |
| SCBLF34F82CH08435 | SCBLF34F93CH09062 | SCBLC37F23CX09602 |

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34FX2CH08436 | SCBLF34F03CH09063 | SCBLC37F43CX09603 |
| SCBLF34F12CH08437 | SCBLF34F83CX09064 | SCBLC37F63CX09604 |
| SCBLF34F32CH08438 | SCBLC37F93CH09065 | SCBLC37F83CX09605 |
| SCBLF34F52CH08439 | SCBLF34FX3CX09066 | SCBLF34F53CX09606 |
| SCBLF34F12CH08440 | SCBLF34F83CH09067 | SCBLF34F33CH09607 |
| SCBLF34F32CH08441 | SCBLC37F83CX09068 | SCBLF34F93CX09608 |
| SCBLF34F52CH08442 | SCBLC37FX3CX09069 | SCBLF34F73CH09609 |
| SCBLF34F72CH08443 | SCBLC37F63CX09070 | SCBLC37F83CH09610 |
| SCBLF34F82CH08444 | SCBLF34F33CX09071 | SCBLF34F93CX09611 |
| SCBLF34F02CH08445 | SCBLC37FX3CX09072 | SCBLF34F03CX09612 |
| SCBLF34F22CH08446 | SCBLF34F73CX09073 | SCBLF34F93CH09613 |
| SCBLF34F82CX08447 | SCBLC37F33CX09074 | SCBLC37F53CH09614 |
| SCBLF34F62CH08448 | SCBLF34F73CH09075 | SCBLF34F63CX09615 |
| SCBLF34F82CH08449 | SCBLF34F23CX09076 | SCBLF34F43CH09616 |
| SCBLF34F42CH08450 | SCBLC37F53CH09077 | SCBLC37F43CX09617 |
| SCBLF34F62CH08451 | SCBLC37F73CH09078 | SCBLC37F83CX09618 |
| SCBLF34F82CH08452 | SCBLC37F93CH09079 | SCBLF34F33CX09619 |
| SCBLF34FX2CH08453 | SCBLC37F53CH09080 | SCBLC37F03CH09620 |
| SCBLF34F12CH08454 | SCBLC37F73CH09081 | SCBLF34F13CX09621 |
| SCBLF34F32CH08455 | SCBLF34F83CX09082 | SCBLC37F83CX09622 |
| SCBLF34F52CH08456 | SCBLC37F43CX09083 | SCBLF34F13CH09623 |
| SCBLF34F72CH08457 | SCBLF34F13CX09084 | SCBLC37F13CX09624 |
| SCBLF34F92CH08458 | SCBLF34FX3CH09085 | SCBLC37FX3CH09625 |
| SCBLF34F02CH08459 | SCBLC37FX3CX09086 | SCBLC37F13CH09626 |
| SCBLF34F72CH08460 | SCBLC37F13CX09087 | SCBLC37F33CH09627 |
| SCBLF34F92CH08461 | SCBLF34F53CH09088 | SCBLF34F03CH09628 |
| SCBLF34F02CH08462 | SCBLC37F13CH09089 | SCBLF34F63CX09629 |
| SCBLF34F22CH08463 | SCBLF34F73CX09090 | SCBLF34F23CX09630 |
| SCBLF34F42CH08464 | SCBLF34F93CX09091 | SCBLC37F93CX09631 |
| SCBLF34F62CH08465 | SCBLC37F53CX09092 | SCBLF34F63CX09632 |
| SCBLF34F82CH08466 | SCBLC37F73CX09093 | SCBLC37F23CX09633 |
| SCBLF34FX2CH08467 | SCBLC37F53CH09094 | SCBLF34FX3CX09634 |
| SCBLF34F12CH08468 | SCBLC37F73CH09095 | SCBLF34F83CH09635 |
| SCBLF34F32CH08469 | SCBLC37F23CX09096 | SCBLC37F43CH09636 |
| SCBLF34FX2CH08470 | SCBLC37F43CX09097 | SCBLF34F13CH09637 |
| SCBLF34F12CH08471 | SCBLC37F63CX09098 | SCBLF34F33CH09638 |
| SCBLF34F32CH08472 | SCBLC37F43CH09099 | SCBLF34F53CH09639 |
| SCBLF34F52CH08473 | SCBLC37F73CH09100 | SCBLF34F13CH09640 |
| SCBLF34F72CH08474 | SCBLF34F43CH09101 | SCBLF34F33CH09641 |
| SCBLF34F92CH08475 | SCBLF34FX3CX09102 | SCBLC37FX3CH09642 |
| SCBLF34F02CH08476 | SCBLF34F13CX09103 | SCBLC37F13CH09643 |
| SCBLF34F22CH08477 | SCBLC37F83CX09104 | SCBLF34F93CH09644 |
| SCBLF34F42CH08478 | SCBLF34F53CX09105 | SCBLF34F03CH09645 |
| SCBLF34FX2CX08479 | SCBLF34F73CX09106 | SCBLF34F63CX09646 |
| SCBLF34F62CX08480 | SCBLF34F93CX09107 | SCBLC37F83CH09647 |
| SCBLF34F82CX08481 | SCBLF34F03CX09108 | SCBLF34F63CH09648 |

RECALL RED4/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34FX2CX08482 | SCBLC37F73CX09109 | SCBLF34F83CH09649 |
| SCBLF34F12CX08483 | SCBLC37F33CX09110 | SCBLF34F43CH09650 |
| SCBLF34FX2CH08484 | SCBLF34F73CH09111 | SCBLF34F63CH09651 |
| SCBLF34F12CH08485 | SCBLC37F73CX09112 | SCBLC37F23CH09662 |
| SCBLF34F32CH08486 | SCBLC37F93CX09113 | SCBLF34FX3CH09653 |
| SCBLF34F52CH08487 | SCBLC37F73CH09114 | SCBLC37F63CH09654 |
| SCBLF34F72CH08488 | SCBLF34F83CX09115 | SCBLC37F83CH09655 |
| SCBLF34F92CH08489 | SCBLF34F63CH09116 | SCBLF34F53CH09656 |
| SCBLF34F52CH08490 | SCBLC37F23CH09117 | SCBLC37F13CH09657 |
| SCBLF34F72CH08491 | SCBLF34F33CX09118 | SCBLC37F33CH09658 |
| SCBLF34F92CH08492 | SCBLC37FX3CX09119 | SCBLF34F03CH09659 |
| SCBLF34F02CH08493 | SCBLF34F13CX09120 | SCBLC37F13CH09660 |
| SCBLF34F22CH08494 | SCBLC37F43CH09121 | SCBLF34F93CH09661 |
| SCBLF34F42CH08495 | SCBLF34F13CH09122 | SCBLF34F84CX09701 |
| SCBLF34F62CH08496 | SCBLF34F33CH09123 | SCBLF34FX4CX09702 |
| SCBLF34F82CH08497 | SCBLC37F33CX09124 | SCBLC37F84CX09703 |
| SCBLF34FX2CH08498 | SCBLF34F03CX09125 | SCBLC37F84CX09704 |
| SCBLF34F12CH08499 | SCBLF34F23CX09126 | SCBLF34F54CX09705 |
| SCBLF34F42CH08500 | SCBLF34F43CX09127 | SCBLF34F74CX09706 |
| SCBLF34F62CH08501 | SCBLF34F63CX09128 | SCBLF34F94CX09707 |
| SCBLC37F82CX08503 | SCBLF34F83CX09129 | SCBLF34F04CX09708 |
| SCBLF34F72CX08505 | SCBLF34F43CX09130 | SCBLF34F24CX09709 |
| SCBLF34F52CH08506 | SCBLF34F63CX09131 | SCBLC37FX4CH09710 |
| SCBLF34F72CH08507 | SCBLF34F43CH09132 | SCBLC37F54CX09711 |
| SCBLF34F92CH08508 | SCBLF34FX3CX09133 | SCBLC37F74CX09712 |
| SCBLF34F02CH08509 | SCBLF34F83CH09134 | SCBLC37F94CX09713 |
| SCBLF34F72CH08510 | SCBLF34F33CX09135 | SCBLC37F04CX09714 |
| SCBLF34F92CH08511 | SCBLF34F13CH09136 | SCBLC37F24CX09715 |
| SCBLF34F02CH08512 | SCBLC37F13CX09137 | SCBLF34FX4CX09718 |
| SCBLC37F02CH08515 | SCBLC37F33CX09138 | SCBLC37F64CX09717 |
| SCBLF34FX2CH08517 | SCBLF34F03CX09139 | SCBLF34F34CX09718 |
| SCBLF34F12CH08518 | SCBLF34F73CX09140 | SCBLC37FX4CX09719 |
| SCBLF34F32CH08519 | SCBLC37FX3CH09141 | SCBLF34F14CX09720 |
| SCBLC37F42CH08520 | SCBLF34F03CX09142 | SCBLF34F34CX09721 |
| SCBLC37F62CH08521 | SCBLC37F73CX09143 | SCBLC37FX4CX09722 |
| SCBLC37F82CH08522 | SCBLC37F93CX09144 | SCBLC37F14CX09723 |
| SCBLC37FX2CH08523 | SCBLC37F03CX09145 | SCBLC37F34CX09724 |
| SCBLC37F12CH08524 | SCBLF34F43CH09146 | SCBLC37F54CX09725 |
| SCBLF34F42CX08526 | SCBLF34F63CH09147 | SCBLF34F24CX09726 |
| SCBLF34F22CH08527 | SCBLC37F63CX09148 | SCBLF34F04CH09727 |
| SCBLC37F92CH08528 | SCBLF34F33CX09149 | SCBLF34F84CX09728 |
| SCBLF34F62CH08529 | SCBLC37F43CX09150 | SCBLF34F84CX09729 |
| SCBLF34F22CH08530 | SCBLF34F13CX09151 | SCBLF34F04CH09730 |
| SCBLF34F42CH08531 | SCBLF34FX3CH09152 | SCBLC37F04CX09731 |
| SCBLC37F02CH08532 | SCBLF34F53CX09153 | SCBLC37F24CX09732 |
| SCBLF34F82CH08533 | SCBLF34F73CX09154 | SCBLF34FX4CX09733 |

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34FX2CH08534 | SCBLF34F93CX09155 | SCBLC37F64CX09734 |
| SCBLF34F12CH08535 | SCBLF34F03CX09156 | SCBLF34F34CX09735 |
| SCBLF34F32CH08536 | SCBLF34F23CX09157 | SCBLF34F54CX09736 |
| SCBLC37FX2CH08537 | SCBLF34F43CX09158 | SCBLC37F14CX09737 |
| SCBLF34F72CH08538 | SCBLF34F63CX09159 | SCBLC37F34CX09738 |
| SCBLC37F32CH08539 | SCBLF34F93CH09160 | SCBLC37F54CX09739 |
| SCBLF34F52CH08540 | SCBLF34F43CX09161 | SCBLF34F74CX09740 |
| SCBLC37F12CH08541 | SCBLF34F63CX09162 | SCBLF34F94CX09741 |
| SCBLF34F92CH08542 | SCBLC37F23CX09163 | SCBLF34F04CX09742 |
| SCBLF34F02CH08543 | SCBLC37F43CX09164 | SCBLC42F04CX09743 |
| SCBLF34F22CH08544 | SCBLC37F23CH09165 | SCBLF34F44CX09744 |
| SCBLF34F42CH08545 | SCBLF34FX3CH09166 | SCBLF34F64CX09745 |
| SCBLF34F62CH08546 | SCBLF34F53CX09167 | SCBLF34F84CX09746 |
| SCBLF34F82CH08547 | SCBLC37F13CX09168 | SCBLC37F44CX09747 |
| SCBLC37F42CH08548 | SCBLC37F33CX09169 | SCBLC42FX4CX09748 |
| SCBLC37F62CH08549 | SCBLF34F13CH09170 | SCBLC37F84CX09749 |
| SCBLF34F82CH08550 | SCBLC37F83CH09171 | SCBLF34FX4CX09750 |
| SCBLC37F42CH08551 | SCBLC37FX3CH09172 | SCBLC37F64CX09751 |
| SCBLF34F12CH08552 | SCBLC37F53CX09173 | SCBLC37F84CX09752 |
| SCBLF34F32CH08553 | SCBLF34F93CH09174 | SCBLF34F54CX09753 |
| SCBLC37FX2CH08554 | SCBLC37F93CX09175 | SCBLF34F74CX09754 |
| SCBLF34F72CH08555 | SCBLC37F03CX09176 | SCBLF34F54CH09755 |
| SCBLC37F32CH08556 | SCBLC37F23CX09177 | SCBLC37F14CH09756 |
| SCBLF34F02CH08557 | SCBLF34FX3CX09178 | SCBLC37F34CH09757 |
| SCBLF34F22CH08558 | SCBLF34F13CX09179 | SCBLF34F04CH09758 |
| SCBLF34F42CH08559 | SCBLF34F83CX09180 | SCBLC37F74CH09759 |
| SCBLF34F02CH08560 | SCBLF34FX3CX09181 | SCBLF34F94CH09760 |
| SCBLF34F62CX08561 | SCBLF34F13CX09182 | SCBLF34F04CH09761 |
| SCBLF34F42CH08562 | SCBLF34F33CX09183 | SCBLF34F64CX09762 |
| SCBLF34F62CH08563 | SCBLF34F63CX09184 | SCBLF34F84CX09763 |
| SCBLF34F82CH08564 | SCBLF34F73CX09185 | SCBLC37F04CH09764 |
| SCBLF34FX2CH08565 | SCBLC37FX3CH09186 | SCBLC37F64CX09765 |
| SCBLF34F12CH08566 | SCBLF34F73CH09187 | SCBLC37F44CH09766 |
| SCBLF34F32CH08567 | SCBLF34F23CX09188 | SCBLC37FX4CX09767 |
| SCBLF34F52CH08568 | SCBLF34F03CH09189 | SCBLF34F74CX09768 |
| SCBLF34F72CX08570 | SCBLC37F13CH09190 | SCBLC37F34CX09769 |
| SCBLF34F92CX08571 | SCBLF34F93CH09191 | SCBLF34F54CX09770 |
| SCBLF34F02CX08572 | SCBLF34F03CH09192 | SCBLC37F14CX09771 |
| SCBLF34F22CX08573 | SCBLF34F23CH09193 | SCBLF34F94CX09772 |
| SCBLF34F42CX08574 | SCBLC37F23CX09194 | SCBLC37F14CH09773 |
| SCBLF34F62CX08575 | SCBLC37F43CX09195 | SCBLF34F94CH09774 |
| SCBLC37F92CH08576 | SCBLC37F63CX09196 | SCBLF34F04CH09775 |
| SCBLF34FX2CX08577 | SCBLC37F83CX09197 | SCBLF34F24CH09776 |
| SCBLF34F12CX08578 | SCBLF34F13CH09198 | SCBLC37F94CH09777 |
| SCBLF34F32CX08579 | SCBLF34F73CX09199 | SCBLF34FX4CX09778 |
| SCBLF34FX2CX08580 | SCBLF34FX3CX09200 | SCBLC42FX4CX09779 |

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34F12CX08581 | SCBLF34F13CX09201 | SCBLF34F44CH09780 |
| SCBLF34F32CX08582 | SCBLF34FX3CH09202 | SCBLC37F04CH09781 |
| SCBLF34F52CX08583 | SCBLC37FX3CX09203 | SCBLC37F84CX09782 |
| SCBLF34F72CX08584 | SCBLF34F73CX09204 | SCBLF34F34CX09783 |
| SCBLF34F92CX08585 | SCBLF34F93CX09205 | SCBLF34F54CX09784 |
| SCBLF34F02CX08586 | SCBLF34F03CX09206 | SCBLC37F84CH09785 |
| SCBLF34F22CX08587 | SCBLC37F73CX09207 | SCBLF34F94CX09786 |
| SCBLF34F42CX08588 | SCBLF34F03CH09208 | SCBLC37F54CX09787 |
| SCBLF34F62CX08589 | SCBLC37F73CH09209 | SCBLF34F24CX09788 |
| SCBLF34F22CX08590 | SCBLC37F73CX09210 | SCBLF34F04CX09790 |
| SCBLF34F42CX08591 | SCBLF34F43CX09211 | SCBLF34F24CX09791 |
| SCBLF34F82CX08593 | SCBLC37F03CX09212 | SCBLC37F94CX09792 |
| SCBLF34FX2CX08594 | SCBLF34F43CH09213 | SCBLF34F84CX09793 |
| SCBLF34F12CX08595 | SCBLF34F63CH09214 | SCBLF34F84CX09794 |
| SCBLF34F32CX08596 | SCBLC37F23CH09215 | SCBLF34F84CH09795 |
| SCBLC37FX2CX08597 | SCBLC37F83CX09216 | SCBLC37F84CX09796 |
| SCBLF34F72CX08598 | SCBLC37FX3CX09217 | SCBLF34FX4CH09797 |
| SCBLF34F92CX08599 | SCBLC37F13CX09218 | SCBLF34F54CX09798 |
| SCBLF34F12CX08600 | SCBLF34F93CX09219 | SCBLF34F34CH09799 |
| SCBLF34F32CX08601 | SCBLF34F53CX09220 | SCBLF34FX4CX09800 |
| SCBLF34F52CX08602 | SCBLF34F73CX09221 | SCBLF34F14CX09801 |
| SCBLF34F72CX08603 | SCBLC37F33CX09222 | SCBLF34F34CX09802 |
| SCBLF34F92CX08604 | SCBLF34F73CH09223 | SCBLF34F14CH09803 |
| SCBLF34F02CX08605 | SCBLF34F93CH09224 | SCBLC37F14CX09804 |
| SCBLF34F22CX08606 | SCBLC37F93CX09225 | SCBLF34F64CH09805 |
| SCBLF34F42CX08607 | SCBLF34F63CX09226 | SCBLF34F74CH09806 |
| SCBLF34F62CX08608 | SCBLF34F83CX09227 | SCBLF34F24CX09807 |
| SCBLF34F82CX08609 | SCBLF34FX3CX09228 | SCBLC37F94CX09808 |
| SCBLF34F42CX08610 | SCBLF34F83CH09229 | SCBLF34F64CX09809 |
| SCBLF34F62CX08611 | SCBLF34F83CX09230 | SCBLC37F34CH09810 |
| SCBLF34F82CX08612 | SCBLC37F43CX09231 | SCBLF34F04CH09811 |
| SCBLF34FX2CX08613 | SCBLF34F13CX09232 | SCBLF34F24CH09812 |
| SCBLF34F12CX08614 | SCBLF34F33CX09233 | SCBLF34F84CX09813 |
| SCBLF34F32CX08615 | SCBLC37F63CH09234 | SCBLC37F44CX09814 |
| SCBLF34F72CX08617 | SCBLC37F13CX09235 | SCBLC37F64CX09815 |
| SCBLF34F92CX08618 | SCBLC37F33CX09236 | SCBLF34F34CX09816 |
| SCBLF34F02CX08619 | SCBLF34F73CH09237 | SCBLC37FX4CX09817 |
| SCBLF34F72CX08620 | SCBLF34F23CX09238 | SCBLF34F74CX09818 |
| SCBLF34F92CX08621 | SCBLF34F43CX09239 | SCBLF34F54CH09819 |
| SCBLF34F02CX08622 | SCBLF34F03CX09240 | SCBLC42F34CX09820 |
| SCBLF34F22CX08623 | SCBLF34F93CH09241 | SCBLF34F34CH09821 |
| SCBLF34F42CX08624 | SCBLC37F93CX09242 | SCBLC37F34CX09822 |
| SCBLF34F62CX08625 | SCBLF34F23CH09243 | SCBLC42F94CX09823 |
| SCBLF34F82CX08626 | SCBLC37F93CH09244 | SCBLF34F94CH09824 |
| SCBLF34FX2CX08627 | SCBLC37F03CH09245 | SCBLF34F04CH09825 |
| SCBLF34F12CX08628 | SCBLF34F13CX09246 | SCBLC37F04CX09826 |

RECALL RE0402 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34F32CX08629 | SCBLC37F43CH09247 | SCBLF34F84CX09827 |
| SCBLF34FX2CX08630 | SCBLC37F63CH09248 | SCBLF34F84CH09828 |
| SCBLF34F12CX08631 | SCBLF34F33CH09249 | SCBLC37F24CH09829 |
| SCBLF34F32CX08632 | SCBLF34F33CX09250 | SCBLF34F84CX09830 |
| SCBLF34F52CX08633 | SCBLF34F13CH09251 | SCBLF34F84CH09831 |
| SCBLF34F72CX08634 | SCBLF34F73CX09252 | SCBLF34F14CX09832 |
| SCBLF34F02CX08636 | SCBLF34F93CX09253 | SCBLF34FX4CH09833 |
| SCBLC37F32CH08637 | SCBLF34F03CX09254 | SCBLF34F14CH09834 |
| SCBLF34F42CX08638 | SCBLC37F73CX09255 | SCBLF34F34CH09835 |
| SCBLF34F62CX08639 | SCBLF34F43CX09256 | SCBLC37FX4CH09836 |
| SCBLC37F72CX08640 | SCBLF34F63CX09257 | SCBLC37F54CX09837 |
| SCBLC37F92CX08641 | SCBLF34F83CX09258 | SCBLC37F34CH09838 |
| SCBLF34F82CX08643 | SCBLF34FX3CX09259 | SCBLF34F44CX09839 |
| SCBLC37F02CH08644 | SCBLF34F63CX09280 | SCBLC37F54CX09840 |
| SCBLF34F12CX08645 | SCBLC37F23CX09261 | SCBLC37F34CH09841 |
| SCBLF34F32CX08646 | SCBLC37F43CX09262 | SCBLF34F44CX09842 |
| SCBLF34F12CH08647 | SCBLF34F13CX09263 | SCBLF34F24CH09843 |
| SCBLF34F72CX08648 | SCBLC37F83CX09264 | SCBLC37F24CX09844 |
| SCBLF34F52CX08650 | SCBLF34F13CH09265 | SCBLC37F44CX09845 |
| SCBLF34F72CX08651 | SCBLC37F13CX09266 | SCBLF34F84CH09846 |
| SCBLF34F92CX08652 | SCBLC37FX3CH09267 | SCBLC37F84CX09847 |
| SCBLF34F02CX08653 | SCBLC37F13CH09268 | SCBLC37F64CH09848 |
| SCBLC37F32CH08654 | SCBLC37F33CH09269 | SCBLC37F84CH09849 |
| SCBLC37F52CH08655 | SCBLF34F63CH09270 | SCBLF34F34CX09850 |
| SCBLC37F72CH08656 | SCBLC37F53CX09271 | SCBLF34F14CH09851 |
| SCBLF34F82CX08657 | SCBLC37F33CH09272 | SCBLF34F74CX09852 |
| SCBLF34F62CH08658 | SCBLF34F43CX09273 | SCBLC37F34CX09853 |
| SCBLC37F62CX08659 | SCBLF34F83CX09274 | SCBLF34F04CX09854 |
| SCBLF34F42CH08660 | SCBLC37F93CH09275 | SCBLC37F74CX09855 |
| SCBLF34F62CH08661 | SCBLF34FX3CX09276 | SCBLC37F94CX09856 |
| SCBLF34F82CH08662 | SCBLF34F13CX09277 | SCBLC37F04CX09857 |
| SCBLF34F72CX08665 | SCBLF34F33CX09278 | SCBLC42F64CX09858 |
| SCBLF34F52CH08666 | SCBLC37FX3CX09279 | SCBLC42F84CX09859 |
| SCBLC37F62CX08667 | SCBLF34F83CH09280 | SCBLF34F64CX09860 |
| SCBLF34F22CX08668 | SCBLC37F83CX09281 | SCBLF34F84CX09861 |
| SCBLF34F42CX08669 | SCBLC37FX3CX09282 | SCBLC37F44CX09862 |
| SCBLF34F02CX08670 | SCBLF34F73CX09283 | SCBLC37F84CX09863 |
| SCBLF34F22CX08671 | SCBLF34F93CX09284 | SCBLC37F44CH09864 |
| SCBLF34F42CX08672 | SCBLF34F03CX09285 | SCBLF41F24CX09865 |
| SCBLF34F62CX08673 | SCBLC37F73CX09286 | SCBLC37F14CX09866 |
| SCBLF34F82CX08674 | SCBLF34F43CX09287 | SCBLC37F34CX09867 |
| SCBLC37F02CH08675 | SCBLF34F63CX09288 | SCBLC37F54CX09868 |
| SCBLF34F12CX08676 | SCBLC37F23CX09289 | SCBLC37F74CX09869 |
| SCBLF34F32CX08677 | SCBLF34F43CX09290 | SCBLC37F34CX09870 |
| SCBLF34F52CX08678 | SCBLC37F03CX09291 | SCBLF34F04CX09871 |
| SCBLF34F72CX08679 | SCBLF34F43CH09292 | SCBLF34F24CX09872 |

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34F32CX08680 | SCBLF34FX3CX09283 | SCBLC37F94CX09873 |
| SCBLF34F52CX08681 | SCBLF34F83CH09294 | SCBLC37F04CX09874 |
| SCBLF34F72CX08682 | SCBLF34FX3CH09295 | SCBLF34F84CX09875 |
| SCBLF34F92CX08683 | SCBLF34F13CH09296 | SCBLF34FX4CX09876 |
| SCBLC37F12CH08684 | SCBLF34F73CX09297 | SCBLC42FX4CX09877 |
| SCBLC37F32CH08685 | SCBLF34F93CX09298 | SCBLF34F34CX09878 |
| SCBLF34F42CX08686 | SCBLF34F03CX09299 | SCBLC37FX4CX09879 |
| SCBLF34F62CX08687 | SCBLF34F33CX09300 | SCBLF34F14CX09880 |
| SCBLC37F22CX08688 | SCBLF34F13CH09301 | SCBLF34F34CX09881 |
| SCBLF34FX2CX08689 | SCBLC37F13CX09302 | SCBLC37FX4CX09882 |
| SCBLF34F62CX08690 | SCBLC37F33CX09303 | SCBLC37F14CX09883 |
| SCBLF34F82CX08691 | SCBLC37F53CX09304 | SCBLF34F54CH09884 |
| SCBLF34FX2CX08692 | SCBLF34F23CX09305 | SCBLF34F04CX09885 |
| SCBLF34F12CX08693 | SCBLF34F43CX09306 | SCBLC37F74CX09886 |
| SCBLF34F32CX08694 | SCBLC37F03CX09307 | SCBLF34F44CX09887 |
| SCBLF34F52CX08695 | SCBLF34F43CH09308 | SCBLF34F64CX09888 |
| SCBLF34F72CX08696 | SCBLC37F03CH09309 | SCBLF34F84CX09889 |
| SCBLF34F92CX08697 | SCBLF34F63CX09310 | SCBLF34F44CX09890 |
| SCBLF34F02CX08698 | SCBLF34F43CH09311 | SCBLF34F64CX09891 |
| SCBLF34F22CX08699 | SCBLC37F43CX09312 | SCBLF34F84CX09892 |
| SCBLF34F52CX08700 | SCBLF34F13CX09313 | SCBLF34FX4CX09893 |
| SCBLF34F72CX08701 | SCBLF34F33CX09314 | SCBLF34F14CX09894 |
| SCBLF34F92CX08702 | SCBLF34F53CX09315 | SCBLF34F34CX09895 |
| SCBLF34F02CX08703 | SCBLF34F73CX09316 | SCBLF34F54CX09896 |
| SCBLF34F22CX08704 | SCBLF34F93CX09317 | SCBLF34F74CX09897 |
| SCBLF34F42CX08705 | SCBLC37F53CX09318 | SCBLF34F94CX09898 |
| SCBLF34F82CX08706 | SCBLF34F93CH09319 | SCBLF34F04CX09899 |
| SCBLF34F82CX08707 | SCBLF34F83CX09320 | SCBLF34F34CX09900 |
| SCBLF34FX2CX08708 | SCBLF34F03CX09321 | SCBLF34F14CH09901 |
| SCBLC37F62CX08709 | SCBLF34F93CH09322 | SCBLF34F74CX09902 |
| SCBLF34F82CX08710 | SCBLF34F43CX09323 | SCBLF34F54CH09903 |
| SCBLF34F82CH08712 | SCBLF34F63CX09324 | SCBLF34F74CH09904 |
| SCBLF34FX2CH08713 | SCBLC37F23CX09325 | SCBLF34F24CX09905 |
| SCBLF34F52CX08714 | SCBLF34FX3CX09326 | SCBLF34F44CX09906 |
| SCBLF34F72CX08715 | SCBLF34F13CX09327 | SCBLF34F64CX09907 |
| SCBLF34F92CX08716 | SCBLC37F83CX09328 | SCBLF34F84CX09908 |
| SCBLF34F72CH08717 | SCBLF34F53CX09329 | SCBLF34FX4CX09909 |
| SCBLF34F22CX08718 | SCBLC37F23CH09330 | SCBLF34F64CX09910 |
| SCBLF34F42CX08719 | SCBLC37F83CX09331 | SCBLC42F64CX09911 |
| SCBLF34F02CX08720 | SCBLF34F13CH09332 | SCBLF34FX4CX09912 |
| SCBLF34F42CX08722 | SCBLF34F73CX09333 | SCBLF34F14CX09913 |
| SCBLF34F22CH08723 | SCBLF34F53CH09334 | SCBLF34F34CX09914 |
| SCBLF34F42CH08724 | SCBLF34F03CX09335 | SCBLC37FX4CX09915 |
| SCBLF34F12CX08726 | SCBLF34F23CX09336 | SCBLF34F74CX09916 |
| SCBLF34F32CX08727 | SCBLC37F93CX09337 | SCBLF34F94CX09917 |
| SCBLF34F52CX08728 | SCBLF34F63CX09338 | SCBLC37F14CH09918 |

RECALL R60402 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34F72CX08729 | SCBLF34F83CX09339 | SCBLF34F24CX09919 |
| SCBLF34F32CX08730 | SCBLF34F43CX09340 | SCBLF34F94CX09920 |
| SCBLF34F52CX08731 | SCBLC37F03CX09341 | SCBLC37F54CX09921 |
| SCBLF34F72CX08732 | SCBLF34F83CX09342 | SCBLF34F24CX09922 |
| SCBLC37FX2CH08733 | SCBLF34FX3CX09343 | SCBLF34F44CX09923 |
| SCBLF34F02CX08734 | SCBLF34F13CX09344 | SCBLF34F64CX09924 |
| SCBLF34F22CX08735 | SCBLF34FX3CH09345 | SCBLF34F84CX09925 |
| SCBLF34F42CX08736 | SCBLF34F53CX09346 | SCBLF34FX4CX09926 |
| SCBLF34F62CX08737 | SCBLC37F13CX09347 | SCBLF34F84CH09927 |
| SCBLC37F22CX08738 | SCBLF34F53CH09348 | SCBLF34F34CX09928 |
| SCBLF34FX2CX08739 | SCBLF34F73CH09349 | SCBLF34F54CX09929 |
| SCBLF34F62CX08740 | SCBLC37F13CX09350 | SCBLF34F14CX09930 |
| SCBLF34F82CX08741 | SCBLF34F53CH09351 | SCBLF34F34CX09931 |
| SCBLF34FX2CX08742 | SCBLF34F03CX09352 | SCBLF34F54CX09932 |
| SCBLF34F12CX08743 | SCBLC37F73CX09353 | SCBLC37F84CH09933 |
| SCBLF34F32CX08744 | SCBLF34F43CX09354 | SCBLF34F94CX09934 |
| SCBLF34F12CH08745 | SCBLC37F03CX09355 | SCBLF34F04CX09935 |
| SCBLF34F72CX08746 | SCBLC37F23CX09356 | SCBLF34F24CX09936 |
| SCBLF34F92CX08747 | SCBLF34FX3CX09357 | SCBLF34F44CX09937 |
| SCBLF34F72CH08748 | SCBLC37F63CX09358 | SCBLF34F24CH09938 |
| SCBLF34F22CX08749 | SCBLF34F33CX09359 | SCBLF34F44CH09939 |
| SCBLF34F82CX08750 | SCBLF34FX3CX09360 | SCBLF34F44CX09940 |
| SCBLF34F02CX08751 | SCBLF34F13CX09361 | SCBLC37F74CH09941 |
| SCBLF34F22CX08752 | SCBLF34F33CX09362 | SCBLF34F44CH09942 |
| SCBLF34F02CH08753 | SCBLC37FX3CX09363 | SCBLF34F84CH09943 |
| SCBLF34F22CH08754 | SCBLC37F13CX09364 | SCBLF34F84CH09944 |
| SCBLF34F42CH08755 | SCBLC37F33CX09365 | SCBLF34FX4CH09945 |
| SCBLC37F02CH08756 | SCBLF34F03CX09366 | SCBLF34F14CH09946 |
| SCBLF34F12CX08757 | SCBLC37F73CX09367 | SCBLC42F54CX09947 |
| SCBLF34F32CX08758 | SCBLF34F03CH09368 | SCBLF34F94CX09948 |
| SCBLC37FX2CX08759 | SCBLC37F03CX09369 | SCBLF34F74CH09949 |
| SCBLC37F62CX08760 | SCBLF34F93CH09370 | SCBLC37F84CH09950 |
| SCBLF34F32CX08761 | SCBLC37F93CX09371 | SCBLF34F94CX09951 |
| SCBLF34F52CX08762 | SCBLF34F63CX09372 | SCBLC37F54CX09952 |
| SCBLF34F72CX08763 | SCBLF34F83CX09373 | SCBLF34F94CH09953 |
| SCBLF34F52CH08764 | SCBLF34FX3CX09374 | SCBLF34F04CH09954 |
| SCBLC37F12CH08765 | SCBLF34F83CH09375 | SCBLF34F24CH09955 |
| SCBLF34F42CX08770 | SCBLC37F83CX09376 | SCBLC37F24CX09956 |
| SCBLF34F22CH08771 | SCBLF34F13CH09377 | SCBLC37F44CX09957 |
| SCBLF34F42CH08772 | SCBLF34F73CX09378 | SCBLF34F84CH09958 |
| SCBLF34F62CH08773 | SCBLF34F93CX09379 | SCBLC37F84CX09959 |
| SCBLF34F12CX08774 | SCBLF34F53CX09380 | SCBLF34F64CH09960 |
| SCBLF34F32CX08775 | SCBLC37F13CX09381 | SCBLC37F64CX09961 |
| SCBLF34F52CX08776 | SCBLC37FX3CH09382 | SCBLF34F34CX09962 |
| SCBLF34F72CX08777 | SCBLF34F73CH09383 | SCBLF34F54CX09963 |
| SCBLF34F92CX08778 | SCBLF34F23CX09384 | SCBLC37F84CH09964 |

RECALL RE0402 AFFECTED VIN LIST

SCBLF34F02CX08779
SCBLC37F82CH08780
SCBLF34F92CX08781
SCBLF34F02CX08782
SCBLC37F72CX08783
SCBLF34F42CX08784
SCBLC37F72CH08785
SCBLC37F22CX08786
SCBLF34F62CH08787
SCBLC37F22CH08788
SCBLF34F32CX08789
SCBLF34FX2CX08790
SCBLF34F82CH08791
SCBLC38F82CH08793
SCBLF34F72CX08794
SCBLF34F92CX08795
SCBLF34F72CH08796
SCBLF34F22CX08797
SCBLC37F92CX08798
SCBLF34F62CX08799
SCBLF34F92CX08800
SCBLF34F72CH08801
SCBLC37F32CH08802
SCBLF34F42CX08803
SCBLF34F62CX08804
SCBLF34F82CX08805
SCBLF34FX2CX08806
SCBLF34F12CX08807
SCBLF34F62CX08821
SCBLF34F82CX08822
SCBLF34FX2CX08823
SCBLF34F82CH08824
SCBLC37F42CH08826
SCBLC37FX2CX08826
SCBLF34F72CH08829
SCBLF34F02CX08832
SCBLC37F32CH08833
SCBLF34F42CX08834
SCBLF34F62CX08835
SCBLF34F82CX08836
SCBLC37F02CH08837
SCBLF34F12CX08838
SCBLF34FX2CH08839
SCBLF36FX2CH08840
SCBLF34FX2CH08842
SCBLC37F62CH08843

SCBLF34F03CH09385
SCBLF34F63CX09386
SCBLF34F83CX09387
SCBLC37F43CX09388
SCBLC37F83CX09389
SCBLF34F83CX09390
SCBLF34FX3CX09391
SCBLF34F13CX09392
SCBLF34F33CX09393
SCBLF34F53CX09394
SCBLC37F13CX09395
SCBLC37F33CX09396
SCBLF34F03CX09397
SCBLF34F93CH09398
SCBLF34F03CH09399
SCBLC37F13CX09400
SCBLC37F33CX09401
SCBLF34F03CX09402
SCBLF34F23CX09403
SCBLF34F43CX09404
SCBLF34F63CX09405
SCBLF34F83CX09406
SCBLF34F63CH09407
SCBLF34F13CX09408
SCBLC37F83CX09409
SCBLC37F03CH09410
SCBLF34F13CX09411
SCBLF34FX3CH09412
SCBLF34F13CH09413
SCBLF34F73CX09414
SCBLF34F93CX09415
SCBLF34F03CX09416
SCBLF34F23CX09417
SCBLC37F53CH09418
SCBLF34F23CH09419
SCBLF34F23CX09420
SCBLC37F93CX09421
SCBLF34F63CX09422
SCBLF34F83CX09423
SCBLF34FX3CX09424
SCBLC37F63CX09425
SCBLC37F83CX09426
SCBLC37F63CH09427
SCBLC37F83CH09428
SCBLF34F53CH09429
SCBLF34F13CH09430

SCBLC37F34CX09965
SCBLF34F04CX09966
SCBLF34F94CH09967
SCBLF34F44CX09968
SCBLC37F04CX09969
SCBLC37F74CX09970
SCBLC37F04CX09972
SCBLC37F24CX09973
SCBLF34F64CH09974
SCBLC37F64CX09975
SCBLF41F04CX09976
SCBLC37F64CH09977
SCBLF34F94CX09979
SCBLF41F24CX09980
SCBLC37F14CX09981
SCBLC37FX4CH09982
SCBLC37F54CX09983
SCBLC37F34CH09984
SCBLC37F54CH09985
SCBLC37F04CX09986
SCBLC37F04CH09988
SCBLC37F64CX09989
SCBLC37F24CX09990
SCBLC37F44CX09991
SCBLC37F24CH09992
SCBLC37F84CH09995
SCBLC37F14CH09997
SCBLC42F04CX09998
SCBLC37F94CX09999
SCBLF34F74CX10001
SCBLC37FX4CH10002
SCBLC37F74CX10004
SCBLF34F64CH10008
SCBLC37F64CX10012
SCBLC37F44CH10044
SCBLC37F35CX10101
SCBLF34F75CH10102
SCBLF34F95CH10103
SCBLC37F95CX10104
SCBLF34F65CX10105
SCBLC37F95CH10106
SCBHE37F22CX19092
SCBLE37G23CH19150
SCBLE37G83CX19151
SCBLE37GX3CX19152
SCBLE37G83CH19153

RECALL RE04/02 AFFECTED VIN LIST

| | | |
|-------------------|-------------------|-------------------|
| SCBLF34F32CH08844 | SCBLC37F83CH09431 | SCBLE37GX3CH19154 |
| SCBLF34F52CH08845 | SCBLC37FX3CH09432 | SCBHE37G63CX19155 |
| SCBLF34F02CX08846 | SCBLC37F13CH09433 | SCBLE37G73CX19156 |
| SCBLF34F22CX08847 | SCBLF34F93CH09434 | SCBLE37G53CH19157 |
| SCBLF34F42CX08848 | SCBLF34F43CX09435 | SCBLE37G73CH19158 |
| SCBLC37F72CH08849 | SCBLF34F63CX09436 | SCBLE37G23CX19159 |
| SCBLF34F92CH08850 | SCBLF34F83CX09437 | SCBLE37G53CH19160 |
| SCBLF34F02CH08851 | SCBLC37F43CX09438 | SCBLE37G73CH19161 |
| SCBLF34F62CX08852 | SCBLF34F13CX09439 | SCBLE37G23CX19162 |
| SCBLF34F03CX08900 | SCBLC37F23CX09440 | SCBHE37A23CX19163 |
| SCBLF34F23CX08901 | SCBLF34FX3CX09441 | SCBLE37G63CX19164 |
| SCBLF34F43CX08902 | SCBLF34F83CH09442 | SCBLE37G43CH19165 |
| SCBLF34F63CX08903 | SCBLC37F63CX09443 | SCBLE37GX3CX19166 |
| SCBLF34F83CX08904 | SCBLC37F63CH09444 | SCBHE37AX3CX19167 |
| SCBLF34FX3CX08905 | SCBLF34F73CX09445 | SCBLE37G33CX19168 |
| SCBLF34F13CX08906 | SCBLC37F33CX09446 | SCBLE37G53CX19169 |
| SCBLF34F33CX08907 | SCBLF34F73CH09447 | SCBLE37G13CX19170 |
| SCBLF34F53CX08908 | SCBLC37F73CX09448 | SCBLE37GX3CH19171 |
| SCBLF34F73CX08909 | SCBLF34F43CX09449 | SCBLE37G13CH19172 |
| SCBLF34F33CX08910 | SCBLF34F03CX09450 | SCBLE37G33CH19173 |
| SCBLF34F53CX08911 | SCBLC37F73CX09451 | SCBHE37A73CX19174 |
| SCBLF34F73CX08912 | SCBLC37F53CH09452 | SCBLE37G03CX19175 |
| SCBLF34F93CX08913 | SCBLF34F23CH09453 | SCBLE37G23CX19176 |
| SCBLF34F03CX08914 | SCBLF34F43CH09454 | SCBHE37A23CX19177 |
| SCBLF34F23CX08915 | SCBLF34FX3CX09455 | SCBLE37G63CX19178 |
| SCBLF34F43CX08916 | SCBLF34F13CX09456 | SCBLE37G83CX19179 |
| SCBLF34F63CX08917 | SCBLF34F33CX09457 | SCBLE37G03CH19180 |
| SCBLF34F83CX08918 | SCBLF34F53CX09458 | SCBLE37G63CX19181 |
| SCBLF34FX3CX08919 | SCBLF34F73CX09459 | SCBLE37G63CH19183 |
| SCBLF34F23CH08920 | SCBLF34F33CX09460 | SCBLE37G13CX19184 |
| SCBLC37F23CX08921 | SCBLC37FX3CX09461 | SCBLE37G33CX19185 |
| SCBLF34FX3CX08922 | SCBLC37F13CX09462 | SCBLE37G53CX19186 |
| SCBLC37F63CX08923 | SCBLF34F93CX09463 | SCBLE37G73CX19187 |
| SCBLC37F83CX08924 | SCBLF34F03CX09464 | SCBLE37G93CX19188 |
| SCBLC37FX3CX08925 | SCBLC37F73CX09465 | SCBLE37G03CX19189 |
| SCBLF34F73CX08926 | SCBLC37F53CH09466 | SCBLE37G93CX19191 |
| SCBLC37F33CX08927 | SCBLF34F63CX09467 | SCBLE37G03CX19192 |
| SCBLF34F03CX08928 | SCBLF34F43CH09468 | SCBLE37G93CH19193 |
| SCBLC37F73CX08929 | SCBLF34FX3CX09469 | SCBLE37G43CX19194 |
| SCBLF34F53CH08830 | SCBLF34F23CH09470 | SCBAM91A44CX19201 |
| SCBLF34F03CX08931 | SCBLF34F83CX09471 | SCBAM91A84CX19202 |
| SCBLF34F23CX08932 | SCBLF34F63CH09472 | SCBLE37G64CH19203 |
| SCBLF34F03CH08933 | SCBLC37F63CX09473 | SCBLN90A04CX19204 |
| SCBLF34F63CX08934 | SCBLC37F83CX09474 | SCBLE37G34CX19205 |
| SCBLF34F83CX08935 | SCBLF34F53CX09475 | SCBLE42G84CX19206 |
| SCBLF34FX3CX08936 | SCBLC37F83CH09476 | SCBLN91A84CX19207 |

RECALL RE0402 AFFECTED VIN LIST

SCBLC37F83CX08937
SCBLC37F83CX08938
SCBLF34F13CH08939
SCBLC37F83CX08940
SCBLC37F83CX08941
SCBLF34F53CX08942
SCBLF34F73CX08943
SCBLF34F93CX08944
SCBLC37F53CX08945
SCBLF34F23CX08946
SCBLC37F93CX08947
SCBLC37F03CX08948
SCBLC37F23CX08949
SCBLF34F03CH08950
SCBLC37F73CH08951
SCBLF34F43CH08952
SCBLC37F03CH08953
SCBLF34F83CH08954
SCBLC37F83CX08955
SCBLC37F83CH08956
SCBLC37F13CX08957
SCBLG37F33CX08958
SCBLF34F03CX08959
SCBLC37F13CX08960
SCBLC37F33CX08961
SCBLF34F73CH08962
SCBLC37F73CX08963
SCBLC37F93CX08964
SCBLC37F03CX08965
SCBLF34F43CH08966
SCBLF34F83CH08967
SCBLC37F63CX08968
SCBLF34FX3CH08969
SCBLC37F43CX08970
SCBLC37F23CH08971

SCBLC37F33CX09477
SCBLF34F73CH09478
SCBLF34F23CX09479
SCBLC37FX3CH09480
SCBLF34F03CX09481
SCBLF34F23CX09482
SCBLF34F03CH09483
SCBLC37F03CX09484
SCBLF34F83CX09485
SCBLC37F03CH09486
SCBLC37F23CH09487
SCBLC37F83CX09488
SCBLC37F63CH09489
SCBLF34F83CH09490
SCBLF34FX3CH09491
SCBLF34F53CX09492
SCBLF34F73CX09493
SCBLF34F53CH09494
SCBLC37F53CX09495
SCBLF34F23CX09496
SCBLC37F53CH09497
SCBLC37F03CX09498
SCBLC37F23CX09499
SCBLC37F53CX09500
SCBLF34F93CH09501
SCBLF34F43CX09502
SCBLF34F23CH09503
SCBLC37F93CH09504
SCBLF34FX3CX09505
SCBLF34F83CH09506
SCBLC37F83CX09507
SCBLF34F53CX09508
SCBLC37F13CX09509
SCBLC37F83CX09510
SCBLC37FX3CX09511

SCBLE42G24CX19208
SCBLM90A84CX19209
SCBLE37G34CH19210
SCBLE37G54CH19211
SCBLE42G44CX19212
SCBAM91A04CX19213
SCBLN91A54CX19214
SCBLE42GX4CX19215
SCBLE42G14CX19216
SCBLE37GX4CX19217
SCBLE42G54CX19218
SCBLE42G74CX19219
SCBAM91A84CX19220
SCBLE37G14CX19221
SCBLM90A94CX19222
SCBLE42G94CX19223
SCBLE37G74CX19224
SCBLE42G24CX19225
SCBLE42G44CX19226
SCBLE42G64CX19227
SCBLN91A54CX19228
SCBLE42GX4CX19229
SCBLE42G84CX19231
SCBLE42GX4CX19232
SCBLE37G84CX19233
SCBLE37G64CH19234
SCBLE37G84CH19235
SCBLE42G74CX19236
SCBLE37G14CH19237
SCBLE37G74CX19238
SCBLE42G24CX19239
SCBLE42G04CX19241
SCBLN90A84CX19242
SCBLE37G84CX19247
SCBLM91A35CX19300