



Mr. George Person
Chief, Recall Management Office
National Highway Traffic Safety Adm.
400 7th Street, S.W.
Washington, D.C. 20590

November 12, 2004

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 04V-464 began on 08 November 2004 and was completed on 12 November 2004. As required, copies of the final notifications are attached for your files.

If you should have any questions, please feel free to contact me at 541-998-3720 x138.

Sincerely,

Gary Dwyer
Director, Quality Assurance and Compliance Administration
Country Coach Inc.

Enclosures (2) Customer Notification, 04V-464
Dealer Notification, 04V-464

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448



VEHICLE SAFETY
DEFECT NOTICE

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

October 29, 2004

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 04V-464

Dear Country Coach Service Provider:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach, Inc. has decided that a safety defect exists on certain motor homes it manufactured. This condition is related certain towed vehicle lighting systems which, when wired into the clearance light circuit of the motorhome, will draw too much amperage causing the Type I circuit breaker to continuously reset. The unchecked resetting of the Type I circuit breakers will result in the overheating of 12V wires and insulation to a point that it could cause a fire.

MODELS AFFECTED:

Model Year: **2004 Inspire Motorhomes** manufactured from May 2003 to
March 2004

Model Year: **2005 Inspire Motorhomes** manufactured from March 2004 to
August 2004

Model Year: **2005 Allure Motorhomes** manufactured from June 2004 to
September 2004

A listing of all affected motorhomes is attached to this letter.

VEHICLE SAFETY
DEFECT NOTICE

Country Coach has determined that the repair for this safety defect will be the replacement of all 12V Type I circuit breakers, except for the circuit breaker on the ignition circuit, with 12V Type II circuit breakers. The 12V Type II circuit breaker remains open once tripped until power is removed and reapplied, or the over-current cause is removed. The labor required to remove and replace the affected circuit breakers and to change the fuse label on the inside of the circuit breaker panel for the appropriate circuits to read Type II is not expected to exceed one-half (1/2) hour.

If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonably equivalent motor home at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with owners and to repair their motor homes as soon as possible. You should be aware that owners are instructed to contact the customer service department if their dealer does not remedy the condition within three (3) days of the mutually agreed upon service date. Owners are also advised to contact the National Highway Traffic Safety Administration if the condition is not remedied without charge and within a reasonable time (Please see the enclosed Letter to Country Coach Owners).

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

Enclosure: Customer Notification

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.
Gary Obermire, Vice President, Engineering, Country Coach, Inc.

COACH LISTING

04V-464

Coach	Model	VIN
31111	MLT-40-MB-ABCD-05	4U7A8DS1351104109
31112	MLT-40-HR-ABD-05	4U7A8DS1X51104110
31113	MLT-40-MB-ABCD-05	4U7A8DS1451104121
31114	MLT-40-MB-ABCD-05	4U7A8DS1651104122
31115	MLT-40-MB-ABCD-05	4U7A8DS1251104134
31116	MLT-40-MB-ABCD-05	4U7A8DS1451104135
31117	MLT-40-MB-ABCD-05	4U7A8DS1651104136
31118	MLT-40-HR-ABD-05	4U7A8DS1851104137
31119	MLT-40-HR-ABD-05	4U7A8DS1X51104138
31120	MLT-40-MB-ABCD-05	4U7A8DS1X51104141
31121	MLT-40-HR-ABD-05	4U7A8DS1151104142
31122	MLT-40-HR-ABD-05	4U7A8DS1351104143
31123	MLT-40-HR-ABD-05	4U7A8DS1551104144
31124	MLT-40-HR-ABD-05	4U7A8DS1751104145
31125	MLT-40-HR-ABD-05	4U7A8DS1951104146
31126	MLT-40-HR-ABD-05	4U7A8DS1051104147
31127	MLT-42-SS-ABCD-05	4U7A8ES1051104168
31128	MLT-40-HR-ABD-05	4U7A8DS1351104174
31129	MLT-40-MB-ABCD-05	4U7A8DS1551104175
31130	MLT-40-HR-ABD-05	4U7A8DS1751104176
31131	MLT-42-SS-ABCD-05	4U7A8ES1151104177
31132	MLT-42-SS-ABCD-05	4U7A8ES1351104178
31133	MLT-40-HR-ABD-05	4U7A8DS1X51104186
31134	MLT-40-HR-ABD-05	4U7A8DS1651104203
31135	MLT-42-SS-ABCD-05	4U7A8ES1051104204
31136	MLT-40-HR-ABD-05	4U7A8DS1X51104205
31137	MLT-40-HR-ABD-05	4U7A8DS1051104214
31138	MLT-42-SS-ABCD-05	4U7A8ES1551104215
31139	MLT-40-MB-ABCD-05	4U7A8DS1451104216
31140	MLT-40-HR-ABD-05	4U7A8DS1651104217
31141	MLT-42-SS-ABCD-05	4U7A8ES1051104218
31142	MLT-40-MB-ABCD-05	4U7A8DS1X51104219
31143	MLT-40-HR-ABD-05	4U7A8DS1651104220
31144	MLT-42-SS-ABCD-05	4U7A8ES1551104229
31145	MLT-40-MB-ABCD-05	4U7A8DS1951104230
31147	MLT-40-HR-ABD-05	4U7A8DS1851104252
31157	MLT-40-HR-ABD-05	4U7A8DS1X51104298
51001	MIN-40-GATS-04	4U7K5EK1541103318
51002	MIN-40-GATS-04	4U7K5EK1741103319
51003	MIN-40-GATS-04	4U7K5EK1341103320
51004	MIN-40-GATS-04	4U7K5EK1041103419
51005	MIN-40-GATS-04	4U7K5EK1741103420
51006	MIN-40-GATS-04	4U7K5EK1941103421
51007	MIN-40-GATS-04	4U7K5EK1041103422
51008	MIN-40-GATS-04	4U7K5EK1241103423

COACH LISTING

04V-464

Coach	Model	VIN
51009	MIN-40-GATS-04	4U7K5EK1441103424
51010	MIN-40-GATS-04	4U7K5EK1641103425
51011	MIN-40-GATS-04	4U7K5EK1841103426
51012	MIN-40-GATS-04	4U7K5EK1X41103427
51013	MIN-40-GATS-04	4U7K5EK1141103428
51014	MIN-40-GATS-04	4U7K5EK1341103429
51015	MIN-40-GATS-04	4U7K5EK1X41103430
51016	MIN-40-GATS-04	4U7K5EK1141103431
51017	MIN-40-GATS-04	4U7K5EK1341103432
51018	MIN-40-GATS-04	4U7K5EK1541103433
51019	MIN-40-GATS-04	4U7K5EK1741103434
51020	MIN-40-GATS-04	4U7K5EK1941103435
51021	MIN-40-GATS-04	4U7K5EK1041103436
51022	MIN-40-GATS-04	4U7K5EK1241103437
51023	MIN-40-GATS-04	4U7K5EK1441103438
51024	MIN-40-GATS-04	4U7K5EK1641103439
51025	MIN-40-GATS-04	4U7K5EK1241103440
51026	MIN-40-GATS-04	4U7K5EK1441103441
51027	MIN-40-GATS-04	4U7K5EK1641103442
51028	MIN-40-GATS-04	4U7K5EK1841103443
51029	MIN-40-GATS-04	4U7K5EK1341103527
51030	MIN-40-GATS-04	4U7K5EK1541103528
51031	MIN-40-GATS-04	4U7K5EK1741103529
51032	MIN-40-GATS-04	4U7K5EK1341103530
51033	MIN-40-GATS-04	4U7K5EK1541103531
51034	MIN-40-GATS-04	4U7K5EK1741103532
51035	MIN-40-GATS-04	4U7K5EK1941103533
51036	MIN-40-GATS-04	4U7K5EK1041103534
51037	MIN-40-GATS-04	4U7K5EK1341103544
51038	MIN-40-GATS-04	4U7K5EK1541103545
51039	MIN-40-GATS-04	4U7K5EK1741103546
51040	MIN-40-GATS-04	4U7K5EK1941103547
51041	MIN-40-GATS-04	4U7K5EK1641103568
51042	MIN-40-GATS-04	4U7K5EK1841103569
51043	MIN-40-DV-ABD-04	4U7K5EK1441103570
51044	MIN-40-GATS-04	4U7K5EK1X41103573
51045	MIN-40-GATS-04	4U7K5EK1941103581
51046	MIN-40-GATS-04	4U7K5EK1041103582
51047	MIN-40-GATS-04	4U7K5EK1241103583
51048	MIN-40-GATS-04	4U7K5EK1X41103587
51049	MIN-40-GATS-04	4U7K5EK1X41103590
51050	MIN-40-DV-ABD-04	4U7K5EK1141103591
51051	MIN-40-DV-ABD-04	4U7K5EK1341103592
51052	MIN-40-GATS-04	4U7K5EK1941103595
51053	MIN-40-GATS-04	4U7K5EK1X41103606

COACH LISTING

04V-464

Coach	Model	VIN
51054	MIN-40-GATS-04	4U7K5EK1141103607
51055	MIN-40-GATS-04	4U7K5EK1341103608
51056	MIN-40-DV-ABD-04	4U7K5EK1141103610
51057	MIN-40-DV-ABD-04	4U7K5EK1341103611
51058	MIN-40-DV-ABD-04	4U7K5EK1541103612
51059	MIN-36-SA-ABCD-04	4U7K5DK1441103613
51060	MIN-40-DV-ABD-04	4U7K5EK1041103615
51061	MIN-40-DV-ABD-04	4U7K5EK1841103619
51062	MIN-40-DV-ABD-04	4U7K5EK1441103620
51063	MIN-40-DV-ABD-04	4U7K5EK1641103621
51064	MIN-36-SA-ABCD-04	4U7K5DK1541103622
51065	MIN-40-DV-ABD-04	4U7K5EK1741103630
51066	MIN-40-GATS-04	4U7K5EK1941103631
51067	MIN-40-DV-ABD-04	4U7K5EK1041103632
51068	MIN-40-DV-ABD-04	4U7K5EK1241103633
51069	MIN-36-SA-ABCD-04	4U7K5DK1241103660
51070	MIN-36-SA-ABCD-04	4U7K5DK1441103661
51071	MIN-36-SA-ABCD-04	4U7K5DK1641103662
51072	MIN-36-SA-ABCD-04	4U7K5DK1841103663
51073	MIN-36-SA-ABCD-04	4U7K5DK1X41103664
51074	MIN-36-SA-ABCD-04	4U7K5DK1141103665
51075	MIN-36-SA-ABCD-04	4U7K5DK1341103666
51076	MIN-36-SA-ABCD-04	4U7K5DK1541103667
51077	MIN-36-SA-ABCD-04	4U7K5DK1641103676
51078	MIN-40-DV-ABD-04	4U7K5EK1041103677
51079	MIN-40-DV-ABD-04	4U7K5EK1241103678
51080	MIN-40-DV-ABD-04	4U7K5EK1441103679
51081	MIN-40-DV-ABD-04	4U7K5EK1141103686
51082	MIN-36-SA-ABCD-04	4U7K6DK1441103687
51083	MIN-36-SA-ABCD-04	4U7K6DK1641103688
51084	MIN-40-DV-ABD-04	4U7K6EK1041103689
51085	MIN-36-SA-ABCD-04	4U7K6DK1541103696
51086	MIN-36-SA-ABCD-04	4U7K6DK1741103697
51087	MIN-40-DV-ABD-04	4U7K6EK1141103698
51088	MIN-36-SA-ABCD-04	4U7K6DK1041103699
51089	MIN-36-SA-ABCD-04	4U7K6DK1341103700
51090	MIN-40-GATS-04	4U7K6EK1841103701
51091	MIN-36-SA-ABCD-04	4U7K6DK1741103702
51092	MIN-40-DV-ABD-04	4U7K6EK1141103703
51093	MIN-40-DV-ABD-04	4U7K6EK1141103720
51094	MIN-36-SA-ABCD-04	4U7K6DK1041103721
51095	MIN-40-GATS-04	4U7K6EK1541103722
51096	MIN-36-SA-ABCD-04	4U7K6DK1441103723
51097	MIN-40-DV-ABD-04	4U7K6EK1941103724
51098	MIN-36-SA-ABCD-04	4U7K6DK1841103725

COACH LISTING

04V-464

Coach	Model	VIN
51099	MIN-36-SA-ABCD-04	4U7K6DK1X41103726
51100	MIN-40-DV-ABD-04	4U7K6EK1441103727
51101	MIN-36-SA-ABCD-04	4U7K6DK1441103737
51102	MIN-40-DV-ABD-04	4U7K6EK1941103738
51103	MIN-36-SA-AD-04	4U7K6DK1841103739
51104	MIN-36-SA-ABCD-04	4U7K6DK1441103740
51105	MIN-36-SA-ABCD-04	4U7K6DK1041103752
51106	MIN-36-SA-ABCD-04	4U7K6DK1241103753
51107	MIN-36-SA-ABCD-04	4U7K6DK1441103754
51108	MIN-36-SA-ABCD-04	4U7K6DK1641103755
51109	MIN-40-DV-ABD-04	4U7K6EK1641103762
51110	MIN-36-SA-ABCD-04	4U7K6DK1541103763
51111	MIN-36-SA-ABCD-04	4U7K6DK1741103764
51112	MIN-36-SA-ABCD-04	4U7K6DK1941103765
51113	MIN-36-SA-ABCD-04	4U7K6DK1041103766
51114	MIN-40-DV-ABD-04	4U7K6EK1541103767
51115	MIN-36-SA-ABCD-04	4U7K6DK1441103768
51116	MIN-40-GATS-04	4U7K6EK1941103769
51117	MIN-36-SA-ABCD-04	4U7K6DK1241103770
51118	MIN-40-GATS-04	4U7K6EK1741103771
51119	MIN-36-SA-ABCD-04	4U7K6DK1641103772
51120	MIN-40-DV-ABD-04	4U7K6EK1041103773
51121	MIN-40-GATS-04	4U7K6EK1141103801
51122	MIN-36-SA-ABD-04	4U7K6DK1041103802
51123	MIN-40-DV-ABD-04	4U7K6EK1541103803
51124	MIN-40-DV-ABD-04	4U7K6EK1741103804
51125	MIN-40-DV-ABD-04	4U7K6EK1941103805
51126	MIN-36-SA-ACD-04	4U7K6DK1841103806
51127	MIN-36-SA-ACD-04	4U7K6DK1X41103807
51128	MIN-40-DV-ABD-04	4U7K6EK1141103829
51129	MIN-40-DV-ABD-04	4U7K6EK1841103830
51130	MIN-36-SA-ABCD-04	4U7K6DK1741103831
51131	MIN-40-GATS-04	4U7K6EK1141103832
51132	MIN-40-GATS-04	4U7K6EK1341103833
51133	MIN-40-DV-ABD-04	4U7K6EK1541103834
51134	MIN-36-SA-ABCD-04	4U7K6DK1441103835
51135	MIN-40-DV-ABD-04	4U7K6EK1941103836
51136	MIN-36-SA-ACD-04	4U7K6DK1841103837
51137	MIN-36-SA-ACD-04	4U7K6DK1141103839
51138	MIN-40-GATS-04	4U7K6EK1041103840
51139	MIN-36-SA-ABCD-04	4U7K6DK1X41103841
51140	MIN-36-SA-ABCD-04	4U7K6DK1141103842
51141	MIN-40-GATS-04	4U7K6EK1641103843
51142	MIN-40-DV-ABD-04	4U7K6EK1541103851
51143	MIN-36-SA-ABD-04	4U7K6DK1441103852

COACH LISTING

04V-464

Coach	Model	VIN
51144	MIN-36-SA-ABCD-04	4U7K6DK1641103853
51145	MIN-36-SA-ABCD-04	4U7K6DK1841103854
51146	MIN-40-GATS-04	4U7K6EK1241103855
51147	MIN-36-SA-ABCD-04	4U7K6DK1941103863
51148	MIN-40-GATS-04	4U7K6EK1341103864
51149	MIN-40-GATS-04	4U7K6EK1541103865
51150	MIN-40-DV-ABD-04	4U7K6EK1741103866
51151	MIN-40-DV-ABD-04	4U7K6EK1941103867
51152	MIN-40-DV-ABD-04	4U7K6EK1041103868
51153	MIN-40-DV-ABD-04	4U7K6EK1241103869
51154	MIN-40-DV-ABD-04	4U7K6EK1941103870
51155	MIN-36-SA-ABCD-04	4U7K6DK1841103871
51156	MIN-40-DV-ABD-04	4U7K6EK1241103872
51157	MIN-40-GATS-04	4U7K6EK1441103873
51158	MIN-36-SA-ABCD-04	4U7K6DK1X41103886
51159	MIN-40-DV-ABD-04	4U7K6EK1441103887
51160	MIN-40-DV-ABD-04	4U7K6EK1641103888
51161	MIN-40-GATS-04	4U7K6EK1441103890
51162	MIN-40-GATS-04	4U7K6EK1641103891
51163	MIN-40-GATS-04	4U7K6EK1841103892
51164	MIN-40-GATS-04	4U7K6EK1X41103893
51165	MIN-36-SA-ABCD-04	4U7K6DK1941103894
51166	MIN-40-DV-ABD-04	4U7K6ES1341103895
51167	MIN-40-DV-ABD-04	4U7K6EK1341103914
51168	MIN-40-DV-ABD-04	4U7K6EK1541103915
51169	MIN-36-SA-ABCD-04	4U7K6DK1441103916
51170	MIN-36-SA-AD-04	4U7K6DK1641103917
51171	MIN-36-SA-ABCD-04	4U7K6DK1841103918
51172	MIN-40-GATS-04	4U7K6EK1241103919
51173	MIN-40-DV-ABD-05	4U7K6ES1751103920
51174	MIN-36-SA-ABCD-05	4U7K6DS1651103921
51175	MIN-40-GATS-05	4U7K6ES1051103922
51176	MIN-40-DV-ABD-05	4U7K6ES1251103923
51177	MIN-40-GATS-05	4U7K6ES1451103924
51178	MIN-36-SA-ABCD-05	4U7K6DS1351103925
51179	MIN-36-SA-ABCD-05	4U7K6DS1051103929
51180	MIN-40-DV-ABD-05	4U7K6ES1X51103930
51181	MIN-40-DV-ABD-05	4U7K6ES1151103931
51182	MIN-40-DV-ABD-05	4U7K6ES1351103932
51183	MIN-40-DV-ABD-05	4U7K6ES1551103933
51184	MIN-36-SA-ABCD-05	4U7K6DS1451103934
51185	MIN-36-SA-ABCD-05	4U7K6DS1151103938
51186	MIN-36-SA-ABCD-05	4U7K6DS1351103939
51187	MIN-40-DV-ABD-05	4U7K6ES1X51103944
51188	MIN-36-SA-ABCD-05	4U7K6DS1951103945

COACH LISTING

04V-464

Coach	Model	VIN
51189	MIN-40-DV-ABD-05	4U7K6ES1351103946
51190	MIN-40-DV-ABD-05	4U7K6ES1551103947
51191	MIN-36-SA-ABD-05	4U7K6DS1551103957
51192	MIN-40-GATS-05	4U7K6ES1X51103958
51193	MIN-36-SA-ABD-05	4U7K6DS1951103959
51194	MIN-36-SA-ABCD-05	4U7K6DS1551103960
51195	MIN-40-DV-ABD-05	4U7K6ES1X51103961
51196	MIN-36-SA-ABCD-05	4U7K6DS1951103962
51197	MIN-40-DV-ABD-05	4U7K6ES1851103988
51198	MIN-36-SA-ABCD-05	4U7K6DS1751103989
51199	MIN-40-DV-ABD-05	4U7K6ES1651103990
51200	MIN-40-DV-ABD-05	4U7K6ES1851103991
51201	MIN-40-GATS-05	4U7K6ES1X51103992
51202	MIN-40-DV-ABD-05	4U7K6ES1151103993
51203	MIN-36-SA-ABCD-05	4U7K6DS1451104002
51204	MIN-40-GATS-05	4U7K6ES1951104003
51205	MIN-36-SA-ABCD-05	4U7K6DS1851104004
51206	MIN-40-GATS-05	4U7K6ES1251104005
51207	MIN-40-GATS-05	4U7K6ES1451104006
51208	MIN-40-GATS-05	4U7K6FS1651104007
51209	MIN-36-SA-ABCD-05	4U7K6DS1951104013
51210	MIN-40-DV-ABD-05	4U7K6ES1351104014
51211	MIN-36-SA-ABCD-05	4U7K6DS1251104015
51212	MIN-36-SA-ABCD-05	4U7K6DS1451104016
51213	MIN-40-DV-ABD-05	4U7K6ES1951104017
51214	MIN-40-DV-ABD-05	4U7K6ES1051104018
51215	MIN-36-SA-ABCD-05	4U7K6DS1351104024
51216	MIN-36-SA-ABCD-05	4U7K6DS1551104025
51217	MIN-40-GATS-05	4U7K6ES1X51104026
51218	MIN-40-DV-ABD-05	4U7K6ES1151104027
51219	MIN-36-SA-ABCD-05	4U7K6DS1051104028
51220	MIN-36-SA-ABCD-05	4U7K6DS1251104029
51221	MIN-40-DV-ABD-05	4U7K6ES1551104046
51222	MIN-36-SA-ABCD-05	4U7K6DS1451104047
51223	MIN-40-DV-ABD-05	4U7K6ES1951104048
51224	MIN-40-GATS-05	4U7K6ES1051104049
51225	MIN-40-GATS-05	4U7K6ES1751104050
51226	MIN-40-DV-ABD-05	4U7K6ES1951104051
51227	MIN-40-DV-ABD-05	4U7K6ES1051104052
51228	MIN-40-DV-ABD-05	4U7K6ES1251104053
51229	MIN-40-DV-ABD-05	4U7K6ES1451104054
51230	MIN-40-DV-ABD-05	4U7K6ES1651104055
51231	MIN-36-SA-ABCD-05	4U7K6DS1551104056
51232	MIN-40-DV-ABD-05	4U7K6ES1X51104057
51233	MIN-40-DV-ABD-05	4U7K6ES1151104058

COACH LISTING

04V-464

Coach	Model	VIN
51234	MIN-40-GATS-05	4U7K6ES1551104077
51235	MIN-36-SA-ABCD-05	4U7K6DS1451104078
51236	MIN-40-GATS-05	4U7K6ES1951104079
51237	MIN-40-DV-ABD-05	4U7K6ES1551104080
51238	MIN-36-SA-ABCD-05	4U7K6DS1451104081
51239	MIN-36-SA-ABD-05	4U7K6DS1651104082
51240	MIN-40-DV-ABD-05	4U7K6ES1051104083
51241	MIN-40-DV-ABD-05	4U7K6ES1251104084
51242	MIN-40-GATS-05	4U7K6ES1451104085
51243	MIN-36-SA-ABCD-05	4U7K6DS1351104086
51244	MIN-40-GATS-05	4U7K6ES1851104087
51245	MIN-36-SA-ABCD-05	4U7K6DS1751104088
51246	MIN-40-DV-ABD-05	4U7K6ES1151104089
51247	MIN-40-GATS-05	4U7K6ES1851104090
51248	MIN-40-GATS-05	4U7K6ES1751104095
51249	MIN-36-SA-ABCD-05	4U7K6DS1651104096
51250	MIN-36-SA-ABCD-05	4U7K6DS1851104097
51251	MIN-36-SA-ABCD-05	4U7K6DS1X51104098
51252	MIN-36-SA-ABCD-05	4U7K6DS1151104099
51253	MIN-36-SA-ABCD-05	4U7K6DS1451104100
51254	MIN-36-SA-ABCD-05	4U7K6DS1651104101
51255	MIN-36-SA-ABCD-05	4U7K6DS1951104111
51256	MIN-36-SA-ABCD-05	4U7K6DS1051104112
51257	MIN-40-DV-ABD-05	4U7K6ES1551104113
51258	MIN-36-SA-ABCD-05	4U7K6DS1451104114
51259	MIN-40-DV-ABD-05	4U7K6ES1951104115
51260	MIN-40-DV-ABD-05	4U7K6ES1051104116
51261	MIN-40-GATS-05	4U7K6ES1251104117
51262	MIN-40-DV-ABD-05	4U7K6ES1851104123
51263	MIN-36-SA-ABCD-05	4U7K6DS1751104124
51264	MIN-36-SA-ABCD-05	4U7K6DS1951104125
51265	MIN-40-DV-ABD-05	4U7K6ES1351104126
51266	MIN-40-DV-ABD-05	4U7K6ES1551104127
51267	MIN-36-SA-ABCD-05	4U7K6DS1451104128
51268	MIN-40-GATS-05	4U7K6ES1951104129
51269	MIN-40-DV-ABD-05	4U7K6ES1251104148
51270	MIN-40-DV-ABD-05	4U7K6ES1451104149
51271	MIN-36-SA-ABCD-05	4U7K6DS1851104150
51272	MIN-40-GATS-05	4U7K6ES1251104151
51273	MIN-40-DV-ABD-05	4U7K6ES1451104152
51274	MIN-36-SA-ABCD-05	4U7K6DS1351104153
51275	MIN-36-SA-ABCD-05	4U7K6DS1551104154
51276	MIN-40-DV-ABD-05	4U7K6ES1351104157
51277	MIN-36-SA-ABCD-05	4U7K6DS1251104158
51278	MIN-36-SA-ABCD-05	4U7K6DS1451104159

COACH LISTING

04V-464

Coach	Model	VIN
51279	MIN-40-DV-ABD-05	4U7K6ES1351104160
51280	MIN-40-GATS-05	4U7K6ES1551104161
51281	MIN-40-GATS-05	4U7K6ES1751104162
51282	MIN-40-DV-ABD-05	4U7K6ES1951104163
51283	MIN-36-SA-ABCD-05	4U7K6DS1X51104179
51284	MIN-36-SA-ABCD-05	4U7K6DS1651104180
51285	MIN-36-SA-ABCD-05	4U7K6DS1851104181
51286	MIN-40-DV-ABD-05	4U7K6ES1251104182
51287	MIN-36-SA-ABCD-05	4U7K6DS1151104183
51288	MIN-40-DV-ABD-05	4U7K6ES1151104187
51289	MIN-36-SA-ABCD-05	4U7K6DS1051104188
51290	MIN-36-SA-ABCD-05	4U7K6DS1251104189
51291	MIN-36-SA-ABCD-05	4U7K6DS1951104190
51292	MIN-40-GATS-05	4U7K6ES1351104191
51293	MIN-40-GATS-05	4U7K6ES1551104192
51294	MIN-40-DV-ABD-05	4U7K6ES1751104193
51295	MIN-40-GATS-05	4U7K6ES1151104206
51296	MIN-36-SA-ABCD-05	4U7K6DS1051104207
51297	MIN-40-DV-ABD-05	4U7K6ES1551104208
51298	MIN-40-GATS-05	4U7K6ES1751104209
51299	MIN-36-SA-ABCD-05	4U7K6DS1051104210
51300	MIN-40-GATS-05	4U7K6ES1551104211
51301	MIN-36-SA-ABCD-05	4U7K6DS1451104212
51302	MIN-40-GATS-05	4U7K6ES1851104221
51303	MIN-36-SA-ABCD-05	4U7K6DS1751104222
51304	MIN-36-SA-ABCD-05	4U7K6DS1951104223
51305	MIN-36-SA-ABCD-05	4U7K6DS1051104224
51306	MIN-36-SA-ABCD-05	4U7K6DS1251104225
51307	MIN-40-DV-ABD-05	4U7K6ES1751104226
51308	MIN-36-SA-ABCD-05	4U7K6DS1651104227
51309	MIN-40-DV-ABD-05	4U7K6ES1551104242
51310	MIN-40-GATS-05	4U7K6ES1751104243
51311	MIN-40-GATS-05	4U7K6ES1951104244
51312	MIN-40-GATS-05	4U7K6ES1051104245
51313	MIN-36-SA-ABCD-05	4U7K6DS1X51104246
51314	MIN-40-DV-ABD-05	4U7K6ES1451104247
51315	MIN-36-SA-ABCD-05	4U7K6DS1051104272
51316	MIN-40-DV-ABD-05	4U7K6ES1551104273
51317	MIN-36-SA-ABCD-05	4U7K6DS1451104274
51318	MIN-36-SA-ACD-05	4U7K6DS1651104275
51319	MIN-40-DV-ABD-05	4U7K6ES1051104276
51320	MIN-36-SA-ABCD-05	4U7K6DS1X51104277
51321	MIN-40-GATS-05	4U7K6ES1451104278
51322	MIN-40-DV-ABD-05	4U7K6ES1651104279
51323	MIN-36-SA-ABCD-05	4U7K6DS1X51104280

COACH LISTING

04V-464

Coach	Model	VIN
51324	MIN-36-SA-ABCD-05	4U7K6ES1651104279
51325	MIN-40-GATS-05	4U7K6ES1651104282
51326	MIN-36-SA-ABCD-05	4U7K6DS1551104283
51327	MIN-36-SA-ABCD-05	4U7K6DS1751104284
51328	MIN-36-SA-ABCD-05	4U7K6DS1951104285
51329	MIN-36-SA-ABCD-05	4U7K6DS1X51104313
51330	MIN-40-GATS-05	4U7K6ES1351104286
51331	MIN-40-DV-ABD-05	4U7K6ES1551104287
51333	MIN-36-SA-ABCD-05	4U7K6DS1651104289
51334	MIN-40-DV-ABD-05	4U7K6ES1551104290
51335	MIN-40-DV-ABD-05	4U7K6ES1751104291
51336	MIN-36-SA-ABD-05	4U7K6DS1651104292
51337	MIN-36-SA-ACD-05	4U7K6DS1151104300
51338	MIN-40-DV-ABD-05	4U7K6ES1651104301
51339	MIN-36-SA-AD-05	4U7K6DS1551104302
51340	MIN-40-GATS-05	4U7K6ES1X51104303
51341	MIN-40-DV-ABD-05	4U7K6ES1151104304
51342	MIN-40-DV-ABD-05	4U7K6ES1351104305
51343	MIN-40-GATS-05	4U7K6ES1551104306
51344	MIN-40-DV-ABD-05	4U7K6ES1751104324



VEHICLE SAFETY
DEFECT NOTICE

COUNTRY COACH

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED, AND
FIRST CLASS MAIL

November 8, 2004

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 04V-464

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, CFR 49, 573.5 and 573.6.

DESCRIPTION OF SAFETY DEFECT:

Country Coach, Inc. has decided that a safety defect exists on certain motor homes it manufactured. This condition is related certain towed vehicle lighting systems which, when wired into the clearance light circuit of the motorhome, will draw too much amperage causing the Type I circuit breaker to continuously reset. The unchecked resetting of the Type I circuit breakers will result in the overheating of 12V wires and insulation to a point that it could cause a fire.

MODELS AFFECTED:

Model Year: 2004 Inspire Motorhomes manufactured from May 2003 to March 2004

Model Year: 2005 Inspire Motorhomes manufactured from March 2004 to August 2004

Model Year: 2005 Allure Motorhomes manufactured from June 2004 to September 2004

A listing of all affected motorhomes is attached to this letter.

Country Coach has determined that the repair for this safety defect will be the replacement of all 12V Type I circuit breakers, except for the circuit breaker on the ignition circuit, with 12V Type II circuit breakers. The 12V Type II circuit breaker remains open once tripped until power is removed and reapplied, or the over-current cause is removed. The labor required to remove and replace the affected circuit breakers and to change the fuse label on the inside of the circuit breaker panel for the appropriate circuits to read Type II is not expected to exceed one-half (1/2) hour. Please present this letter and the enclosed warranty claim to the dealer when you take your motor home in to be serviced. The service facility that does the repairs will need the warranty claim for their billing.

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue, | PO Box 400 | Junction City, OR 97448

Page 1

VEHICLE SAFETY
DEFECT NOTICE

If you need assistance in locating your nearest Country Coach dealer, please contact Country Coach's customer service department at 1-800-452-8015. The service department will refer you to a service facility near you. Country Coach has provided all of its dealers with instructions for making the necessary repairs. If your dealer fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Country Coach customer service by calling 1-800-452-8015 and ask for the Technical Service Representative handling this recall.

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Country Coach Inc. Compliance Administration at 1-800-452-8015, extension 382.

If after contacting both your dealer and Country Coach you are not satisfied that the noncompliance has been remedied within a reasonable time, and at no cost to you, you may wish to contact the National Highway Traffic Safety Administration at the following address or call the Auto Safety Hotline's toll free number:

Administrator
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington D.C. 20590

Auto Safety Hotline's toll free number: 1-888-327-4236.

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Gary Dwyer, Director, QA and Compliance
Country Coach, Inc.

Enclosures (2): Vehicle Reply Card
Warranty Claim

cc: Dick Sabath, QA and Compliance Administration, Country Coach, Inc.
Gary Obermire, Vice President, Engineering, Country Coach, Inc.