

Facsimile

Arent Fox

Date: May 8, 2007
Pages (including cover): 6
Attorney #: 0047
Client.Matter #: 016606 00000

Lawrence F. Henneberger
Attorney
202/857-6087 DIRECT
202/857-6395 FAX
hennl@arentfox.com

PLEASE DELIVER TO:

| Name/Company | Fax # | Verify # |
|--|--------------|--------------|
| George Person/Kelly Schuler Office of Defects Investigation | 202/366-7882 | 202/366-5232 |

MESSAGE/INSTRUCTIONS

Re: Transmission of Harley-Davidson Third Recall Notice Package (Recall No. 04E-094)

George/Kelly: Attached is a third notice recall package from my client Harley-Davidson Motor Company, in the above-referenced campaign. This recall involved fuel valve and parts kits.

This action is part of Harley-Davidson's continuing efforts to increase completion rates of its recalls with follow-up notifications to affected motorcycle owners and purchasers of components who have not yet responded to the campaign. As you will note, the third notice letter attaches, in turn, the original Part 577 customer letter approved by NHTSA/ODI which was sent in that campaign. The third notice package also includes an explanatory letter to dealers.



Attachments (3)

cc: Robert J. Brand, Esq. (w/o attachments)
Ms. Lisa Garner (w/o attachments)

RPP/166038.1 PLEASE CALL OUR FAX OPERATOR AS SOON AS POSSIBLE IF TRANSMISSION IS NOT COMPLETE:
202/857-6119

This facsimile contains privileged and confidential information intended only for the use of the addressee(s) named above. If you are not the intended recipient of this facsimile, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that any dissemination or copying of this facsimile is strictly prohibited. If you have received this facsimile in error, please immediately notify us by telephone and return the original facsimile to us at the address below via the postal service. Thank you.

Arent Fox LLP / 1050 Connecticut Avenue, NW / Washington, DC 20036-5339 / T 202.857.6000 / F 202.857.6395 / www.arentfox.com

SAFETY RECALL THIRD NOTICE

May 18, 2007

NHTSA SAFETY RECALL CAMPAIGN # - 04V-607; 04E-094; NVS-215kjs

Dear Harley-Davidson Motorcycle Owner:

In January 2005, you and other registered owners were notified by the attached letters that a defect which relates to motor vehicle safety exists on certain 2005 carbureted Sportsters, Dyna, Softail and Touring model Motorcycles and in some fuel valve parts/kits. These parts/kits consist of four separate part numbers as follows: Part # 61338-02, 62169-02A, 61338-94D and 62169-95C. This is a follow-up to that earlier communication.

Our records indicate you have not responded to our recall notice. Therefore, we are sending you this third notice in order to re-emphasize the importance of having your motorcycle serviced immediately to remedy the safety issues described in our earlier letter. A brief description of the defect and safety issue involved is described in the attached copy of our earlier letter to you.

Please contact your Harley-Davidson dealer immediately for an appointment to have your motorcycle serviced according to instructions contained in the letter attached.

If your dealer has already serviced your motorcycle under this recall, you are receiving this letter because we have not been notified that the work had been completed. We ask that you take the enclosed service card to your dealer, have it completed, signed by you and your dealer, and returned to us for our records as required by law. (Disregard this instruction if you have had the service completed recently, since it takes some time for mailing and our processing of information). This will assist us in accurately reporting vital information to NHTSA about your vehicle, as required by law.

If you have sold your motorcycle, please fill out and mail the enclosed Motorcycle Owner Card with the appropriate information about your purchaser. This will enable us to contact him/her and advise that person of this recall.

Sincerely,

Harley-Davidson Motor Company, Inc.
Attachments 0118

SAMPLE COPY

January 27, 2005

NHTSA SAFETY RECALL CAMPAIGN #: 04E-094

Dear Harley-Davidson Motorcycle Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Harley-Davidson Motor Company, Inc. has decided that a defect, which relates to motor vehicle safety, exists in some fuel valve parts/kits. These parts/kits consist of four separate part numbers as follows: Part # 61338-02, 62169-02A, 61338-94D and 62169-95C. These parts/kits were manufactured defectively by our supplier. As a result the functionality of the "on" position and the "reserve" position of the valve have been reversed. Consequently, when the control handle of the valve is set in the "on" position the valve actually selects the "reserve" position fuel flow path, and when the valve is in the "reserve" position it selects the "on" flow path. When the operator of a vehicle with one of these valves is operating the bike with the valve in the "on" position, and begins to run out of fuel, the expected fuel reserve will not be available. This could lead to the driver running out of gas without warning and cause an accident with resulting injuries or death.

Dealer records indicate that you have purchased one of these parts/kits involved in this safety recall, and therefore may have installed on your vehicle.

If you or the dealer have installed one of these suspect valves on your motorcycle, we strongly urge you to take your motorcycle to your dealer to have the valve inspected for proper operation as soon as possible. If you had this inspection and/or repair completed before you received this letter, you may be eligible to receive reimbursement for the cost of the repair. For more information contact Harley-Davidson at 1-414-343-4056. Should you choose to ride your motorcycle prior to this service, we urge you to be aware of this condition.

Please contact your Harley-Davidson motorcycle dealer immediately and arrange an appointment to have your fuel valve inspected and replaced if necessary. The dealer labor time to perform

this service takes less than 1 hour and the parts and labor will be free of charge to you. Parts should be available at your dealership on approximately the week of January 17, 2005. To verify that the service has been completed your Dealer will ask you to sign a recall claim. If you have sold your motorcycle, please forward the appropriate information about your purchaser. This will enable us to contact him/her and advise that person of this recall. Also, Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you take your motorcycle to your dealer on a mutually agreed upon date and he does not perform the required service to your satisfaction, please contact Harley-Davidson Motor Company, Inc. for immediate assistance at the address or telephone number listed on this letterhead. If your dealer or Harley-Davidson Motor Company, Inc. fails or is unable to remedy your motorcycle without charge within a reasonable time, you may wish to inform the Administrator, The National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, or call the toll-free Auto Safety Hotline at 1-888-DASH-2DOT or contact NHTSA at www.NHTSA.DOT.GOV.

We regret any inconvenience this may cause you, but we are initiating this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.

Sincerely,

Harley-Davidson Motor Company, Inc.
0118

May 8, 2007

SERVICE LETTER ML-426

NHTSA SAFETY RECALL CAMPAIGN # - 04V-607; 04E-094; NVS-215kjs

IMPORTANT SAFETY RECALL CAMPAIGN INFORMATION!

Dear Dealer,

In a continuing effort to increase the completion rates of our safety recalls we have established a procedure to send follow-up notifications to the motorcycle owners of record who haven't had their motorcycles serviced in response to selected recalls. This communication and the attached sample Customer Letter relate to the following recall.


CODE 0118 FUEL SHUT-OFF VALVE CARB

This recall relates to certain 2005 carbureted Sportsters, Dyna, Softail and Touring model Motorcycles and in some fuel valve parts/kits. The recall was initiated in January 2005. A sample of the follow-up letter, which we are sending to all registered owners of unserviced vehicles, is attached. Please refer to h-dnet.com on the **Service Page, Safety Campaign and Product Campaign link, Safety Campaign and Open VIN lists link** for an updated list of Code 0118 vehicle VINs which our records show as still being unserviced. Select the appropriate campaign number link (0118) to view any outstanding vehicles involved in this recall. Refer to Harley-Davidson Service Bulletin M-1167 dated January 26, 2005 for details on carrying out the requirements for this recall. Parts for this recall are currently available. Current shipment records indicate a number of kits are available in the field at the dealer level. Please check your inventory before placing any orders for parts. You may be required to provide a VIN for each recall kit ordered. Please refer to the related Service Bulletin for detailed instructions.

If a VIN appears on the h-dnet.com list for a vehicle on which you have recently completed this recall, please disregard. DO NOT send in a duplicate service card. However, if a vehicle appears on the list that you know you have completed the recall on some time ago, please fill out a Dealer Service Card and attach a copy of your internal repair order to the card. We will use this information to update our records and issue you the appropriate amount of labor for performing the service. This information will be essential in reporting our completion rates to NHTSA, as required.

Your cooperation in this effort is appreciated.

Sincerely,

A handwritten signature in black ink, reading "Sarah S. Ottallah". The signature is written in a cursive style with a large, looping initial "S".

Sarah S. Ottallah
Manager, Warranty and Recall Administration
0118