



All

DATE 07/05

7-30USA

SERVICE

ADMINISTRATION BULLETIN

Accelerator Pedal Alignment –
Check/Replace Accelerator Pedal Assembly –
Recall Action R847

MODEL 2006 MY
XK Range
VIN See VIN list

Issue:

A concern has been identified with the alignment of the accelerator pedal on a number of XK vehicles within the above VIN range.

The accelerator pedal arms, manufactured out of circular section steel, were incorrectly formed by the pedal supplier. Some of the parts from this batch of pedal arms were assembled into the accelerator pedal assemblies of Jaguar XK vehicles. This results in reduced clearance between the accelerator pedal and the brake pedal and can increase the risk of both pedals being applied by the driver at the same time.

Jaguar Cars has decided to recall the affected vehicles for an inspection to determine if the pedal assembly is from the affected batch. If needed, the pedal assembly will be replaced with a new one.

A number of vehicles have been reworked at the factory prior to dispatch and are not affected by this Recall Action. **To assist you in identifying the vehicles that need to be inspected, an affected vehicle listing is included. If the vehicle is not on the affected vehicle list, no rework action is required.** Please ensure that you check the vehicle is still outstanding prior to undertaking any rework action. DDW will be updated from the date of this Recall Action to reflect only the vehicles still outstanding the inspection and rework.

Action:

Check the accelerator pedal alignment of all 2006 MY XK vehicles listed in this bulletin.

All unsold vehicles and vehicles that have not been handed over to the customer must be inspected and, if necessary, repaired prior to sale or onward distribution.

If the inspection reveals that the alignment of the accelerator pedal is within the acceptable limit, no further action is required. The workshop procedure for the inspection is included in this bulletin.

If the alignment of the accelerator pedal is outside of the acceptable limit, replace the accelerator pedal assembly. To replace the accelerator pedal assembly, refer to Global Technical Reference (GTR), Workshop Manual; section 310-02 Acceleration Control.

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

XK ACCELERATOR PEDAL ALIGNMENT

Check the alignment of the accelerator pedal (item 1 of Illustration 1) and the throttle stop (item 2 of Illustration 1).




ILLUSTRATION 1

1. Depress the accelerator pedal to contact the throttle stop.

Note: The accelerator pedal should cover a minimum of half the throttle stop laterally (measuring across the center) leaving a maximum of 20 mm (A, Illustration 2) of exposed throttle stop.

2. If the measurement is 20 mm or less, torque the accelerator pedal assembly fixings




ILLUSTRATION 2

to 9 Nm (6.6 lb-ft); no further action is required.

3. If the measurement is greater than 20 mm (C, Illustration 3), remove the accelerator pedal assembly. Refer to Global Technical Reference (GTR), Workshop Manual, section 310-02.




ILLUSTRATION 3

4. Remove the throttle stop and locating stud from the removed accelerator pedal assembly and install it on the new accelerator pedal assembly, part number JLM 21753.
5. If the accelerator pedal pad is aluminum, remove the aluminum pedal pad from the removed pedal assembly and install it on the new pedal assembly.
6. Install the new accelerator pedal assembly, refer to Global Technical Reference (GTR), Workshop Manual, section 310-02.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechinfo.com>

Parts Information:

Please note that not every vehicle will require a throttle pedal. Please order accordingly.

DESCRIPTION

Accelerator pedal assembly

PART NUMBER

JLM 21753

QTY

1

VIN LIST OF AFFECTED VEHICLES**USA**

VIN	DLR NO.	DLR NAME
SAJDA42C462A45375	0349	Byers Imports
SAJDA41B663A45834	0580	Bauer Jaguar
SAJDA41C862A45798	0609	Jaguar of Great Neck/Roslyn
SAJDA42B063A45357	0609	Jaguar of Great Neck/Roslyn
SAJDA42B763A45646	0609	Jaguar of Great Neck/Roslyn
SAJDA42B563A45399	0660	Bill Rapp Jaguar
SAJDA41C662A45654	0696	Alpine Jaguar
SAJDA42C462A45943	0734	Thoroughbred Motorcars, Inc
SAJDA42C662A45832	5454	Checkered Flag Jaguar
SAJDA42C762A45869	5454	Checkered Flag Jaguar
SAJDA41B863A45768	5490	Jaguar Tysons Corner
SAJDA42C062A46135	5490	Jaguar Tysons Corner
SAJDA41C862A45624	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA41C962A45681	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA42C462A45473	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA42C662A45958	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA41B163A45367	5612	Jaguar Huntsville
SAJDA42C162A45544	5612	Jaguar Huntsville
SAJDA42B463A46009	5618	Hennessy Jaguar
SAJDA42B763A45453	5618	Hennessy Jaguar
SAJDA42B763A45548	5618	Hennessy Jaguar
SAJDA42B963A46006	5618	Hennessy Jaguar
SAJDA42C762A45435	5618	Hennessy Jaguar
SAJDA42CX62A45378	5618	Hennessy Jaguar
SAJDA41B163A45966	5662	Leith Jaguar
SAJDA41C562A45693	5662	Leith Jaguar
SAJDA42B363A45465	5670	White Plains Jaguar
SAJDA42B563A45676	5670	White Plains Jaguar
SAJDA42C662A45538	5691	Jaguar of Sarasota
SAJDA42C162A45673	5703	Galpin Jaguar
SAJDA41B963A45780	5708	THE COLLECTION
SAJDA41C462A45684	5708	THE COLLECTION
SAJDA42C062A45910	5708	THE COLLECTION
SAJDA42C162A45964	5708	THE COLLECTION
SAJDA42C262A45908	5708	THE COLLECTION
SAJDA42C662A45961	5708	THE COLLECTION
SAJDA41BX63A45870	5709	Ray Catena Jaguar of Edison
SAJDA42B263A45330	5725	Manhattan Jaguar/NYC
SAJDA42C562A45336	5725	Manhattan Jaguar/NYC



USA continued

VIN	DLR NO.	DLR NAME
SAJDA42B163A45545	5726	Parretti Jaguar Baton Rouge
SAJDA42B663A45959	5727	Crest Jaguar of Woodbridge
SAJDA41B263A45510	5735	Millennium Motor Cars
SAJDA41B763A45406	5736	Holman Motorcars
SAJDA42C362A45836	5741	Royal Jaguar of Tucson
SAJDA42B563A45354	5742	Heritage Jaguar of Freeport
SAJDA42B563A46102	5742	Heritage Jaguar of Freeport
SAJDA42B663A45380	5742	Heritage Jaguar of Freeport
SAJDA42C062A45499	5742	Heritage Jaguar of Freeport
SAJDA42C462A46039	5742	Heritage Jaguar of Freeport
SAJDA42C662A45426	5742	Heritage Jaguar of Freeport
SAJDA42CX62A45476	5742	Heritage Jaguar of Freeport
SAJDA42C262A45830	5744	Jaguar Huntington
SAJDA42C662A45829	5749	Ray Catena Jaguar of Monmouth
SAJDA41C562A45645	5759	Bobby Rahal Jaguar
SAJDA42B363A45563	5759	Bobby Rahal Jaguar
SAJDA42C062A45700	5759	Bobby Rahal Jaguar
SAJDA42C462A45604	5759	Bobby Rahal Jaguar
SAJDA42C562A45353	5761	Dreher-Holloway Jaguar
SAJDA41B863A45334	5766	Nalley Jaguar
SAJDA41B863A45687	5766	Nalley Jaguar
SAJDA42C062A45583	5766	Nalley Jaguar
SAJDA42C362A45366	5766	Nalley Jaguar
SAJDA42C662A45541	5766	Nalley Jaguar
SAJDA41C262A45702	5768	Jaguar of Tampa
SAJDA42C762A45905	5768	Jaguar of Tampa
SAJDA41C362A45711	5777	Hennessy Jaguar of Gwinnett
SAJDA42B363A45479	5791	Jaguar Mt. Kisco
SAJDA42C162A45589	5797	Jaguar Annapolis
SAJDA42C162A45592	5797	Jaguar Annapolis
SAJDA41BX63A45495	9762	Jaguar Cars
SAJDA42B363A45434		
SAJDA42B663A45413		
SAJDA42B663A45461		
SAJDA42C262A45827		
SAJDA42C362A45514		
SAJDA42C462A46364		
SAJDA42C662A45345		
SAJDA42C662A45751		

Warranty Information:

Warranty claims should be submitted quoting program code R847 together with the relevant option code from the table below or on the next page. This will result in payment of the appropriate parts and SROs.

The options that allow for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

As option codes are being used, there is no requirement to enter parts or SROs onto the claim.

Service Action R847

Refer to VIN list.

Program Code	Option	Description	SRO	Time	Part Number	Part Description	Qty
R847	A	Check alignment of accelerator pedal and re-torque pedal assembly fixings – no further action required	10.10.99	0.2			
R847	K	Check alignment of accelerator pedal and re-torque pedal assembly fixings – no further action required	10.10.99	0.2			
		Drive in/drive out	10.10.10	0.1			

Program Code	Option	Description	SRO	Time	Part Number	Part Description	Qty
R847	B	Check alignment and renew accelerator pedal assembly	19.20.01	0.2	Accelerator pedal assembly	JLM 21753	1
R847	C	Check alignment and renew accelerator pedal assembly	19.20.01	0.2	Accelerator pedal assembly	JLM 21753	1
		Drive in/drive out	10.10.10	0.1			

Note: Always review a Vehicle's Claim History within DDW first to determine whether this recall has been performed on this vehicle. The "Review Claim History" function will display a list of claims against the vehicle. If this recall appears in the program code field, do not perform this recall.



JAGUAR CARS

555 MACARTHUR BLVD

MAHWAH NJ 07430

July 2005

RE: R847- Accelerator Pedal Incorrectly Manufactured

Vehicles Affected: 2006 MY XK Vehicles VIN Range A45323-A46978

Dear Jaguar Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Jaguar Cars has decided that a defect relating to motor vehicle safety exists on a number of 2006 MY XK vehicles. If you are a recipient of this notice, and an owner of one of the vehicles within the Vehicle Identification Number (VIN) range listed below, this letter is to inform you that your vehicle is included in this recall.

➤ R847 Accelerator Pedal 2006 XK Vehicles A45323-A46978

Vehicles within this VIN range may be fitted with incorrectly formed accelerator pedal.

What is the concern?

A small number of accelerator pedals may have been incorrectly formed. This could result in reduced clearance between the accelerator pedal and the brake pedal and can increase the risk of both pedals being applied by the driver at the same time, which could result in a vehicle crash.

What will Jaguar and your Dealer do?

Jaguar Cars will inspect the accelerator pedal and if necessary replace the accelerator pedal assembly.

What should you do?

At your earliest convenience you should contact your authorized Jaguar Dealer who will be able to make an appointment to undertake the necessary actions. To assist your dealer please ensure that at the time of contact you have at hand your applicable Vehicle Identification Number.

How long will it take?

The time to complete the repair on your vehicle is approximately 30 minutes. However due to vehicle scheduling your dealer may need to keep your vehicle longer to complete the repair.

Moved or no longer own a Jaguar?

Please fill out the enclosed card and return it to Jaguar by simply putting it in the mail.

What you should do if you have already paid to have this work completed?

If you meet all the following requirements, you are eligible to receive reimbursement

1. You own or have owned a 2006 MY Jaguar XK within the VIN range listed above.
2. You have paid for an Accelerator Pedal due to the defect outlined previously in this letter.
3. The repair was performed before June 30th 2005.
4. You have an original or legible copy of the paid repair order or invoice showing:
 - A description of the concern reported
 - Itemized parts and labor charges
 - The vehicle model and year and the vehicle identification number
 - The repair date
 - Repair mileage
 - Name and address of the authorized Jaguar Dealer or licensed repair shop
 - Your name and address at the time of the repair

If you have all of the above information, present it to the Dealership Service Manager and they will arrange reimbursement of your claim.

Please ensure that you retain copies of all of the paperwork supporting this claim.

If an authorized Jaguar Dealer fails or is unable to satisfactorily answer your concerns about this notice, without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 888-327-4236.

Attention Leasing Agencies.

Please forward this Recall notice to the lessee within 10 days.

What should you do if you have further questions?

Please contact your Jaguar Dealer or the Jaguar Customer Relationship Center at 1 800 4JAGUAR (1-800-452-4827), option 9 or by e-mail at jaguarowner@jaguar.com. Should you have the need to contact Jaguar by mail, please address the correspondence to the Jaguar Customer Relationship Center using the above address.

Sincerely,



Benjamin I. Weiner
Customer Satisfaction Manager



XK

DATE 07/05

310-R847

SERVICE

TECHNICAL BULLETIN

Accelerator Pedal Alignment –
Check/Replace Accelerator Pedal Assembly –
Recall Action R847

MODEL 2006 MY
XK Range
VIN See VIN list

Issue:

A concern has been identified with the alignment of the accelerator pedal on a number of XK vehicles within the above VIN range.

The accelerator pedal arms, manufactured out of circular section steel, were incorrectly formed by the pedal supplier. Some of the parts from this batch of pedal arms were assembled into the accelerator pedal assemblies of Jaguar XK vehicles. This results in reduced clearance between the accelerator pedal and the brake pedal and can increase the risk of both pedals being applied by the driver at the same time.

Jaguar Cars has decided to recall the affected vehicles for an inspection to determine if the pedal assembly is from the affected batch. If needed, the pedal assembly will be replaced with a new one.

A number of vehicles have been reworked at the factory prior to dispatch and are not affected by this Recall Action. **To assist you in identifying the vehicles that need to be inspected, an affected vehicle listing is included. If the vehicle is not on the affected vehicle list, no rework action is required.** Please ensure that you check the vehicle is still outstanding prior to undertaking any rework action. DDW will be updated from the date of this Recall Action to reflect only the vehicles still outstanding the inspection and rework.

Action:

Check the accelerator pedal alignment of all 2006 MY XK vehicles listed in this bulletin. **All unsold vehicles or vehicles that have not been handed over to the customer must be inspected and, if necessary, repaired prior to sale or onward distribution.**

If the inspection reveals that the alignment of the accelerator pedal is within the acceptable limit, no further action is required. The workshop procedure for the inspection is included in this bulletin.

If the alignment of the accelerator pedal is outside of the acceptable limit, replace the accelerator pedal assembly. To replace the accelerator pedal assembly, refer to Global Technical Reference (GTR), Workshop Manual; section 310-02 Acceleration Control.

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

XK ACCELERATOR PEDAL ALIGNMENT

Check the alignment of the accelerator pedal (item 1 of Illustration 1) and the throttle stop (item 2 of Illustration 1).

ACCELERATOR PEDAL AND STOP




ILLUSTRATION 1

1. Depress the accelerator pedal to contact the throttle stop.

Note: The accelerator pedal should cover a minimum of half the throttle stop laterally (measuring across the center) leaving a maximum of 20 mm (A, Illustration 2) of exposed throttle stop.

ACCELERATOR PEDAL POSITION RELATED TO STOP




ILLUSTRATION 2

2. If the measurement is 20 mm or less, torque the accelerator pedal assembly fixings to 9 Nm (6.6 lb-ft); no further action is required.
3. If the measurement is greater than 20 mm (C, Illustration 3), remove the accelerator pedal assembly. Refer to Global Technical Reference (GTR), Workshop Manual, section 310-02.




ILLUSTRATION 3

4. Remove the throttle stop and locating stud from the removed accelerator pedal assembly and install it on the new accelerator pedal assembly, part number JLM 21753.
5. If the accelerator pedal pad is aluminum, remove the aluminum pedal pad from the removed pedal assembly and install it on the new pedal assembly.
6. Install the new accelerator pedal assembly, refer to Global Technical Reference (GTR), Workshop Manual, section 310-02.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Parts Information:

Please note that not every vehicle will require a throttle pedal. Please order accordingly.

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Accelerator pedal assembly	JLM 21753	1

VIN LIST OF AFFECTED VEHICLES

Canada

VIN	DLR NO.	DLR NAME
SAJFA42B163A45764		Jaguar Canada
SAJFA42B363A45796		Jaguar Canada
SAJFA42B363A46656		Jaguar Canada

Mexico

VIN	DLR NO.	DLR NAME
SAJPA42R163A45619	0200	Ford Motor Company, S. A. DE C. V.
SAJPA42R363A45623	0224	Jaguar Picacho
SAJPA42R363A46433	0200	Ford Motor Company, S. A. DE C. V.
SAJPA42R563A45607	0200	Ford Motor Company, S. A. DE C. V.
SAJPA42R663A45566	0224	Jaguar Picacho
SAJPA42R763A45625	0200	Ford Motor Company, S. A. DE C. V.
SAJPA42R963A46436	0200	Ford Motor Company, S. A. DE C. V.
SAJPA42RX63A46350	0200	Ford Motor Company, S. A. DE C. V.

USA

VIN	DLR NO.	DLR NAME
SAJDA42C462A45375	0349	Byers Imports
SAJDA41B663A45834	0580	Bauer Jaguar
SAJDA41C862A45798	0609	Jaguar of Great Neck/Roslyn
SAJDA42B063A45357	0609	Jaguar of Great Neck/Roslyn
SAJDA42B763A45646	0609	Jaguar of Great Neck/Roslyn
SAJDA42B563A45399	0660	Bill Rapp Jaguar
SAJDA41C662A45654	0696	Alpine Jaguar
SAJDA42C462A45943	0734	Thoroughbred Motorcars, Inc
SAJDA42C662A45832	5454	Checkered Flag Jaguar
SAJDA42C762A45869	5454	Checkered Flag Jaguar
SAJDA41B863A45768	5490	Jaguar Tysons Corner
SAJDA42C062A46135	5490	Jaguar Tysons Corner
SAJDA41C862A45624	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA41C962A45681	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA42C462A45473	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA42C662A45958	5581	Palm Beach Motor Cars Ltd., Inc.
SAJDA41B163A45367	5612	Jaguar Huntsville

USA continued

VIN	DLR NO.	DLR NAME
SAJDA42C162A45544	5612	Jaguar Huntsville
SAJDA42B463A46009	5618	Hennessy Jaguar
SAJDA42B763A45453	5618	Hennessy Jaguar
SAJDA42B763A45548	5618	Hennessy Jaguar
SAJDA42B963A46006	5618	Hennessy Jaguar
SAJDA42C762A45435	5618	Hennessy Jaguar
SAJDA42CX62A45378	5618	Hennessy Jaguar
SAJDA41B163A45966	5662	Leith Jaguar
SAJDA41C562A45693	5662	Leith Jaguar
SAJDA42B363A45465	5670	White Plains Jaguar
SAJDA42B563A45676	5670	White Plains Jaguar
SAJDA42C662A45538	5691	Jaguar of Sarasota
SAJDA42C162A45673	5703	Galpin Jaguar
SAJDA41B963A45780	5708	THE COLLECTION
SAJDA41C462A45684	5708	THE COLLECTION
SAJDA42C062A45910	5708	THE COLLECTION
SAJDA42C162A45964	5708	THE COLLECTION
SAJDA42C262A45908	5708	THE COLLECTION
SAJDA42C662A45961	5708	THE COLLECTION
SAJDA41BX63A45870	5709	Ray Catena Jaguar of Edison
SAJDA42B263A45330	5725	Manhattan Jaguar/NYC
SAJDA42C562A45336	5725	Manhattan Jaguar/NYC
SAJDA42B163A45545	5726	Parretti Jaguar Baton Rouge
SAJDA42B663A45959	5727	Crest Jaguar of Woodbridge
SAJDA41B263A45510	5735	Millennium Motor Cars
SAJDA41B763A45406	5736	Holman Motorcars
SAJDA42C362A45836	5741	Royal Jaguar of Tucson
SAJDA42B563A45354	5742	Heritage Jaguar of Freeport
SAJDA42B563A46102	5742	Heritage Jaguar of Freeport
SAJDA42B663A45380	5742	Heritage Jaguar of Freeport
SAJDA42C062A45499	5742	Heritage Jaguar of Freeport
SAJDA42C462A46039	5742	Heritage Jaguar of Freeport
SAJDA42C662A45426	5742	Heritage Jaguar of Freeport
SAJDA42CX62A45476	5742	Heritage Jaguar of Freeport
SAJDA42C262A45830	5744	Jaguar Huntington
SAJDA42C662A45829	5749	Ray Catena Jaguar of Monmouth
SAJDA41C562A45645	5759	Bobby Rahal Jaguar

USA continued

VIN	DLR NO.	DLR NAME
SAJDA42B363A45563	5759	Bobby Rahal Jaguar
SAJDA42C062A45700	5759	Bobby Rahal Jaguar
SAJDA42C462A45604	5759	Bobby Rahal Jaguar
SAJDA42C562A45353	5761	Dreher-Holloway Jaguar
SAJDA41B863A45334	5766	Nalley Jaguar
SAJDA41B863A45687	5766	Nalley Jaguar
SAJDA42C062A45583	5766	Nalley Jaguar
SAJDA42C362A45366	5766	Nalley Jaguar
SAJDA42C662A45541	5766	Nalley Jaguar
SAJDA41C262A45702	5768	Jaguar of Tampa
SAJDA42C762A45905	5768	Jaguar of Tampa
SAJDA41C362A45711	5777	Hennessey Jaguar of Gwinnett
SAJDA42B363A45479	5791	Jaguar Mt. Kisco
SAJDA42C162A45589	5797	Jaguar Annapolis
SAJDA42C162A45592	5797	Jaguar Annapolis
SAJDA41BX63A45495	9762	Jaguar Cars
SAJDA42B363A45434		
SAJDA42B663A45413		
SAJDA42B663A45461		
SAJDA42C262A45827		
SAJDA42C362A45514		
SAJDA42C462A46364		
SAJDA42C662A45345		
SAJDA42C662A45751		

Warranty Information:

Warranty claims should be submitted quoting program code R847 together with the relevant option code from the table below or on the next page. This will result in payment of the appropriate parts and SROs.

The options that allow for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

As option codes are being used, there is no requirement to enter parts or SROs onto the claim.

Service Action R847

Refer to VIN list.

Program Code	Option	Description	SRO	Time	Part Number	Part Description	Qty
R847	A	Check alignment of accelerator pedal and re-torque pedal assembly fixings – no further action required	10.10.99	0.2			
R847	K	Check alignment of accelerator pedal and re-torque pedal assembly fixings – no further action required	10.10.99	0.2			
		Drive in/drive out	10.10.10	0.1			

Program Code	Option	Description	SRO	Time	Part Number	Part Description	Qty
R847	B	Check alignment and renew accelerator pedal assembly	19.20.01	0.2	Accelerator pedal assembly	JLM 21753	1
R847	C	Check alignment and renew accelerator pedal assembly	19.20.01	0.2	Accelerator pedal assembly	JLM 21753	1
		Drive in/drive out	10.10.10	0.1			

Note: Always review a Vehicle's Claim History within DDW first to determine whether this recall has been performed on this vehicle. The "Review Claim History" function will display a list of claims against the vehicle. If this recall appears in the program code field, do not perform this recall.



JAGUAR CARS

555 MACARTHUR BLVD

MAHWAH NJ 07430

RE: R847- Accelerator Pedal Incorrectly Manufactured

Vehicles Affected: 2006 MY XK Vehicles VIN Range A45323-A46978

Dear Jaguar Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Jaguar Cars has decided that a defect relating to motor vehicle safety exists on a number of 2006 MY XK vehicles. If you are a recipient of this notice, and an owner of one of the vehicles within the Vehicle Identification Number (VIN) range listed below, this letter is to inform you that your vehicle is included in this recall.

➤ R847 Accelerator Pedal 2006 XK Vehicles A45323-A46978

Vehicles within this VIN range may be fitted with incorrectly formed accelerator pedal.

What is the concern?

A small number of accelerator pedals may have been incorrectly formed. This could result in reduced clearance between the accelerator pedal and the brake pedal and can increase the risk of both pedals being applied by the driver at the same time, which could result in a vehicle crash.

What will Jaguar and your Dealer do?

Jaguar Cars will inspect the accelerator pedal and if necessary replace the accelerator pedal assembly.

What should you do?

At your earliest convenience you should contact your authorized Jaguar Dealer who will be able to make an appointment to undertake the necessary actions. To assist your dealer please ensure that at the time of contact you have at hand your applicable Vehicle Identification Number.

How long will it take?

The time to complete the repair on your vehicle is approximately 30 minutes. However due to vehicle scheduling your dealer may need to keep your vehicle longer to complete the repair.

Moved or no longer own a Jaguar?

Please fill out the enclosed card and return it to Jaguar by simply putting it in the mail.

What you should do if you have already paid to have this work completed?

If you meet all the following requirements, you are eligible to receive reimbursement

1. You own or have owned a 2006 MY Jaguar XK within the VIN range listed above.
2. You have paid for an Accelerator Pedal due to the defect outlined previously in this letter.
3. The repair was performed before June 30th 2005.
4. You have an original or legible copy of the paid repair order or invoice showing:
 - A description of the concern reported
 - Itemized parts and labor charges
 - The vehicle model and year and the vehicle identification number
 - The repair date
 - Repair mileage
 - Name and address of the authorized Jaguar Dealer or licensed repair shop
 - Your name and address at the time of the repair

If you have all of the above information, present it to the Dealership Service Manager and they will arrange reimbursement of your claim.

Please ensure that you retain copies of all of the paperwork supporting this claim.

If an authorized Jaguar Dealer fails or is unable to satisfactorily answer your concerns about this notice, without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 888-327-4236.

Attention Leasing Agencies.

Please forward this Recall notice to the lessee within 10 days.

What should you do if you have further questions?

Please contact your Jaguar Dealer or the Jaguar Customer Relationship Center at 1 800 4JAGUAR (1-800-452-4827), option 9 or by e-mail at jaguarowner@jaguar.com. Should you have the need to contact Jaguar by mail, please address the correspondence to the Jaguar Customer Relationship Center using the above address.

Sincerely,



Benjamin I. Weiner
Customer Satisfaction Manager