



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

JUL 15 2005

DANIEL A. BENSMAN
FAULKNER, GARMHAUSEN, KEISTER & SHENK
COURTVIEW CENTER – SUITE 300
100 SOUTH MAIN AVENUE
SIDNEY OH 45365

NVS-215
05V-323

Subject: INSTRUMENT PANEL CLUSTER/FMVSS 101/105/WORKHORSE

Dear MR. BENSMAN:

This letter is to acknowledge the recent defect or noncompliance information report submitted on behalf of Airstream, Inc. Please review the following information to ensure that it conforms to your records as this is the information that will be made available to the public.

Makes/Models/Model Years:
AIRSTREAM/LAND YACHT/2003-2005
AIRSTREAM/SKY DECK/2003-2005

NHTSA Campaign Number: 05V-323

Recall Date: July13, 2005

Components:
ELECTRICAL SYSTEM

Potential Number of Units Affected: 213

Summary:
CERTAIN MOTOR HOMES BUILT ON WORKHORSE CHASSIS AND EQUIPPED WITH ACTIA CORPORATE INSTRUMENT CLUSTERS FAIL TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD (FMVSS) NOS. 101 "CONTROLS AND DISPLAYS" AND 105 "HYDRAULIC AND ELECTRIC BRAKE SYSTEMS." THE INCORRECT SOFTWARE PROGRAMMED INTO THE INSTRUMENT PANEL CLUSTER SUCH THAT CERTAIN DRIVER WARNINGS REQUIRED BY FMVSS 101 AND 105 ARE NOT DISPLAYED. AS A RESULT OF THIS INCORRECT SOFTWARE, THE INSTRUMENT PANEL CLUSTER MAY FAIL TO ILLUMINATE WARNING LAMPS INDICATING BRAKE SYSTEM FAILURE CODES.

Consequence:

DRIVERS WOULD NOT BE WARNED OF BRAKE SYSTEM FAILURES.

Remedy:

AIRSTREAM IS WORKING WITH WORKHORSE TO NOTIFY OWNERS AND HAVE THE REPAIR PERFORMED ON THEIR VEHICLES. OWNERS SHOULD CONTACT WORKHORSE AT 1-877-246-7731 OR AIRSTREAM AT 1-877-596-6505.


Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-327-4236; (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

As stated in your report, Workhorse will be handling the owner notification, remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.5 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Workhorse's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@nhtsa.dot.gov or delia.lopez@NHTSA.dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement