

05V-221
(2 pages)

RECEIVED
2005 MAY 13 P 1:54
OFFICE OF DEFECTS
AND COMPLAINTS

INITIAL DEFECT INFORMATION

(Use separate sheets if insufficient space)

DATE: 5/6/05

1. NAME AND ADDRESS OF COMPANY: DUCATI NORTH AMERICA INC.
10443 BANNLEY DRIVE
CUPERTINO CA 95014

2. CLASS(S) OF VEHICLES AFFECTED: ST4S AND ST4S ABS
AND ST3 MODELS

3. MAKE, MODEL(S) AND MODEL YEAR(S): DUCATI MOTORCYCLES
ST4S - ST4S ABS AND ST3 MODEL
MY 2004

4. VEHICLE IDENTIFICATION NUMBER(S): VIN # LIST PROVIDED
WITH NOTIFICATION LETTERS.

5. TOTAL QUANTITY OF VEHICLES INVOLVED: 662 UNITS
INCLUSIVE OF 40 CANADIAN MODELS.

6. DESCRIPTION OF DEFECT: AIR BOX BLEATHER HOSE
MAY BECOME IN CONTACT WITH THE
HORIZONTAL CYLINDER EXHAUST PIPE
CREATING A POTENTIAL FINE HAZARD

7. SAFETY REGULATION(S) STANDARD(S) AFFECTED: 573.6 - 577

8. MEASURES TAKEN TO CORRECT DEFECT: DEALER WILL SHORTEN
THE AIR BOX BLEATHER HOSE SECURING
IT AWAY FROM THE HORIZONTAL CYLINDER
EXHAUST PIPE

PREPARED BY: RENATO AIME TELEPHONE: 202 264 8307
TITLE: SERVICE - WARRANTY MANAGER

AFTER COMPLETION MAIL OR FACSIMILE TO THE ATTENTION OF:

MS. PATRICIA WALLACE - MS. DELIA LOPEZ

NATIONAL HIGHWAY
TRAFFIC SAFETY
ADMINISTRATION

FAX: 202 - 366 - 7882