

August 11, 2005

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
U.S. Department of Transportation  
400 Seventh Street SW  
Washington, DC 20590

05V-366  
(2 pages)

Dear Associate Administrator:

Pursuant to 49 CFR Part 573, Monaco Coach Corporation ("Monaco" or the "Company") is submitting this report to NHTSA concerning a safety recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.5(c)(2) Identification of Class A Motorhomes in Campaign

**Monaco Diplomat**

Model Year 2006 -65

**Monaco Camelot**

Model Year 2006 - 11

**Monaco Windsor**

Model Year 2006 -4

**Holiday Rambler Endeavor**

Model Year 2006 - 26

**Holiday Rambler Sceptor**

Model Year 2006 - 7

**Beaver Monterey**

Model Year 2006 - 1

The recall population was determined from the manufacturing records for the Company's manufacturing facilities in Wakarusa, Indiana, and Coburg, Oregon which produced the affected motorhomes. All floor plans are affected. The affected units were manufactured March 16, 2005, through July 13, 2005.

573.5(c)(3)

A total of one hundred and fourteen (114) Class A motorhomes are in the recall population. Specific Monaco Diplomat, Monaco Camelot, Monaco Windsor, Holiday Rambler Endeavor, Holiday Rambler Sceptor and Beaver Monterey Serial Number and VIN break points are as follows:

**2006 Monaco Diplomat** with serial number of 060119713883301-155176 thru 060119713883301-157114, a VIN of 1RF43464262036594 thru 1RF43454462037666

**2006 Monaco Camelot** with serial number of 060119183883400-154376 thru 060119184083401-156004, a VIN of 1RF43554462036135 thru 1RF43564062037068

**2006 Monaco Windsor** with serial number of 060120703883400-156244 thru 060120704083400-156729, a VIN of 1RF43554562037200 thru 1RF43564662037494

**2006 Holiday Rambler Endeavor** with serial number of 060119153883301-156382 thru 060119154083401-156533, a VIN of 1RF43454762037290 thru 1RF43464962037421

**2006 Holiday Rambler Sceptor** with serial number of 060119164083400-155672 thru 060119164083401-156005, a VIN of 1RF43564362036786 thru 1RF43564262037069

**2006 Beaver Monterey** with serial number of 061620824088401-801535 thru 061620824088401-801535, a VIN of 1RFC9564261036438 thru 1RFC9564261036438

573.5(c)(4)

Monaco has determined that all of the motorhomes in this recall population need to have the repair made.

573.5(c)(5)

Monaco became aware of this safety defect on August 8, 2005. During a technical meeting it was determined that the headlight switch in the front electrical box/firewall of the motorhome was overloading. Changes in the component supplier relay requirements with an updated controller were causing headlights to stop functioning without warning. This defect could potentially cause an accident while driving at night.

573.5(c)(6)

Monaco is currently not aware of any casualties or losses related to this issue.

573.5(c)(8)

The remedy will be the addition of a new harness.


All affected motorhomes in Monaco's inventory have been corrected.

Copies of the owner and dealer notification letters and the repair instructions are forthcoming for your pre-approval. The Company is prepared to begin Dealer and Owner notification in September 2005.

Please acknowledge receipt of this defect information report and provide the recall number that will be assigned by NHTSA to this campaign.

Thank you for your assistance.

Sincerely,



Walter Lewis  
Recall Administrator  
Monaco Coach Corporation