

RECEIVED
NVS-215

2005 OCT 25 A 11: 30

OFFICE OF
DEFECTS INVESTIGATION

ISUZU

DET-05-082

October 21, 2005

Mr. Ronald Medford
Senior Associate Administrator
National Highway Traffic Safety Administration
400 Seventh Street, SW
Washington D.C. 20590

Subject: MY 2002–2004 Isuzu Rodeo, Rodeo Sport, Axiom and Honda Passport –
Fuel Pump –
Part 573 Report –
Recall Number 05V-466

Dear Mr. Medford:

On behalf of Isuzu Motors Limited, Japan ("Isuzu Motors"), Isuzu Manufacturing Services of America, Inc. (collectively, "Isuzu") hereby submits this updated report pursuant to 49 CFR part 573. On October 6, 2005 Isuzu submitted DET-05-073 informing the agency of a safety recall of certain 2002, 2003 and 2004 model year SUVs. At that time the information required by part 573.6 (c)(3) was unavailable. This information is included here in the attachment.

If you have any questions or require additional information, please contact me at 734-582-9262 or Christine Ueno of my staff at 734-582-9260.

Sincerely,



Jeffery A. Marsee
Chief Representative
Emission and Safety
Isuzu Manufacturing Services of America, Inc.

Attachment

573.6 (c)(2) and (3):

Vehicles Potentially Affected by Make, Model and Model Year plus Inclusive Dates of Manufacture.

MAKE	MODEL SERIES	MODEL YEAR	NUMBER INVOLVED	INCLUSIVE MANUFACTURING DATES	
				FROM	TO
Isuzu	Rodeo	2002 – 2004 MY	11,654	July 2001	June 2004
	Rodeo Sport	2002 – 2003 MY	672	July 2001	April 2003
	Axiom	2002 – 2004 MY	2,344	November 2001	June 2004
Honda	Passport	2002 MY	845	July 2001	January 2002
TOTAL			15,515		