

05V-015




**Mack Trucks, Inc.**



# **Service ALERT**

**Date:** 04 May 2005 **Number:** SA-231-002  
**To:** All U.S. & Canadian Distributors  
**Attention:** Service Manager, Warranty Manager, Parts Manager  
**From:** Mack Reliability Engineering Department  
**Subject:** Re-Activation for SC-292 Safety Campaign

Mack Reliability Engineering is announcing the reactivation of Safety Campaign SC-292, effective May 4, 2005. Please provide your service technicians a new copy of the Safety Campaign dated May 4, 2005. The new copy contains updated parts information regarding the requirement to replace a fitting in the fuel supply pump when the fuel supply hose is replaced. The part number for the fuel supply hose (42QE3240P14) did not change. However, all fuel supply hoses installed after 5/4/05 **must** have a white dot on the hex nut of the fuel supply hose which connects to the fuel supply pump fitting and or have a manufacturing date of April 1, 2005 or later.

All dealer inventory of the 42QE3240P14 hoses **with and without the green dot must** be returned per the recall instructions that were sent out on April 18, 2005 and April 21, 2005 by the Mack Service Parts Organization. **Disregard the blue dot on the fitting of the fuel hose.**





Use only a 42QE3240P14 fuel supply hose with a **manufacturing date of 4/1/05** or later for this campaign. The manufacturing date is located on an orange tag attached to the hose. All of these hoses will be marked with a **small or large white dot** on the hex nut. See illustration above for date and dot locations.