

GM SERVICE AND PARTS OPERATIONS
DCS1368
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 21, 2005

Subject: Upcoming Safety Recall
05035 / Body Wiring Harness

Model: 2003-2005 GMT560 Medium Duty Truck Equipped
With Conventional Cab

To: All Chevrolet and GMC Dealers

Attention: Dealer Operator, General Manager, Sales
Manager, Used Car Manager, Service Manager,
Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) web site, the media may report that General Motors will be announcing a safety recall involving certain 2003-2005 model year GMT560 medium duty trucks equipped with conventional cabs.

On some of these vehicles, the body wiring harness had no protective conduit under the driver's feet to reduce the potential for harness wear. The body wiring harness that includes SDM wiring can be damaged from chafing and wear by the vehicle operators, which can result in an airbag deployment. The higher the frequency of an operator entering and exiting the vehicle, the higher the potential for harness wear.

To correct this condition, dealers will inspect the wiring harness for potential damage, repair or replace the harness if required and add conduit to all harnesses. These repairs will be made at no charge to the customer.

Approximately 26,000 vehicles are involved. GM is working with its suppliers to obtain the parts needed to correct this condition as quickly as possible. Dealers will be notified when a date for the mailing of customer notification letters is scheduled.

GMVIS information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS