

May Postings

Discussion Forum: BATTERY 2005 BIKES - Microsoft Internet Explorer provided by Big Dog Motorcycles

Address: http://www.bigdogmotorcyclesdealer.net/forums/display_topic_threads.asp?ForumID=37&TopicID=101&PagePosition=1

Topic: BATTERY 2005 BIKES

Message posted by **richard** on 26 May 2005 at 10:44am - IP Logged

richard
Standard Member
United States
22 May 2003
9 Posts

HAVE FOUND THAT BOLT HEADS ON BATTERY TRAY ARE CUTTING THOUGH PAD ON BACK OF BATTERY AND CUTTING INTO BATTERY HAVE TALK TO TEC AND THEY ARE WORKING FIX NEED TO CHECK

bigdogatlanta

Message posted by **jbeck** on 26 May 2005 at 11:07am - IP Logged

jbeck
Standard Member
United States
18 October 2004
13 Posts

Engineering have been made aware of the battery tray bolt heads protruding through the padding on the backside of the battery. Technical Support will monitor the progress and keep you informed.

John

Message posted by **JayCee** on 28 May 2005 at 8:37am - IP Logged

Discussion Forum: BATTERY 2005 BIKES - Microsoft Internet Explorer provided by Big Dog Motorcycles

Address: http://www.bigdogmotorcyclesdealer.net/forums/display_topic_threads.asp?ForumID=37&TopicID=101&PagePosition=1

15 October 2004
13 Posts

Message posted by **JayCee** on 28 May 2005 at 8:37am - IP Logged

JayCee
Standard Member
United States
02 October 2003
4 Posts

we have also had one instance of left rear corner of battery on 05 ridgeback hitting seat pan and wearing the corner of the battery causing it to start leaking battery acid. we had to lower the battery tray to create the needed clearance. ron has photos.

Message posted by **jbeck** on 28 May 2005 at 10:41am - IP Logged

jbeck
Standard Member
United States
13 October 2004
13 Posts

These pictures were forwarded to engineering. Currently data is being compiled and examined. Technical Support will keep you informed.

John

Post Reply

*Indicates required fields