


*** * TECHNICAL INFORMATION NOTICE * ***

DATE: June 27, 2005
TO: Mitsubishi Motors Sales Managers, Parts Managers and Service Managers
RE: 2006 Eclipse Brake Master Cylinder Replacement
ATIN NO. TIN-05-SR-005

PURPOSE

SR-05-003 instructs dealers to replace the master cylinder, using kit p/n 4625A027KT (A/T) or p/n 4625A028KT (M/T). Before removing the master cylinder from the customer's vehicle to perform the recall procedure, inspect the new replacement part provided in the kit. If the master cylinder replacement part has **two additional ports** (located on the bottom) that have black rubber plugs, **DO NOT USE THIS PART.** Immediately notify your facing PDC supervisor for assistance.

Inspect all of the master cylinder kits in your inventory.



OK TO
USE

DO NOT USE IF
THE PART HAS
THESE
ADDITIONAL
PORTS