



INTERNATIONAL TRUCK AND ENGINE CORPORATION  
4201 WINFIELD ROAD, WARRENVILLE, IL 60555

-----  
TRUCK GROUP

**RECALL REMINDER NOTICE G-05519**  
**November 2006**



***THIS IS AN ~~ISIS~~ ONLY NOTIFICATION.***

*Please refer to the dealer letter G-05519 for service instructions.*

**SUBJECT: SAFETY RECALL (U.S., EXPORT)**  
**Driver's Seat Belt Tethers on certain 5500i, 5600i,**  
**and 9200i Models built 8/23/2004 thru 9/13/2005**

When certain Sears Atlas seats are in their lowest, most rearward adjusted position they may chafe the seat belt tether that connects from the seat to the back of the cab. This chafing may eventually cut through the tether, thus weakening the effectiveness of the seat belt assembly in a vehicle crash, possibly resulting in **property damage, personal injury or death.**

This letter is to inform you that the *owners* of suspect vehicles who have not completed the Recall Service Procedure, have been sent a reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

**INTERNATIONAL TRUCK AND ENGINE CORPORATION**