

GM SERVICE AND PARTS OPERATIONS  
DCS1474

Date: October 19, 2005

Subject: Upcoming Noncompliance Recall  
05091 - Tire and Loading Information Label

Model: 2006 Chevrolet Malibu

To: All Chevrolet Dealers

Attention: Dealer Operator, General Manager, Sales Manager,  
Used Car Manager, Service Manager, Parts Manager  
and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) web site, the media may report that General Motors will be announcing a noncompliance recall involving certain 2006 model year Chevrolet Malibu vehicles.

Some of these vehicles fail to conform to Federal Motor Vehicle Safety Standard (MVSS) 110, Tire Selection and Rims - Passenger Cars. Vehicles built from September 1, 2005 to September 9, 2005 with the correct T125/70D16 spare tire have a Tire and Loading Information Label that incorrectly designates a T125/70D15 spare tire. A 15 inch diameter replacement spare tire can not be installed on the front axle due to a fit interference with the brake caliper.

To remedy this situation, GM will send corrected labels to affected customers for self-installation and to involved dealers for installation in vehicles currently in their inventory. Customers will also be provided the option of taking their vehicle to a dealer for installation of the label. Dealers will perform this repair at no charge to customers.

Approximately 2,300 vehicles are involved and GM is working with its supplier to obtain the replacement labels as quickly as possible.

GMVIS information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS