



JAGUAR CARS
555 MACARTHUR BLVD
MAHWAH NJ 07430

July 2005

RE: R847- Accelerator Pedal Incorrectly Manufactured

Vehicles Affected: 2006 MY XK Vehicles VIN Range A45323-A46978

Dear Jaguar Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Jaguar Cars has decided that a defect relating to motor vehicle safety exists on a number of 2006 MY XK vehicles. If you are a recipient of this notice, and an owner of one of the vehicles within the Vehicle Identification Number (VIN) range listed below, this letter is to inform you that your vehicle is included in this recall.

➤ R847 Accelerator Pedal 2006 XK Vehicles A45323-A46978

Vehicles within this VIN range may be fitted with incorrectly formed accelerator pedal.

What is the concern?

A small number of accelerator pedals may have been incorrectly formed. This could result in reduced clearance between the accelerator pedal and the brake pedal and can increase the risk of both pedals being applied by the driver at the same time, which could result in a vehicle crash.

What will Jaguar and your Dealer do?

Jaguar Cars will inspect the accelerator pedal and if necessary replace the accelerator pedal assembly.

What should you do?

At your earliest convenience you should contact your authorized Jaguar Dealer who will be able to make an appointment to undertake the necessary actions. To assist your dealer please ensure that at the time of contact you have at hand your applicable Vehicle Identification Number.

How long will it take?

The time to complete the repair on your vehicle is approximately 30 minutes. However due to vehicle scheduling your dealer may need to keep your vehicle longer to complete the repair.

Moved or no longer own a Jaguar?

Please fill out the enclosed card and return it to Jaguar by simply putting it in the mail.

What you should do if you have already paid to have this work completed?

If you meet all the following requirements, you are eligible to receive reimbursement

1. You own or have owned a 2006 MY Jaguar XK within the VIN range listed above.
2. You have paid for an Accelerator Pedal due to the defect outlined previously in this letter.
3. The repair was performed before June 30th 2005.
4. You have an original or legible copy of the paid repair order or invoice showing:
 - A description of the concern reported
 - Itemized parts and labor charges
 - The vehicle model and year and the vehicle identification number
 - The repair date
 - Repair mileage
 - Name and address of the authorized Jaguar Dealer or licensed repair shop
 - Your name and address at the time of the repair

If you have all of the above information, present it to the Dealership Service Manager and they will arrange reimbursement of your claim.

Please ensure that you retain copies of all of the paperwork supporting this claim.

If an authorized Jaguar Dealer fails or is unable to satisfactorily answer your concerns about this notice, without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 888-327-4236.

Attention Leasing Agencies.

Please forward this Recall notice to the lessee within 10 days.

What should you do if you have further questions?

Please contact your Jaguar Dealer or the Jaguar Customer Relationship Center at 1 800 4JAGUAR (1-800-452-4827), option 9 or by e-mail at jaguarowner@jaguar.com. Should you have the need to contact Jaguar by mail, please address the correspondence to the Jaguar Customer Relationship Center using the above address.

Sincerely,



Benjamin I. Weiner
Customer Satisfaction Manager