

8 August 2005

First Last
Address
City, ST ZIP

N.H.T.S.A. No. 05V – 276

Dear First;

IMPORTANT MOTORCYCLE SAFETY RECALL

Replacement of Coolant Hose & Addition of Securing Clip to Rear Brake Hose

Sprint ST 1050

Affected VIN Range: Start of Production to VIN 234545

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Triumph Motorcycles (America) Ltd has decided that a defect which relates to motor vehicle safety exists in certain +2005 Sprint ST motorcycles. The coolant bypass hose situated on the left hand side of the bike may leak coolant, resulting in your engine overheating and possible serious engine damage. We have further identified an improvement to guarantee the consistent routing of the rear brake hose to avoid the hose coming into contact with the rear drive chain.

Our records indicate you are the owner of a Sprint ST – **VIN (VIN)**

This machine is included within the above Safety Recall and we therefore urge you to contact your local Triumph dealer immediately to arrange for these updates. The repair is not likely to take more than 1 hour and will be free of charge.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problems associated with this Recall. Please provide the paid invoice to an authorized dealer, or directly to Triumph Customer Service at 385 Walt Sanders Memorial Drive, Suite 100, Newnan, GA 30265,

Failure to have this rectification work carried out may result in serious engine damage, or a loss of rear brake, causing loss of control of the motorcycle which could result in a crash.

Federal regulations requires that any vehicle lessor receiving the Recall Notice must forward a copy of this notice to lessee within 10 (ten) days of receipt.

Should you need to discuss any aspect of this Recall, then in the first instance please contact your dealer, who has been advised of this action and, who will be able to answer your concerns. If necessary, you can of course call our Customer Service representative at (678) 854 – 2010.

May we take this opportunity to apologize for any inconvenience this action may cause, but we are confident you can appreciate the importance of having a safe and reliable motorcycle. This action is being monitored by the N.H.T.S.A. As the owner of the above vehicle, you may submit a complaint to The Administrator, National Highway Traffic Safety Administration, 400 Seventh St. S.W., Washington, DC 40990; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://WWW.safercar.gov>, if after contacting your dealer you are still not satisfied that we have done our best to remedy this condition without charge and within reasonable time.

Shell Barr – Recall Coordinator

8 August 2005

N.H.T.S.A. No. 05V – 276

First Last
Address
City, ST Zip

Dear First;

IMPORTANT MOTORCYCLE SAFETY RECALL

Replacement of Coolant Hose

Affected VIN: Speed Triple	Start of Production to VIN 234916
Sprint ST 1050	VIN 234546 – 239096
Daytona 955i	VIN 227652 – 234933

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Triumph Motorcycles (America) Limited has decided that a defect which relates to motor vehicle safety exists in certain MY 2005 motorcycles. The coolant bypass hose situated on the left hand side of the bike may leak coolant, resulting in a possible ruptured coolant hose, which may cause the engine to overheat and possible serious engine damage.

Our records indicate you are the owner of a Triumph – **VIN (VIN)**

This machine is included within the above Safety Recall and we therefore urge you to contact your local Triumph dealer immediately to arrange for this update. The repair is not likely to take more than 1 hour and will be free of charge.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this Recall. Please provide the paid invoice to an authorized dealer, or directly to Triumph Customer Service at 385 Walt Sanders Memorial Drive, Suite 100, Newnan, GA 30265.

Failure to have this rectification work carried out may result in a loss of coolant from the engine which can cause the engine to overheat and seize, which may result in a crash.

Federal regulations requires that any vehicle lessor receiving the Recall Notice must forward a copy of this notice to the lessee within 10 (ten) days of receipt.

Should you need to discuss any aspect of this Recall, then in the first instance please contact your dealer, who has been advised of this action and, who will be able to answer your concerns. If necessary, you can of course contact our Customer Service representative at (678) 854 – 2010.

May we take this opportunity to apologize for any inconvenience this action may cause, but we are confident you can appreciate the importance of having a safe and reliable motorcycle. This action is being monitored by the N.H.T.S.A. As the owner of the above vehicle, you may submit a complaint to The Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, DC 40090; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>, if after contacting your dealer you are still not satisfied that we have done our best to remedy this condition without charge and within reasonable time.

Shell Barr – Recall Coordinator