



RECEIVED

2006 FEB -2 A 9:39

OFFICE OF TECHNICAL AFFAIRS
U.S. DEPARTMENT OF TRANSPORTATION
WASHINGTON, D.C.

Timothy A. Blubaugh
Director
Government Technical Affairs

Freightliner LLC
4747 N. Channel Avenue
Portland, OR 97217-7699
503.745.5219 Telephone
503.745.6800 Facsimile
TimothyBlubaugh@Freightliner.com

January 20, 2006

Ron Medford
Sr. Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590


Re: Defect Information Report (FL-467), NHTSA 05V-551

Mr. Medford:

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Freightliner LLC herewith submits supplemental defect information concerning the front axles on Business Class M2, Century, Columbia, Coronado; Sterling AT, LT, Acterra; FCC Motor Homes.

Please contact me if you have any questions.

Sincerely yours,



Timothy Blubaugh

Cc: Michael Mason, CAL-OSHA
DOSH, Legal Unit
10th Floor
455 Golden Gate Avenue
San Francisco, CA 94102

Certified Mail Article Number:

Section 573.6 Non-Compliance Information Report
FL-467, Front Axle I-Beam; NHTSA no. 05V-551
Supplement No.: 1

January 20, 2006

(c) (1) Manufacturer: FREIGHTLINER LLC
P.O. BOX 3849
Portland, Oregon 97208
(503) 745-5219

(c) (9) Estimated Owner Notification Date: Customer notification will be by first class mail using Freightliner records to determine the customers affected. Parts will be in place to complete owner notification by approximately February 3, 2006.