



Driven to Explore

Fleetwood Folding Trailers, Inc.
258 Beacon Street / P.O. Box 111
Somerset, PA 15501-3100
p: 814.445.9661 / f: 814.443.7320
www.worldsbesttrailers.com

IMPORTANT RECALL INFORMATION MAY, 2005

TO: All Fleetwood Folding Trailer Dealer Principals, Service Managers, and Parts Managers

**SUBJECT: RECALL CAMPAIGN #05V144
2005 Scorpion Reflex Reflector Recall**

Fleetwood Folding Trailers, Inc. is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the National Highway Traffic and Motor Vehicle Safety Act.

Fleetwood Folding Trailers, Inc. has decided that certain 2005 Scorpion folding trailers fail to conform to Federal Motor Vehicle Safety Standard #108, "Lamps, Reflective Devices, and Associated Equipment", and are notifying owners in order to correct the nonconformance. A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

The subject folding trailers were not equipped with red reflex reflectors on the rear and red reflex reflectors on the side as far to the rear as practicable, resulting in a nonconformance to FMVSS #108. At night, without these reflectors installed, when the folding trailer is approached directly from the rear or the side, the approaching driver will not receive reflected reflex light that indicates a large vehicle is ahead. This can result in a collision.

WHAT SHOULD YOU DO?

Owners of the above mentioned folding trailers have been asked to contact you for application of the recall remedy. The installation will need to be performed as outlined in the Recall Service Bulletin (PR:05-1). A copy of this bulletin is enclosed with this notice.

Should you perform this service, please complete a Fleetwood Folding Trailer Warranty Claim Form utilizing the flat rate and trouble codes listed in the Recall Service Bulletin (PR:05-1). Once repairs are completed, have the customer sign the work order and submit a warranty claim to Fleetwood Folding Trailers, Inc. for processing. You will be paid a fee in accordance with Recall Service Bulletin PR:05-1. Customers will not be charged for these repairs.

If you have any of these vehicles in your inventory, included with this notice will be a computer list of all the trailers involved that were sold to you. The appropriate number of repair kits will automatically be shipped to your dealership. Fleetwood is asking our dealers to repair stock units on their lots.


Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act of 1966) requires that:

If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles.

Please review this entire recall package with your Parts and Service Staff to familiarize them with the step by step procedure and implement the Voluntary Safety Recall Campaign.

If you have any questions, please contact our Customer Service Department at 800/841-3605. Thank you for helping Fleetwood Folding Trailers, Inc. with its continuing efforts to maintain customer satisfaction.

Sincerely,

A handwritten signature in black ink, appearing to read "Lynn Hickey", with a stylized flourish at the end.

Lynn Hickey
Technical Administrator
FLEETWOOD FOLDING TRAILERS, INC.

/kp

Enclosures: Recall Bulletin PR:05-1
Copy of Retail Notification
Computer List (if applicable)



Fleetwood Folding Trailers, Inc.
258 Beacon Street / P.O. Box 111
Somerset, PA 15501 3100
p: 814.445.9661 / f: 814.443.7320
www.worldsbesttrailers.com

PRODUCT RECALL SERVICE BULLETIN #PR:05-1

RECALL
BULLETIN:
PR:05-1

SUBJECT:

This service bulletin describes the procedure to replace the rear and side marker lights on certain 2005 Scorpion folding trailer with replacements that incorporate reflex reflectors.

YEAR(S)
AFFECTED:
2005

UNITS AFFECTED:

PRODUCT(S)
AFFECTED:
FOLDING
TRAILERS

2005 Scorpion folding trailers manufactured between December 12, 2004 through March 31, 2005.

IDENTIFICATION OF AFFECTED TRAILERS:

MODEL
AFFECTED:
SCORPION

	<u>Beginning</u>		<u>Ending</u>
2005 Scorpion V.I.N. range:	4CG648M2057273500	to	4CG648M2157273599
2005 Scorpion V.I.N. range:	4CG648M2257275300	to	4CG648M2057275375

ISSUE DATE:
April 2005

RECALL KIT (P/N 4713-0111) WHICH INCLUDES:

4	Mounting bracket #2592	4800-408
4	Reflex reflector light #M143R	4800-409
4	Mounting plate	4800-410
8	Rivet (long)	4734J186
8	Rivet (short)	4733G060

PROCEDURE:

1. Remove the four marker lights from the bumper by removing the inner cover plate and pulling the wire plug from the rear of each light. See photo 1 for the location of the marker lights to be removed.
2. Align the holes in the "aluminum" mounting bracket with the holes in the "black" mounting plate. Attach both parts using two rivets (P/N 4733G060). See photo 2.

NOTE: Make sure the raised flanges are facing upward.

3. Center the mounting plate assembly over the original hole in the bumper. Make sure the original mounting holes are covered by the assembly and mark the holes. See photo 3.

NOTE: Double check the hole locations before drilling to ensure they are not too close to the edge of the bumper.

4. Drill two 0.199 diameter holes and attach the mounting plate assembly to the bumper using two rivets (P/N 4734J186). See photo 4.
5. Install the reflex reflector marker light to the bracket by inserting the light into the raised flanges and turning clockwise. Turn until the light is tight in the mounting plate assembly.
6. Reattach the wire plug to the back of the new light.
7. Repeat steps 1 - 6 for the other lights indicated in photo 1.
8. Check the function of all the lights.
9. Reinstall both inner cover plates.

When filing a Flectwood Folding Trailer warranty claim, please use Trouble Code **PR05-1**. A Flat Rate of **.75 hour** will be allowed to perform this product recall. Any questions should be directed to the Technical Service Department at 800/841-3605.




PHOTO 1




PHOTO 2




PHOTO 3




PHOTO 4




PHOTO 5