



Fleetwood Enterprises, Inc.
3051 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92553-7638
p: 951.322.8216 / www.fleetwood.com

IMPORTANT RECALL INFORMATION

October 2005

TO: All Fleetwood Dealer Principals,
Service Managers,
Parts Managers

SUBJECT: RECALL CAMPAIGN #50825
2004 and 2005 Model Year Prowler, Wilderness, Terry Fifth Wheel Travel Trailers -
Propane Gas Pipe

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Rialto, California and Pendleton, Oregon is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the National Highway Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., has decided that a defect relating to motor vehicle safety exists in certain 2004 and 2005 model year Prowler, Wilderness and Terry Fifth Wheel Travel Trailers. These Fifth Wheel Travel Trailers were manufactured at the above-mentioned manufacturing plants from February 7, 2003 through March 29, 2005.

We are notifying the owners of the affected units in order to correct the problem. A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

On Fifth Wheel Travel Trailers affected by this recall, the propane gas lines that run through the floor of the slide out room penetrate the floor too far from the outside wall causing the potential for pinched lines during slide out room operation. This could lead to a propane gas leak and the potential for an explosion and/or fire. (Fleetwood notes that all affected Fifth Wheel Travel Trailers are equipped with a propane gas detector designed to sound an audible warning). To correct this defect, it is necessary to inspect and reroute the propane gas lines as described in the enclosed Recall Service Bulletin #50825.

WHAT SHOULD YOU DO?

Owners of the above mentioned Fifth Wheel Travel Trailers have been asked to contact a Fleetwood dealer to have the described defective condition remedied. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the enclosed Recall Service Bulletin #50825 prior to beginning the repairs. Should a customer have you perform this service, please complete the Fleetwood Repair Order (form X-SR-042).

WHAT SHOULD YOU DO? (continued)

Once repairs are completed, have the customer sign the Fleetwood Repair Order and return it to your National Warranty Processing Center in Decatur, Indiana for payment. You will be reimbursed in accordance with Service Bulletin #50825. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific Fifth Wheel Travel Trailer. Fleetwood is asking our dealers to make repairs to stock units on dealer lots prior to sale or lease.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act of 1966) requires that:

If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Safety Recall Campaign.

Thank you for helping Fleetwood with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your regional Fleetwood Service Center.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Steve Mitchell
Compliance Manager
Recreational Vehicle Group

Enclosures: Recall #50825 Customer Letter
Recall #50825 Service Bulletin



Fleetwood Enterprises, Inc.
3051 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p. 800.322.8216 / www.fleetwood.com

IMPORTANT RECALL INFORMATION #50825

October 2005

Dear Valued Fleetwood Fifth Wheel Travel Trailer Customer:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Rialto, California and Pendleton, Oregon has decided that a safety defect exists in certain 2004 and 2005 model year Prowler, Wilderness and Terry Fifth Wheel Travel Trailers

WHAT IS THE PROBLEM?

On Fifth Wheel Travel Trailers affected by this recall, the propane gas lines that run through the floor of the slide out room penetrate the floor to far from the outside wall causing the potential for pinched lines during slide out room operation. This could lead to a propane gas leak and the potential for an explosion and/or fire.

WHAT SHOULD YOU DO?

Due to safety related reasons and the potential for an explosion and/or fire, please make certain your Fifth Wheel Travel Trailer is immediately inspected and repaired by contacting the dealer who sold you the Fifth Wheel Travel Trailer and making an appointment to have this repair performed. If they are not available, another Fleetwood Fifth Wheel Travel Trailer dealer may do this work for you.

It is recommended that, until your Fifth Wheel Travel Trailer is inspected or repaired, you need to be extremely aware of an odor similar to garlic/rotten egg or a sustained hissing noise coming from the area of the exterior slide out room. If either occurs, shut off the propane gas at the main shut-off valves located on the propane gas tanks.

If you have had this concern corrected previously, you may be eligible for reimbursement of your cost for that repair. For more information contact Fleetwood Owner Relations at (800) 509-3418.

When you deliver your Fifth Wheel Travel Trailer for repairs, your dealer will complete a Fleetwood Repair Order. Upon completion of the repair, please sign the Fleetwood Repair Order.

If you no longer own this vehicle, please take a moment to provide the name and address of the new

owner on the enclosed *Vehicle Information Update Card* and return it to Fleetwood. This will enable us to send this important recall information to the new owner.

For leased vehicles - Any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you are unable to obtain the specified repair promptly and without charge, please contact:

Fleetwood Owner Relations
P.O. Box 59933
Riverside, California 92517
(800) 509-3418

If you believe that the dealer and Fleetwood Enterprises, Inc., have failed or have been unable to remedy the defect without charge or within a reasonable period of time, you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
400 Seventh Street SW
Washington, DC 20590

Or call the toll-free Vehicle Safety Hotline at 1-888-327-4236
(TTY: 1-800-424-9153)
or go to
<http://www.safercar.gov>

Fleetwood Enterprises, Inc., regrets any inconvenience this may cause you. We are taking these steps in the interest of your safety. We appreciate your prompt assistance in eliminating this potential hazard.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Steve Mitchell
Compliance Manager
Recreational Vehicle Group