



05V-244

WORLD LEADER SINCE 1946

March 20, 2007

ADVANCED MECHANICAL AIR CORP
710 N BROAD ST STE 20
MOORESVILLE, NC 28115-9553

Dear Sir or Madam:

REF: NHTSA Recall Follow-up Notification (# 05V-244)

This is a follow up to a notice that was sent to you on June 27, 2005. Hackney, a division of Specialized Vehicles Corporation, has decided that Hackney model AC/1000, AC/2000, DC/2000, DMB, ES/1000, ES/2000, P/2000, PL, SU, SVX, UBW, UBWR, UPL, and VU truck bodies and DMT, RTX, TX, and UTX trailers, model years 2004 and 2005, with lights installed between August 2004 and May 2005 fail to conform to Federal Motor Vehicle Safety Standard No. 108 Lamps, Reflective Devices, and Associated Equipment. Hackney's and State motor vehicle registration records indicate that you are the owner of one or more of these.

Description of noncompliance – FMVSS 108 requires license plate lamps to meet SAE Standard J587. One of the requirements of this standard is that the license plate lamp projects no white light to the rear. These vehicles had license plate lamps installed, which do not meet this requirement.

The consequence of this is that the license plate will not be properly illuminated.

What Hackney will do – Hackney will send you a replacement lamp for each vehicle that is coated on the sides so that will not project white light to the rear. The estimated time to install this lamp is five minutes.

What you should do – As soon as possible, inspect the license plate lamp on your vehicle. If it projects white light to the rear, replace it with the one Hackney sent you. Then fill out the enclosed card and return it to Hackney. Hackney will send you a check to reimburse you for reasonable labor costs incurred in installing the lamp.

If your license plate lamp does not project white light to the rear, indicate this on the enclosed card and return it to Hackney. You may keep the replacement lamp at no charge.

400 Hackney Avenue · PO Box 880 · Washington, NC 27889-0880
Phone 252-946-6521 · Fax 252-975-8340 · www.HackneyUSA.com

Washington, North Carolina · Independence, Kansas · Assembly Plants Worldwide

If you have already replaced the license plate lamp – Note on the return card that you furnished parts and include your receipt for parts when returning the card to Hackney. Then Hackney will reimburse you for the parts and reasonable labor costs.

If you are a vehicle lessor – Federal regulation requires that you forward a copy of this notice to the lessee within 10 days.

If you need help – If you have questions about this recall or have difficulty installing parts, please call the Hackney Parts & Warranty Supervisor at 800-763-0700.

Complaints - You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW., Washington, DC 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.if you believe that:


- (A) Hackney has failed or is unable to remedy the defect without charge.
- (B) Hackney has failed or is unable to remedy the defect without charge within 60 days unless the Administrator extends the period.

We are sorry for any inconvenience. We trust that you will give prompt attention to this matter in the interest of the safety of your vehicle.

Regards,



Gene Newman
Parts & Warranty Supervisor



PO Box 880 · 400 Hackney Ave. · Washington NC 27889

Advanced Mechanical Air Corp.
710 N. Broad St Ste 20
Mooresville, NC 28115-9553

SAFETY RECALL NOTICE

NHTSA Recall Number 05V-244

Truck Body or Trailer with VIN# **1GBJG31U151123184**

(Check only one):

_____ Replacement license plate lamp has been installed.

_____ License plate lamp does not project white light to rear.

Customer Name: **ADVANCED MECHANICAL AIR CORP**

Signed _____ Date _____



Mr. Gene Newman
Hackney
P. O. Box 880
Washington, NC 27889