



INTERNATIONAL TRUCK AND ENGINE CORPORATION
 4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

RECALL REMINDER FOR SAFETY RECALL 05519

November 2006

Dear International Truck Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International® has decided that a defect which relates to motor vehicle safety exists in certain **driver's seat belt tethers** of 5500*i*, 5600*i*, and 9200*i* models built between 8/23/2004 and 9/13/2005 with Sears Atlas 35, 70 and 80 seats.

This is a follow up notice to the initial notification of this recall, sent in October of 2005. Our records indicate the vehicle identified on the attached card has not yet had the recall service performed.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

REASON FOR THIS RECALL

When certain Sears Atlas seats are in their lowest, most rearward adjusted position they may chafe the seat belt tether that connects from the seat to the back of the cab.

RISK TO MOTOR VEHICLE SAFETY:

This chafing may eventually cut through the tether, thus weakening the effectiveness of the seat belt assembly in a vehicle crash, possibly resulting in **property damage, personal injury or death.**

In the event you no longer own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so that we can contact the current owner and you will not be contacted again regarding this recall.

Please contact your local International dealer to schedule an appointment and have the service procedure completed. Be prepared to read your vehicle identification number from your attached card when you call to schedule an appointment. The repair will be made without charge to you and will require approximately **1 hour** of repair time.

ALL VEHICLES IN THIS SAFETY RECALL MUST BE CORRECTED.

If the vehicle will not or cannot be corrected, please mark on the attached card the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.

If you paid to repair your vehicle for these defects prior to receiving the original notification letter, you may be eligible for reimbursement of the repair costs. Please see your International dealer for details.

WE URGE YOUR PROMPT ATTENTION TO THE CORRECTION OF THIS SAFETY DEFECT AND APOLOGIZE FOR ANY INCONVENIENCE THIS MAY CAUSE YOU.

INTERNATIONAL TRUCK AND ENGINE CORPORATION

RECALL REMINDER UPDATE

Model Name	Vehicle Identification Number (VIN)	TSR	Dealer Code	Campaign #

Please check only one (1) of the following:

- 1 Vehicle inspected – no corrections necessary.
- 2 Vehicle corrections completed.
- 3 I do not own this vehicle any more.
(Please complete the NEW OWNER INFORMATION block)
- 4 Service Not Desired. Reason: _____
- 5 Vehicle Scrapped (junked). Will not return to public streets.
- 6 Vehicle Stolen (whereabouts unknown).
- 7 Vehicle exported from U.S. to another country.
(Please complete the NEW OWNER INFORMATION block)



New Owner Information

Name

Street

City State Zip