

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

September 2009
FL462A
NHTSA #05V-453
REMINDER NOTICE

Subject: Western Star Fuel Line Routing

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. It is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Freightliner LLC, on behalf of its Freightliner Trucks Division, has decided that a defect which relates to motor vehicle safety exists on specific Western Star 4800, 4900, 5800, 5900, and 6900 vehicles manufactured between March 1995 and January 2005 with an optional in-cab battery box mounted under the passenger seat and dual suction and return fuel lines.

On some vehicles with optional in-cab batteries, the dual suction and return fuel lines were installed above the front cab mount crossmember and may contact the cab power harness under the cab deck. Abrasion of these lines may result in a fuel leak and possible vehicle fire.

The fuel lines will be inspected and rerouted as needed. Any fuel lines found to have wear or damage from chafing will be replaced.

This is a follow up to a previous communication. Our records indicate that your vehicle has not yet had this recall performed. Please make arrangement to have this repair done as soon as possible. If it has been completed, please disregard this letter.

Contact your authorized dealer to arrange to have your vehicle(s) modified. To locate a dealer, search online at www.Freightliner.com or contact the Warranty Campaigns Department for assistance.

When you contact your dealer, refer to campaign number **FL462A**. The modification will take between approximately half an hour and four hours, depending on the work needed, and will be performed at no charge to you.

IMPORTANT: When the recall has been completed, please ensure that a label has been affixed to your vehicle referencing **FL462A**.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you are not able to have the defect remedied without charge and within a reasonable time, which is not longer than 60 days after you tender the vehicle for repair, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com, or the Customer Assistance Center at (800) FTL-HELP or (800) STL-HELP, after normal business hours. You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. If your vehicle is involved in the Canadian portion, you may wish to notify Transport Canada, ASFAD, Place de Ville Tower C, 330 Sparks Street, Ottawa, ON K1A 0N5, or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure