



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

June 29, 2006

JOE LABONTE
COMPLIANCE AND SAFETY OFFICER
SETRA OF NORTH AMERICA
6012 B HIGH POINT ROAD
GREENSBORO NC 27407

NVS-215
06V-233

Subject: TURBOCHARGER FAILURE/POSSIBLE FIRE/SERIES 60/DDC

Dear MR. LABONTE:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
SETRA/S417/2003-2006

NHTSA Campaign Number: 06V-233

Mfg's Report Date: June 20, 2006

Components: ENGINE AND ENGINE COOLING: ENGINE: DIESEL

Potential Number of Units Affected: 335

Summary:

ON CERTAIN BUSES EQUIPPED WITH DETROIT DIESEL SERIES C-60 ENGINES, THE ELECTRONIC CONTROL MODULE (ECM) WILL REQUIRE TO BE REPROGRAMMED TO CURRENT MAINFRAME CALIBRATIONS.

Consequence:

REPROGRAMMING THE ECM WILL PREVENT THE POTENTIAL OF A TURBOCHARGER FAILURE FROM PROGRESSING TO AN ENGINE COMPARTMENT FIRE.

Remedy:

DETROIT DIESEL IS CONDUCTING THIS RECALL (PLEASE SEE 06E019000) AND WILL REPROGRAM THE ECM TO CURRENT MAINFRAME CALIBRATIONS FREE OF CHARGE. OWNERS MAY CONTACT DETROIT DIESEL AT 313-592-3708 OR SETRA AT 905-403-7807.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, Detroit Diesel will be handling the owner notification, remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.5 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Detroit Diesel's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@nhtsa.dot.gov or delia.lopez@NHTSA.dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement