



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

September 13, 2006

STEPHAN SPETH
DIRECTOR, VEHICLE COMPLIANCE
AND SAFETY AFFAIRS
DAIMLERCHRYSLER CORPORATION
800 CHRYSLER DRIVE
AUBURN HILLS MI 48326-2757

NVS-215
06V-341

Subject: POWERTRAIN CONTROL MODULE

Dear MR. SPETH:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

CHRYSLER/300/2007
CHRYSLER/CHARGER/2007
DODGE/DAKOTA/2007
DODGE/DURANGO/2007
DODGE/MAGNUM/2007
DODGE/NITRO 4X2/2007
DODGE/RAM/2007
JEEP/LIBERTY/2007

NHTSA Campaign Number: 06V-341

Mfg's Report Date: September 6, 2006

Components: POWER TRAIN: AUTOMATIC TRANSMISSION

Potential Number of Units Affected: 2,333

Summary:

ON CERTAIN PASSENGER AND SPORT UTILITY VEHICLES AND PICKUP TRUCKS EQUIPPED WITH AUTOMATIC TRANSMISSIONS, THE SOFTWARE PROGRAMMED INTO THE POWERTRAIN CONTROL MODULE CAN CAUSE A MOMENTARY LOCK UP OF THE DRIVE WHEELS IF THE VEHICLE IS TRAVELING OVER 40 MPH AND THE OPERATOR SHIFTS FROM DRIVE TO NEUTRAL AND BACK TO DRIVE.

Consequence:

IF THE DRIVE WHEELS LOCKED UP, LOSS OF VEHICLE CONTROL COULD OCCUR INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL REPROGRAM THE POWERTRAIN CONTROL MODULE FREE OF CHARGE. THE RECALL IS EXPECTED DURING SEPTEMBER 2006. OWNERS MAY CONTACT DAIMLERCHRYSLER AT 1-800-853-1403.

Notes:

DAIMLERCHRYSLER RECALL NO. F43. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during September 2006. Therefore, the first quarterly report will be due on or before October 30, 2006.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person

Chief, Recall Management Division