



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

November 14, 2006

MICHAEL ATKINSON
RECALL ADMINISTRATOR
MONACO COACH CORPORATION
1809 WEST HIVELY AVENUE; PLANT 6
ELKHART IN 46517

NVS-215
06V-429

Subject: MISSING HEAT SHIELD

Dear MR. ATKINSON:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BEAVER/CONTESSA/2007
HOLIDAY RAMBLER/SCEPTER/2007
MONACO/CAMELOT/2007

NHTSA Campaign Number: 06V-429

Mfg's Report Date: October 26, 2006

Components: EQUIPMENT:RECREATIONAL VEHICLE:LPG TANK ASSEMBLY

Potential Number of Units Affected: 206

Summary:

ON CERTAIN CLASS A MOTOR HOMES, HEAT SHIELDS WERE NOT INSTALLED IN THE LP TANK BAY.

Consequence:

THE HEAT FROM THE HYDROHOT EXHAUST COULD PLACE EXCESSIVE TEMPERATURE ON THE EXTERIOR OF THE LP TANK AND RESULT IN UNEXPECTED VENTING OF LP GAS THROUGH THE LP TANK SAFETY RELIEF VALVE. LP GAS LEAKAGE IN THE PRESENCE OF AN IGNITION SOURCE COULD RESULT IN A FIRE.

Remedy:

DEALERS WILL INSTALL A HEAT SHIELD BETWEEN THE HYDROHOT EXHAUST AND THE LP TANK AT NO COST TO YOU. THE RECALL IS EXPECTED TO BEGIN DURING NOVEMBER 2006. OWNERS MAY CONTACT MONACO AT 1-800-685-6545.

Notes:

MONACO RECALL NO. R06036. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

We have reviewed your proposed owner letter and a risk needs to be added to the fourth paragraph, i.e, "LP gas leakage in the presence of an ignition source could result in a fire."


Please provide the following additional information and be reminded of the following requirements:

Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during November 2006. Therefore, the first quarterly report will be due on or before January 30, 2007.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read 'GHP', with a long horizontal flourish extending to the right.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement