



Polaris Industries Inc.
Product Development Center
7290 Viking Blvd E
Wyoming, MN 55092
T: 651-408-7579
F: 651-408-7605

06 V-258
(18 pages)

July 12, 2006

National Highway Traffic Safety Administration
Patricia Wallace, Office of Defects Investigation
400 Seventh Street, S.W.
Washington, D.C. 20590
T: (202) 366-5232
F: (202) 366-7882

Dear Ms. Wallace:

573.6 Defect Information Report

573.6.c.1.

Vehicle manufacturer's full name:

Polaris Industries Inc., Victory Motorcycle Division

Address:

2100 Highway 55
Medina, MN 55340-9800

573.6.c.2.

Vehicles potentially containing defect:

All MY 2004 and 2005 Victory Kingpin motorcycles and sixty-five MY 2004 Victory Vegas motorcycles produced with floorboards as part of Victory's custom order program.

Vehicle Identification Numbers:

A list of affected VINs is attached.

Inclusive dates of manufacture:

May 12, 2005 to March 1, 2005.

Basis for recall population:

The population includes all of the machines built for MY 2004 and 2005 that use this type of shift lever shaft.

573.6.c.3.

Total number of vehicles potentially containing defect:

A total of 3,902 vehicles may contain this defect.

573.6.c.4.

Percentage of vehicles estimated to actually contain defect:

Victory estimates that 100% of the identified units may have this defect.

573.6.c.5.

Brief Summary:

Victory has determined that the welded joint on the shift lever shaft may fail causing the shift lever to become inoperable.

Detailed description:

The affected Victory motorcycles utilize a linkage system to connect the shift lever to the shift shaft of the transmission.

The joint on one of the components (shift lever shaft) is a welded joint and failures have been observed in this area.

The metal specified for this component contains some impurities which can result in a welded joint which is not reliable.

If this component separates at the welded joint, the transmission cannot be shifted and will remain in the gear that was selected prior to the joint breaking.

573.6.c.6.

Chronology:

Victory has received seven warranty claims for the affected MY 2004 machines and 68 warranty claims for the affected MY 2005 machines. No accident or a loss of control issues has been reported. If the failure occurs, the machine can be ridden until repairs can be made.

Due to the small, but constant failures that have occurred, Victory investigated the issue. An engineering evaluation revealed that the material selected for this application is not suitable and is the root cause of the failures.

573.6. c.8.

Remedy program:

Victory will conduct a safety recall by which we will require our dealer network to replace the shift lever shaft on all affected machines using a shift lever shaft made out of material that does not contain the impurities causing the current issue.

Estimated date on which notifications to Owners will begin:

July 28, 2006

Estimated date on which notification will be completed:

August 4, 2006

573.6.c.10.

Owner letter:

See attached Owner Notification letter.

573.6.c.11.

Manufacturer's campaign number:

V-06-04

Signed: _____

Don L. Good

Product Compliance Specialist

Polaris Industries Inc.

Date: _____

Attachments:

VINs: Pages 4 -- 12

Draft of Consumer Letter: Page 13

Draft of Dealer Bulletin: Page 14

SUBJECT: Recall Campaign - Weld Failure on Shift Lever Shaft

2006 Victory Vegas[®], Kingpin[™] and Kingpin Deluxe[™] models.

Warning and Safety Recall Notice 06V-xxx

July 21, 2006

Reference: Victory Safety Recall Bulletin V-06-04

PLEASE READ IMMEDIATELY

DRAFT

Dear Victory Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2006 Victory motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

A weld on the shift lever shaft on some 2004-2005 Victory models listed above may not meet Victory quality standards and may fail during operation. If the weld fails, the operator cannot shift gears, increasing the risk of a crash.

What Victory and your dealer will do:

To correct this possible defect, your authorized Victory dealer will install a new shift lever shaft. Repairs will be made by an authorized Victory motorcycle dealer at no cost to you. The repair will take approximately twenty minutes to perform, although your dealership may need your motorcycle for a longer period of time depending on the work schedule.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment. Do not attempt repairs yourself. Repairs must be done only by an authorized Victory motorcycle dealer.

DO NOT OPERATE YOUR MOTORCYCLE UNTIL ALL REPAIRS HAVE BEEN COMPLETED!

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you are having difficulty obtaining the recall repair outlined in this letter, please call our Consumer Service department at (763) 417-8650.

If you no longer own your motorcycle, please call our Consumer Service department at (763) 417-8650 or write to the address below with the name and address of the new owner.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration at 400 Seventh Street S.W., Washington, D.C. 20590 or call the toll-free safety hotline at 1-888-327-4236 (TTY: 1-888-424-9153).

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,



Christopher Wolf
Manager, Service Dealer Development & Warranty

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days. If you are no longer the owner of the Victory motorcycle indicated by this letter, please contact our Consumer Service department @ 763-417-8650

so we may update our records. Or write to us at:

Polaris Industries Inc.
Consumer Service Department
2100 Highway 55
Medina, MN 55340-9962

Ref: V0603



TECHNICAL SERVICE BULLETIN

THE NEW AMERICAN MOTORCYCLE

Date: 7/17/2006

Victory Motorcycle

Bulletin Number: V-06-04

Model Years: 2004 & 2005

☐ Safety Bulletin ☒ **Safety Recall** ☐ Service Bulletin ☐ Service Alert Fax ☐ Production Update Kit

Distribution: ☐ Owner / Principal ☐ Service Manager ☐ Sales Manager ☐ Parts Manager ☐ Technicians

This Service Bulletin is located at www.polarisdealers.com

- Confidential and Proprietary -



SUBJECT: Shift Lever Shaft Weld Failure


AFFECTED MODEL(S):

DRAFT

Model(s) Affected	Model Number(s)	Serial Number(s)
2004-2005 Vegas 2004-2005 Kingpin 2004-2005 Kingpin Deluxe	V04GB16; V05GB16 V04CB16; V05CB16 V04CD16; V05CD16 IN PROCESS	5VPG16#*6 P ??????? - ??????? 5VPC16#*6 P ??????? - ??????? 5VPCD16#D*6 P ??????? - ??????? IN PROCESS # = May be a C (Canada), D (U.S. 49 State), L (California), or U (United Kingdom) * = Check Digit. This could be either a letter or a number ALWAYS ENTER THE VIN NUMBER IN UNIT INQUIRY TO SEE IF A BULLETIN APPLIES.

PURPOSE:

The welded joint on the shift lever shaft may fail, causing the shift pedal to become inoperable. The inability of an operator to shift gears increases the risk of a crash.



WHAT YOUR DEALERSHIP SHOULD DO:

1. Contact owners of delivered units immediately and make arrangements to perform this warranty repair.
2. Replace the shift shaft lever shaft on all affected vehicles in your inventory following procedure outlined on page 3. DO NOT operate or sell an affected vehicle until this bulletin has been completed.
3. File a warranty claim for affected units immediately after completion of this bulletin. Follow warranty claim filing procedures on page 2.

NOTE: Always enter the VIN number in *Unit Inquiry* to determine if this bulletin applies.

CUSTOMER NOTIFICATION:

A customer Notification letter 06V-xxx (06-xxx in Canada) will be sent to registered owners of motorcycles affected by this bulletin. An example of the letter is shown on page 4. In addition to the notification letter sent by Victory, dealers are required to notify owners of motorcycles sold by their dealership, and to make arrangements to perform this bulletin repair immediately.

The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.



TECHNICAL SERVICE BULLETIN

THE NEW AMERICAN MOTORCYCLE

Date: 7/17/2006

Victory Motorcycle

Bulletin Number: V-06-04

Model Years: 2004 & 2005

☐ Safety Bulletin ☒ **Safety Recall** ☐ Service Bulletin ☐ Service Alert Fax ☐ Production Update Kit

Distribution: ☐ Owner / Principal ☐ Service Manager ☐ Sales Manager ☐ Parts Manager ☐ Technicians

This Service Bulletin is located at www.polarisdealers.com



-Confidential and Proprietary-

SUBJECT: Shift lever shaft weld failure


AFFECTED MODEL(S):

DRAFT

Model(s) Affected	Model Number(s)	Serial Number(s)
2004-2005 Vegas (F&O) 2004-2005 Kingpin (F & O) 2004-2005 Kingpin/Deluxe	V04G116, V04G216, V05G116, V04C116; V04C216, V05C116 V04CB16C, D, L, or U; V05CB16C, D, or L	5VPG16#*6 5VPC16#*6 IN PROCESS
2005 Ness Signature Series Kingpin	V05DC16C, D, or L	5VPCD16#*6 # = May be a C (Canada), D (U.S. 49 State), L (California), or U (United Kingdom) * = Check Digit. This could be either a letter or a number ALWAYS ENTER THE VIN NUMBER IN UNIT INQUIRY TO SEE IF A BULLETIN APPLIES.

PURPOSE:

The welded joint on the shift lever shaft may fail, causing the shift pedal to become inoperable. The inability of an operator to shift gears increases the risk of a crash.



WHAT YOUR DEALERSHIP SHOULD DO:

1. Contact owners of delivered units immediately and make arrangements to perform this warranty repair.
2. Replace the shift shaft lever shaft on all affected vehicles in your inventory following procedure outlined on page 3. DO NOT operate or sell an affected vehicle until this bulletin has been completed.
3. File a warranty claim for affected units immediately after completion of this bulletin. Follow warranty claim filing procedures on page 2.

NOTE: Always enter the VIN number in *Unit Inquiry* to determine if this bulletin applies.

CUSTOMER NOTIFICATION:

A customer Notification letter 06V-xxx (06-xxx in Canada) will be sent to registered owners of motorcycles affected by this bulletin. An example of the letter is shown on page 4. In addition to the notification letter sent by Victory, dealers are required to notify owners of motorcycles sold by their dealership, and to make arrangements to perform this bulletin repair immediately.

The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

PARTS INFORMATION:

PART NUMBER / DESCRIPTION	1014589 / Shift Lever Shaft
QUANTITY	1 per affected unit
DIRECT SHIP FROM VICTORY?	NO
TO BE ORDERED BY DEALERS?	YES
AVAILABILITY	Currently Available

WARRANTY CLAIM INFORMATION:

A single group claim may be submitted listing the complete (17 digit) Vehicle Identification Number for machines with the same model number. File claim type **SB (Service Bulletin)**. DO NOT PUT MORE THAN ONE MODEL NUMBER ON A CLAIM. The warranty claim system will automatically enter the parts listed below (Claim Part Numbers). If other parts are found to be necessary while performing this bulletin, contact Victory Technical Service for special authorization.

Service Bulletin #	V-06-04
Claim Type	SB
Labor Allowance	:18 minutes
Claim Part #	(Qty 1) 1014589 Shift Lever Shaft (Qty 1) 7170107 Warranty Decal

SERVICE BULLETIN COMPLETION DECAL:


1) Fill out a Service Bulletin Completion Decal, PN 7170107. 2) Clean the surface of the inside of the battery side cover. 3) Remove the decal from the sheet and apply as shown. 4) Peel the adhesive backing off of the *clear* protective outer film of the decal. 5) Press the clear film over the decal.

If you require more decals, order them through normal parts ordering channels.

Sincerely,





Christopher Wolf
Manager, Service Dealer Development and Warranty



The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

SPECIAL INSTRUCTIONS FOR SHIFT LEVER SHAFT REPLACEMENT:

1. Disconnect linkage rod by removing nut (A) and bolt (B).
2. Remove retaining ring (C).
3. Remove shift lever shaft.
4. Remove wave washer from existing shaft and install on new shaft.
5. Grease pedal bushings and shift pedal and re-assemble as shown. (See Fig. 2.)
6. Install pedal onto pivot and insert new shaft, aligning the flats of shaft with the bushings.
7. Install retaining ring. Be sure ring is fully seated in the groove of new shaft.
8. Install linkage bolt and nut. Torque nut to 10 Nm. (84 in. lbs.).



EXAMPLE OF CONSUMER LETTER 06V-xxx

Subject: Recall Campaign - Shift lever shaft weld failure

2004-2005 Victory Vegas[®], Kingpin[™], Kingpin Deluxe[™] & Ness Signature Series Kingpin models.

Warning and Safety Recall Notice 06V-xxx

Reference: Victory Safety Recall Bulletin V-06-04

PLEASE READ IMMEDIATELY

Dear Victory Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2006 Victory motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

A weld on the shift lever shaft on some 2004-2005 Victory models listed above may not meet Victory quality standards and may fail during operation. If the weld fails, the operator cannot shift gears, increasing the risk of a crash.

What Victory and your dealer will do:

To correct this possible defect, your authorized Victory dealer will install a new shift lever shaft. Repairs will be made by an authorized Victory motorcycle dealer at no cost to you. The repair will take approximately twenty minutes to perform, although your dealership may need your motorcycle for a longer period of time depending on the work schedule.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment. Do not attempt repairs yourself. Repairs must be done only by an authorized Victory motorcycle dealer.

DO NOT OPERATE YOUR MOTORCYCLE UNTIL ALL REPAIRS HAVE BEEN COMPLETED!

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you are having difficulty obtaining the recall repair outlined in this letter, please call our Consumer Service department at (763) 417-8650. If you no longer own your motorcycle, please call our Consumer Service department at (763) 417-8650 or write to the address below with the name and address of the new owner.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration at 400 Seventh Street S.W., Washington, D.C. 20590 or call the toll-free safety hotline at 1-888-327-4236 (TTY: 1-888-424-9153).

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,



Christopher Wolf
Manager, Service Dealer Development & Warranty

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days. If you are no longer the owner of the Victory motorcycle indicated by this letter, please contact our Consumer Service department @ 763-417-8650 so we may update our records. Or write to us at:

Polaris Industries Inc.
Consumer Service Department
2100 Highway 55
Medina, MN 55340-9962

Ref: V0604

The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

VIN	VIN	VIN	VIN
5VPCB16LX53009715	5VPCB16D953008063	5VPCB16D653007307	5VPCB16D353006423
5VPCB16LX53009570	5VPDC16D953008050	5VPCB16D653007291	5VPCB16D353006406
5VPCB16LX53009407	5VPDC16D953008047	5VPCB16D653007288	5VPCB16D353006390
5VPCB16LX53009357	5VPCB16D953008032	5VPCB16D653007260	5VPCB16D353006387
5VPCB16LX53009004	5VPCB16D953008029	5VPCB16D653007257	5VPCB16D353006373
5VPCB16LX53008953	5VPDC16D953008016	5VPCB16D653007243	5VPCB16D353006356
5VPCB16LX53008936	5VPCB16D953007771	5VPCB16D653007047	5VPCB16D353006244
5VPCB16LX53008886	5VPCB16D953007768	5VPCB16D653007016	5VPCB16D353006230
5VPCB16LX53008791	5VPCB16D953007754	5VPCB16D653007002	5VPCB16D353006227
5VPCB16LX53008774	5VPDC16D953007741	5VPCB16D653006996	5VPCB16D353006213
5VPCB16LX53008757	5VPDC16D953007738	5VPCB16D653006982	5VPCB16D353006194
5VPCB16LX53008502	5VPDC16D953007707	5VPCB16D653006979	5VPCB16D353006180
5VPCB16LX53008452	5VPDC16D953007609	5VPCB16D653006965	5VPCB16D353006177
5VPCB16LX53008435	5VPCB16D953007480	5VPCB16D653006951	5VPCB16D353006163
5VPCB16LX53008421	5VPCB16D953007477	5VPCB16D653006948	5VPCB16D353006146
5VPCB16LX53008418	5VPCB16D953007463	5VPDC16D653006935	5VPCB16D353006132
5VPDC16LX53007545	5VPCB16D953007446	5VPDC16D653006904	5VPCB16D353006129
5VPDC16LX53006766	5VPCB16D953007432	5VPCB16D653006805	5VPCB16D353006115
5VPDC16LX53006752	5VPCB16D953007429	5VPCB16D653006741	5VPCB16D353006101
5VPCB16LX53006653	5VPCB16D953007415	5VPCB16D653006738	5VPCB16D353006096
5VPCB16LX53006507	5VPCB16D953007396	5VPCB16D653006724	5VPCB16D353006082
5VPCB16LX53006488	5VPCB16D953007348	5VPDC16D653006711	5VPCB16D353006079
5VPCB16LX53006474	5VPCB16D953007284	5VPDC16D653006708	5VPCB16D353006065
5VPCB16LX53006362	5VPCB16D953007267	5VPCB16D653006691	5VPCB16D353006051
5VPCB16LX53006345	5VPCB16D953007253	5VPCB16D653006688	5VPCB16D353006048
5VPCB16LX53006331	5VPCB16D953007236	5VPCB16D653006674	5VPCB16D353005918
5VPCB16L953009706	5VPCB16D953007057	5VPCB16D653006643	5VPCB16D353005904
5VPCB16L953009463	5VPCB16D953007026	5VPDC16D653006501	5VPCB16D353005899
5VPCB16L953009401	5VPCB16D953007009	5VPDC16D653006496	5VPCB16D353005885
5VPCB16L953008930	5VPCB16D953006992	5VPCB16D653006495	5VPCB16D353005871
5VPCB16L953008894	5VPCB16D953006989	5VPCB16D653006464	5VPCB16D353005868
5VPCB16L953008877	5VPCB16D953006975	5VPCB16D653006450	5VPCB16D353005854
5VPCB16L953008796	5VPCB16D953006961	5VPCB16D653006447	5VPCB16D353005840
5VPCB16L953008782	5VPCB16D953006958	5VPCB16D653006416	5VPCB16D353005837
5VPCB16L953008779	5VPCB16D953006944	5VPCB16D653006402	5VPCB16D353005823
5VPCB16L953008443	5VPDC16D953006931	5VPCB16D653006397	5VPCB16D353005806
5VPCB16L953008426	5VPCB16D953006815	5VPCB16D653006383	5VPDC16D353005743
5VPCB16L953008412	5VPCB16D953006765	5VPCB16D653006240	5VPCB16D353005675
5VPDC16L953006791	5VPCB16D953006734	5VPCB16D653006237	5VPCB16D353005627
5VPDC16L953006774	5VPCB16D953006720	5VPCB16D653006223	5VPCD16D353004388
5VPCB16L953006482	5VPCB16D953006717	5VPCB16D653006206	5VPCB16D253009847
5VPCB16L953006479	5VPDC16D953006704	5VPCB16D653006190	5VPCD16D253009808
5VPCB16L953006434	5VPDC16D953006699	5VPCB16D653006187	5VPCB16D253009703
5VPCB16L953006370	5VPCB16D953006684	5VPCB16D653006173	5VPCB16D253009636
5VPCB16L953006367	5VPCB16D953006670	5VPCB16D653006156	5VPCB16D253009586
5VPCB16L953006353	5VPCB16D953006667	5VPCB16D653006142	5VPCB16D253009510
5VPCB16L953006336	5VPCB16D953006636	5VPCB16D653006139	5VPCB16D253009491
5VPCB16L853009714	5VPCB16D953006460	5VPCB16D653006125	5VPCB16D253009460
5VPCB16L853009468	5VPCB16D953006457	5VPCB16D653006111	5VPCB16D253009457

5VPCB16L853009356	5VPCB16D953006443	5VPCB16D653006108	5VPCB16D253009443
5VPCB16L853008952	5VPCB16D953006426	5VPCB16D653006092	5VPCB16D253009345
5VPCB16L853008949	5VPCB16D953006412	5VPCB16D653006089	5VPCB16D253009331
5VPCB16L853008935	5VPCB16D953006409	5VPCB16D653006075	5VPCB16D253009328
5VPCB16L853008885	5VPCB16D953006393	5VPCB16D653006061	5VPCB16D253009300
5VPCB16L853008790	5VPCB16D953006376	5VPCB16D653006058	5VPCB16D253009295
5VPCB16L853008773	5VPCB16D953006359	5VPCB16D653005945	5VPCB16D253009233
5VPCB16L853008501	5VPCB16D953006247	5VPCB16D653005914	5VPCB16D253009202
5VPCB16L853008479	5VPCB16D953006233	5VPCB16D653005900	5VPCB16D253009197
5VPCB16L853008434	5VPCB16D953006216	5VPCB16D653005895	5VPCB16D253009183
5VPCB16L853008417	5VPCB16D953006202	5VPCB16D653005881	5VPCB16D253009149
5VPDC16L853007544	5VPCB16D953006197	5VPCB16D653005878	5VPCB16D253009118
5VPDC16L853006751	5VPCB16D953006183	5VPCB16D653005864	5VPCB16D253009071
5VPCB16L853006683	5VPCB16D953006166	5VPCB16D653005850	5VPCB16D253009037
5VPCB16L853006652	5VPCB16D953006152	5VPCB16D653005847	5VPCB16D253008941
5VPCB16L853006506	5VPCB16D953006149	5VPCB16D653005833	5VPCB16D253008924
5VPCB16L853006487	5VPCB16D953006135	5VPCB16D653005816	5VPCB16D253008910
5VPCB16L853006344	5VPCB16D953006121	5VPDC16D653005770	5VPCB16D253008907
5VPCB16L853006330	5VPCB16D953006118	5VPDC16D653005753	5VPCB16D253008874
5VPCB16L753009445	5VPCB16D953006104	5VPDC16D653005736	5VPCB16D253008860
5VPCB16L753009400	5VPCB16D953006099	5VPCB16D653005671	5VPCB16D253008857
5VPCB16L753009249	5VPCB16D953006085	5VPCB16D653005668	5VPCB16D253008843
5VPCB16L753009042	5VPCB16D953006071	5VPCB16D653005623	5VPCB16D253008728
5VPCB16L753008893	5VPCB16D953006068	5VPCB16D553009856	5VPCB16D253008695
5VPCB16L753008876	5VPCB16D953006054	5VPDC16D553009818	5VPCB16D253008664
5VPCB16L753008795	5VPCB16D953005941	5VPCB16D553009632	5VPCB16D253008602
5VPCB16L753008781	5VPCB16D953005938	5VPCB16D553009596	5VPDC16D253008519
5VPCB16L753008778	5VPCB16D953005924	5VPCB16D553009582	5VPDC16D253008486
5VPCB16L753008473	5VPCB16D953005910	5VPCB16D553009579	5VPCB16D253008440
5VPCB16L753008442	5VPCB16D953005907	5VPCB16D553009548	5VPCB16D253008406
5VPCB16L753008439	5VPCB16D953005891	5VPCB16D553009520	5VPDC16D253008231
5VPCB16L753008425	5VPCB16D953005888	5VPCB16D553009498	5VPCB16D253008213
5VPDC16L753006790	5VPCB16D953005874	5VPCB16D553009453	5VPCB16D253008194
5VPDC16L753006773	5VPCB16D953005860	5VPCB16D553009436	5VPCB16D253008180
5VPCB16L753006481	5VPCB16D953005857	5VPCB16D553009324	5VPCB16D253008177
5VPCB16L753006478	5VPCB16D953005843	5VPCB16D553009243	5VPCB16D253008163
5VPCB16L753006433	5VPCB16D953005826	5VPCB16D553009226	5VPCB16D253008101
5VPCB16L753006366	5VPCB16D953005812	5VPCB16D553009209	5VPCB16D253008096
5VPCB16L753006352	5VPCB16D953005809	5VPCB16D553009193	5VPCB16D253008065
5VPCB16L753006349	5VPDC16D953005746	5VPCB16D553009159	5VPDC16D253008018
5VPCB16L753006335	5VPCB16D953005695	5VPCB16D553009114	5VPDC16D253007984
5VPCB16L653009467	5VPCB16D953005681	5VPCB16D553009033	5VPCB16D253007756
5VPCB16L653009405	5VPCB16D953005678	5VPCB16D553008951	5VPDC16D253007595
5VPCB16L653009355	5VPCB16D953004448	5VPCB16D553008920	5VPCB16D253007479
5VPCB16L653008948	5VPGB16D853009853	5VPCB16D553008917	5VPCB16D253007465
5VPCB16L653008934	5VPCB16D853009642	5VPCB16D553008903	5VPCB16D253007451
5VPCB16L653008898	5VPCB16D853009639	5VPCB16D553008870	5VPCB16D253007448
5VPCB16L653008884	5VPCB16D853009608	5VPCB16D553008867	5VPCB16D253007434
5VPCB16L653008500	5VPCB16D853009592	5VPCB16D553008853	5VPCB16D253007420
5VPCB16L653008464	5VPCB16D853009589	5VPDC16D553008823	5VPCB16D253007417

5VPCB16L653008433	5VPCB16D853009561	5VPDC16D553008806	5VPCB16D253007305
5VPCB16L653008416	5VPCB16D853009558	5VPDC16D553008787	5VPCB16D253007286
5VPDC16L653007543	5VPCB16D853009544	5VPCB16D553008755	5VPCB16D253007255
5VPCB16L653006682	5VPCB16D853009513	5VPCB16D553008724	5VPCB16D253007241
5VPCB16L653006679	5VPCB16D853009494	5VPDC16D553008546	5VPCB16D253007238
5VPCB16L653006651	5VPCB16D853009351	5VPCB16D553008450	5VPCB16D253007059
5VPCB16L653006505	5VPCB16D853009348	5VPCB16D553008447	5VPCB16D253007031
5VPCB16L653006486	5VPCB16D853009320	5VPCB16D553008402	5VPCB16D253007028
5VPCB16L653006343	5VPCB16D853009317	5VPCB16D553008397	5VPCB16D253007000
5VPCB16L553009542	5VPCB16D853009303	5VPDC16D553008384	5VPCB16D253006994
5VPCB16L553009461	5VPCB16D853009222	5VPCB16D553008383	5VPCB16D253006980
5VPCB16L553009041	5VPCB16D853009219	5VPDC16D553008370	5VPCB16D253006977
5VPCB16L553008956	5VPCB16D853009205	5VPDC16D553008367	5VPCB16D253006963
5VPCB16L553008939	5VPCB16D853009186	5VPDC16D553008241	5VPCB16D253006946
5VPCB16L553008892	5VPCB16D853009169	5VPCB16D553008206	5VPDC16D253006933
5VPCB16L553008889	5VPCB16D853009155	5VPCB16D553008190	5VPCB16D253006817
5VPCB16L553008875	5VPCB16D853009141	5VPCB16D553008187	5VPCB16D253006736
5VPCB16L553008794	5VPCB16D853009138	5VPCB16D553008142	5VPCB16D253006722
5VPCB16L553008777	5VPCB16D853009110	5VPCB16D553008139	5VPCB16D253006719
5VPCB16L553008455	5VPCB16D853009107	5VPCB16D553008111	5VPDC16D253006706
5VPCB16L553008441	5VPCB16D853009057	5VPCB16D553008108	5VPCB16D253006686
5VPCB16L553008438	5VPCB16D853008944	5VPCB16D553008092	5VPCB16D253006672
5VPDC16L553006772	5VPCB16D853008927	5VPCB16D553008089	5VPCB16D253006669
5VPDC16L553006769	5VPCB16D853008913	5VPCB16D553008075	5VPCB16D253006641
5VPDC16L553006755	5VPCB16D853008863	5VPDC16D553008045	5VPCB16D253006493
5VPCB16L553006480	5VPCB16D853008846	5VPCB16D553008030	5VPCB16D253006462
5VPCB16L553006477	5VPDC16D853008802	5VPCB16D553008027	5VPCB16D253006459
5VPCB16L553006432	5VPCB16D853008720	5VPDC16D553008014	5VPCB16D253006445
5VPCB16L553006365	5VPCB16D853008717	5VPCB16D553007766	5VPCB16D253006428
5VPCB16L553006351	5VPCB16D853008698	5VPDC16D553007719	5VPCB16D253006414
5VPCB16L553006348	5VPCB16D853008667	5VPDC16D553007607	5VPCB16D253006400
5VPCB16L553006334	5VPCB16D853008636	5VPDC16D553007591	5VPCB16D253006395
5VPCD16L553004447	5VPCB16D853008605	5VPCB16D553007492	5VPCB16D253006381
5VPCD16L553004383	5VPDC16D853008542	5VPCB16D553007489	5VPCB16D253006378
5VPCB16L453009712	5VPDC16D853008539	5VPCB16D553007461	5VPCB16D253006235
5VPCB16L453009709	5VPCB16D853008409	5VPCB16D553007458	5VPCB16D253006221
5VPCB16L453009404	5VPDC16D853008248	5VPCB16D553007444	5VPCB16D253006218
5VPCB16L453009399	5VPCB16D853008216	5VPCB16D553007430	5VPCB16D253006204
5VPCB16L453008947	5VPCB16D853008202	5VPCB16D553007427	5VPCB16D253006199
5VPCB16L453008933	5VPCB16D853008197	5VPCB16D553007413	5VPCB16D253006185
5VPCB16L453008897	5VPCB16D853008183	5VPCB16D553007394	5VPCB16D253006171
5VPCB16L453008883	5VPCB16D853008166	5VPCB16D553007282	5VPCB16D253006168
5VPCB16L453008446	5VPCB16D853008121	5VPCB16D553007279	5VPCB16D253006154
5VPCB16L453008429	5VPCB16D853008104	5VPCB16D553007265	5VPCB16D253006140
5VPCB16L453008415	5VPCB16D853008099	5VPCB16D553007251	5VPCB16D253006137
5VPDC16L453007542	5VPCB16D853008071	5VPCB16D553007248	5VPCB16D253006123
5VPDC16L453007539	5VPCB16D853008068	5VPCB16D553007234	5VPCB16D253006106
5VPDC16L453006794	5VPDC16D853008041	5VPCB16D553007055	5VPCB16D253006090
5VPCB16L453006681	5VPCB16D853008023	5VPCB16D553007024	5VPCB16D253006087
5VPCB16L453006678	5VPDC16D853008010	5VPCB16D553007010	5VPCB16D253006073

5VPCB16L453006650	5VPDC16D853008007	5VPCB16D553007007	5VPCB16D253006056
5VPCB16L453006485	5VPDC16D853007987	5VPCB16D553006990	5VPCB16D253005943
5VPCB16L453006437	5VPCB16D853007762	5VPCB16D553006987	5VPCB16D253005926
5VPCB16L453006342	5VPDC16D853007603	5VPCB16D553006973	5VPCB16D253005912
5VPCB16L453006339	5VPCB16D853007485	5VPCB16D553006956	5VPCB16D253005909
5VPCB16L353009717	5VPCB16D853007471	5VPCB16D553006942	5VPCB16D253005893
5VPCB16L353009569	5VPCB16D853007468	5VPCB16D553006813	5VPCB16D253005876
5VPCB16L353009409	5VPCB16D853007454	5VPCB16D553006763	5VPCB16D253005862
5VPCB16L353009359	5VPCB16D853007440	5VPCB16D553006746	5VPCB16D253005859
5VPCB16L353009247	5VPCB16D853007437	5VPCB16D553006732	5VPCB16D253005845
5VPCB16L353008955	5VPCB16D853007423	5VPCB16D553006729	5VPCB16D253005831
5VPCB16L353008938	5VPCB16D853007311	5VPDC16D553006716	5VPCB16D253005828
5VPCB16L353008891	5VPCB16D853007308	5VPDC16D553006702	5VPCB16D253005814
5VPCB16L353008888	5VPCB16D853007292	5VPDC16D553006697	5VPDC16D253005751
5VPCB16L353008793	5VPCB16D853007289	5VPCB16D553006696	5VPDC16D253005748
5VPCB16L353008759	5VPCB16D853007275	5VPCB16D553006665	5VPDC16D253005734
5VPCB16L353008499	5VPCB16D853007261	5VPCB16D553006472	5VPCB16D253005621
5VPCB16L353008454	5VPCB16D853007258	5VPCB16D553006469	5VPDC16D253004471
5VPCB16L353008437	5VPCB16D853007244	5VPCB16D553006455	5VPDC16D253004446
5VPCB16L353008423	5VPCB16D853007230	5VPCB16D553006441	5VPCB16D153009630
5VPDC16L353007547	5VPCB16D853007227	5VPCB16D553006438	5VPCB16D153009627
5VPDC16L353006771	5VPCB16D853007051	5VPCB16D553006424	5VPCB16D153009594
5VPDC16L353006768	5VPCB16D853007020	5VPCB16D553006410	5VPCB16D153009580
5VPDC16L353006754	5VPCB16D853007017	5VPCB16D553006407	5VPCB16D153009546
5VPCB16L353006476	5VPCB16D853007003	5VPCB16D553006391	5VPCB16D153009496
5VPCB16L353006431	5VPCB16D853006997	5VPCB16D553006388	5VPCB16D153009451
5VPCB16L353006364	5VPCB16D853006983	5VPCB16D553006374	5VPCB16D153009319
5VPCB16L353006350	5VPCB16D853006966	5VPCB16D553006360	5VPCB16D153009241
5VPCB16L353006347	5VPCB16D853006952	5VPCB16D553006357	5VPCB16D153009210
5VPCB16L353006333	5VPCB16D853006949	5VPCB16D553006245	5VPCB16D153009207
5VPCB16L253009711	5VPDC16D853006936	5VPCB16D553006231	5VPCB16D153009191
5VPCB16L253009708	5VPDC16D853006905	5VPCB16D553006228	5VPCB16D153009157
5VPCB16L253009465	5VPCB16D853006837	5VPCB16D553006214	5VPCB16D153009143
5VPCB16L253009403	5VPCB16D853006742	5VPCB16D553006200	5VPCB16D153009109
5VPCB16L253009353	5VPCB16D853006739	5VPCB16D553006195	5VPCB16D153009062
5VPCB16L253008946	5VPCB16D853006725	5VPCB16D553006181	5VPCB16D153009059
5VPCB16L253008932	5VPDC16D853006712	5VPCB16D553006178	5VPCB16D153009031
5VPCB16L253008929	5VPDC16D853006709	5VPCB16D553006164	5VPCB16D153009028
5VPCB16L253008896	5VPCB16D853006692	5VPCB16D553006150	5VPCB16D153008915
5VPCB16L253008882	5VPCB16D853006689	5VPCB16D553006147	5VPCB16D153008901
5VPCB16L253008476	5VPCB16D853006675	5VPCB16D553006133	5VPCB16D153008851
5VPCB16L253008445	5VPDC16D853006502	5VPCB16D553006116	5VPCB16D153008848
5VPCB16L253008431	5VPDC16D853006497	5VPCB16D553006102	5VPDC16D153008821
5VPCB16L253008414	5VPCB16D853006465	5VPCB16D553006097	5VPDC16D153008804
5VPDC16L253007541	5VPCB16D853006451	5VPCB16D553006083	5VPDC16D153008799
5VPDC16L253007538	5VPCB16D853006448	5VPCB16D553006066	5VPDC16D153008785
5VPDC16L253006793	5VPCB16D853006420	5VPCB16D553006052	5VPCB16D153008722
5VPCB16L253006680	5VPCB16D853006417	5VPCB16D553006049	5VPCB16D153008719
5VPCB16L253006484	5VPCB16D853006403	5VPCB16D553005919	5VPCB16D153008638
5VPCB16L253006436	5VPCB16D853006398	5VPCB16D553005905	5VPDC16D153008544

5VPCB16L253006372	5VPCB16D853006384	5VPCB16D553005886	5VPCB16D153008428
5VPCB16L253006369	5VPCB16D853006241	5VPCB16D553005872	5VPCB16D153008400
5VPCB16L253006355	5VPCB16D853006238	5VPCB16D553005869	5VPDC16D153008396
5VPCB16L253006341	5VPCB16D853006224	5VPCB16D553005855	5VPCB16D153008395
5VPCB16L253006338	5VPCB16D853006210	5VPCB16D553005841	5VPCB16D153008221
5VPCB16L153009568	5VPCB16D853006207	5VPCB16D553005838	5VPCB16D153008218
5VPCB16L153009408	5VPCB16D853006191	5VPCB16D553005824	5VPCB16D153008204
5VPCB16L153009246	5VPCB16D853006188	5VPCB16D553005810	5VPCB16D153008199
5VPCB16L153009005	5VPCB16D853006174	5VPCB16D553005807	5VPCB16D153008185
5VPCB16L153008954	5VPCB16D853006160	5VPDC16D553005744	5VPCB16D153008154
5VPCB16L153008937	5VPCB16D853006157	5VPCB16D553005676	5VPCB16D153008090
5VPCB16L153008890	5VPCB16D853006143	5VPCB16D553005628	5VPCB16D153008087
5VPCB16L153008887	5VPCB16D853006126	5VPCB16D553004382	5VPCB16D153008056
5VPCB16L153008792	5VPCB16D853006112	5VPCB16D453009851	5VPCB16D153008039
5VPCB16L153008789	5VPCB16D853006109	5VPCB16D453009699	5VPDC16D153007989
5VPCB16L153008775	5VPCB16D853006093	5VPCB16D453009606	5VPCB16D153007781
5VPCB16L153008761	5VPCB16D853006076	5VPCB16D453009590	5VPCB16D153007778
5VPCB16L153008758	5VPCB16D853006062	5VPCB16D453009587	5VPCB16D153007764
5VPCB16L153008503	5VPCB16D853006059	5VPCB16D453009556	5VPDC16D153007751
5VPCB16L153008470	5VPCB16D853005946	5VPCB16D453009508	5VPDC16D153007748
5VPCB16L153008467	5VPCB16D853005915	5VPCB16D453009492	5VPDC16D153007720
5VPCB16L153008453	5VPCB16D853005901	5VPCB16D453009489	5VPDC16D153007717
5VPCB16L153008422	5VPCB16D853005896	5VPCB16D453009444	5VPDC16D153007703
5VPCB16L153008419	5VPCB16D853005882	5VPCB16D453009332	5VPDC16D153007605
5VPDC16L153007546	5VPCB16D853005879	5VPCB16D453009329	5VPCB16D153007490
5VPDC16L153006770	5VPCB16D853005865	5VPCB16D453009315	5VPCB16D153007487
5VPDC16L153006767	5VPCB16D853005851	5VPCB16D453009301	5VPCB16D153007473
5VPDC16L153006753	5VPCB16D853005848	5VPCB16D453009296	5VPCB16D153007456
5VPCB16L153006654	5VPCB16D853005834	5VPCB16D453009234	5VPCB16D153007442
5VPCB16L153006508	5VPCB16D853005820	5VPCB16D453009217	5VPCB16D153007439
5VPCB16L153006475	5VPCB16D853005817	5VPCB16D453009203	5VPCB16D153007425
5VPCB16L153006363	5VPCB16D853005803	5VPCB16D453009198	5VPCB16D153007411
5VPCB16L153006346	5VPDC16D853005754	5VPCB16D453009170	5VPCB16D153007408
5VPCB16L153006332	5VPDC16D853005740	5VPCB16D453009167	5VPCB16D153007392
5VPCD16L153004381	5VPDC16D853005737	5VPCB16D453009153	5VPCB16D153007294
5VPCB16L053009464	5VPCB16D853005672	5VPCB16D453009105	5VPCB16D153007280
5VPCB16L053009447	5VPCB16D853005669	5VPCB16D453009069	5VPCB16D153007277
5VPCB16L053009397	5VPCB16D853005624	5VPCB16D453009038	5VPCB16D153007263
5VPCB16L053008945	5VPCB16D853004389	5VPCB16D453008942	5VPCB16D153007246
5VPCB16L053008931	5VPCD16D753009819	5VPCB16D453008925	5VPCB16D153007232
5VPCB16L053008895	5VPCB16D753009700	5VPCB16D453008911	5VPCB16D153007229
5VPCB16L053008878	5VPCB16D753009633	5VPCB16D453008908	5VPCB16D153007053
5VPCB16L053008797	5VPCB16D753009602	5VPCB16D453008861	5VPCB16D153007022
5VPCB16L053008783	5VPCB16D753009583	5VPCB16D453008858	5VPCB16D153007019
5VPCB16L053008461	5VPCB16D753009549	5VPCB16D453008844	5VPCB16D153007005
5VPCB16L053008458	5VPCB16D753009518	5VPDC16D453008800	5VPCB16D153006999
5VPCB16L053008430	5VPCB16D753009440	5VPCB16D453008729	5VPCB16D153006985
5VPCB16L053008427	5VPCB16D753009437	5VPCB16D453008696	5VPCB16D153006971
5VPCB16L053008413	5VPCB16D753009325	5VPCB16D453008665	5VPCB16D153006968
5VPDC16L053007540	5VPCB16D753009230	5VPCB16D453008634	5VPCB16D153006954

5VPDC16L053006792	5VPCB16D753009227	5VPCB16D453008603	5VPCB16D153006940
5VPDC16L053006775	5VPCB16D753009213	5VPDC16D453008540	5VPDC16D153006938
5VPCB16L053006483	5VPCB16D753009194	5VPDC16D453008487	5VPDC16D153006907
5VPCB16L053006435	5VPCB16D753009115	5VPCB16D453008424	5VPCB16D153006811
5VPCB16L053006371	5VPCB16D753009096	5VPCB16D453008410	5VPCB16D153006744
5VPCB16L053006368	5VPCB16D753009065	5VPCB16D453008407	5VPCB16D153006730
5VPCB16L053006354	5VPCB16D753009034	5VPCB16D453008391	5VPCB16D153006727
5VPCB16L053006340	5VPCB16D753008921	5VPCB16D453008388	5VPDC16D153006714
5VPCB16L053006337	5VPCB16D753008918	5VPDC16D453008263	5VPDC16D153006700
5VPCB16DX53009643	5VPCB16D753008904	5VPDC16D453008246	5VPCB16D153006694
5VPCB16DX53009626	5VPCB16D753008899	5VPDC16D453008229	5VPCB16D153006677
5VPCB16DX53009593	5VPCB16D753008871	5VPCB16D453008228	5VPCB16D153006663
5VPCB16DX53009545	5VPCB16D753008868	5VPCB16D453008214	5VPDC16D153006504
5VPCB16DX53009495	5VPCB16D753008854	5VPCB16D453008200	5VPDC16D153006499
5VPCB16DX53009349	5VPCB16D753008840	5VPCB16D453008195	5VPCB16D153006470
5VPCB16DX53009321	5VPDC16D753008824	5VPCB16D453008181	5VPCB16D153006467
5VPCB16DX53009304	5VPDC16D753008807	5VPCB16D453008178	5VPCB16D153006453
5VPCB16DX53009299	5VPDC16D753008788	5VPCB16D453008133	5VPCB16D153006422
5VPCB16DX53009223	5VPCB16D753008756	5VPCB16D453008102	5VPCB16D153006419
5VPCB16DX53009206	5VPCB16D753008725	5VPCB16D453008066	5VPCB16D153006405
5VPCB16DX53009190	5VPDC16D753008547	5VPDC16D453008053	5VPCB16D153006386
5VPCB16DX53009187	5VPDC16D753008516	5VPCB16D453008035	5VPCB16D153006243
5VPCB16DX53009142	5VPDC16D753008483	5VPDC16D453007971	5VPCB16D153006226
5VPCB16DX53009139	5VPCB16D753008451	5VPDC16D453007968	5VPCB16D153006212
5VPCB16DX53009111	5VPCB16D753008448	5VPCB16D453007774	5VPCB16D153006209
5VPCB16DX53009061	5VPCB16D753008420	5VPCB16D453007757	5VPCB16D153006193
5VPCB16DX53009058	5VPCB16D753008403	5VPDC16D453007744	5VPCB16D153006176
5VPCB16DX53009030	5VPCB16D753008398	5VPDC16D453007601	5VPCB16D153006162
5VPCB16DX53009027	5VPDC16D753008256	5VPCB16D453007483	5VPCB16D153006159
5VPCB16DX53008928	5VPDC16D753008239	5VPCB16D453007466	5VPCB16D153006145
5VPCB16DX53008914	5VPDC16D753008225	5VPCB16D453007452	5VPCB16D153006131
5VPCB16DX53008900	5VPCB16D753008224	5VPCB16D453007449	5VPCB16D153006128
5VPCB16DX53008847	5VPCB16D753008210	5VPCB16D453007435	5VPCB16D153006114
5VPDC16DX53008803	5VPCB16D753008207	5VPCB16D453007421	5VPCB16D153006100
5VPDC16DX53008798	5VPCB16D753008191	5VPCB16D453007418	5VPCB16D153006095
5VPDC16DX53008784	5VPCB16D753008188	5VPCB16D453007306	5VPCB16D153006081
5VPCB16DX53008721	5VPCB16D753008160	5VPCB16D453007290	5VPCB16D153006078
5VPCB16DX53008718	5VPCB16D753008157	5VPCB16D453007287	5VPCB16D153006064
5VPCB16DX53008699	5VPCB16D753008093	5VPCB16D453007242	5VPCB16D153006050
5VPCB16DX53008637	5VPCB16D753008062	5VPCB16D453007239	5VPCB16D153005917
5VPCB16DX53008606	5VPCB16D753008059	5VPCB16D453007029	5VPCB16D153005903
5VPDC16DX53008543	5VPDC16D753008015	5VPCB16D453007001	5VPCB16D153005898
5VPCB16DX53008444	5VPCB16D753007767	5VPCB16D453006995	5VPCB16D153005884
5VPCB16DX53008394	5VPCB16D753007753	5VPCB16D453006981	5VPCB16D153005870
5VPDC16DX53008364	5VPDC16D753007706	5VPCB16D453006978	5VPCB16D153005867
5VPDC16DX53008252	5VPDC16D753007611	5VPCB16D453006964	5VPCB16D153005853
5VPDC16DX53008235	5VPDC16D753007592	5VPCB16D453006950	5VPCB16D153005836
5VPCB16DX53008220	5VPCB16D753007493	5VPCB16D453006947	5VPCB16D153005822
5VPCB16DX53008217	5VPCB16D753007476	5VPDC16D453006934	5VPCB16D153005819
5VPCB16DX53008203	5VPCB16D753007462	5VPCB16D453006835	5VPCB16D153005805

5VPCB16DX53008198	5VPCB16D753007459	5VPCB16D453006740	5VPDC16D153005756
5VPCB16DX53008184	5VPCB16D753007445	5VPCB16D453006737	5VPDC16D153005742
5VPCB16DX53008136	5VPCB16D753007431	5VPCB16D453006723	5VPDC16D153005739
5VPCB16DX53008105	5VPCB16D753007428	5VPDC16D453006710	5VPCB16D153005674
5VPCB16DX53008086	5VPCB16D753007414	5VPDC16D453006707	5VPDC16D153005658
5VPCB16DX53008072	5VPCB16D753007395	5VPCB16D453006690	5VPCB16D153005626
5VPCB16DX53008069	5VPCB16D753007350	5VPCB16D453006687	5VPCB16D053009859
5VPDC16DX53008042	5VPCB16D753007347	5VPCB16D453006673	5VPCB16D053009702
5VPCB16DX53008038	5VPCB16D753007283	5VPDC16D453006500	5VPCB16D053009635
5VPCB16DX53008024	5VPCB16D753007266	5VPCB16D453006494	5VPCB16D053009604
5VPDC16DX53008011	5VPCB16D753007252	5VPCB16D453006463	5VPCB16D053009599
5VPDC16DX53008008	5VPCB16D753007249	5VPCB16D453006446	5VPCB16D053009585
5VPCB16DX53007990	5VPCB16D753007235	5VPCB16D453006429	5VPCB16D053009540
5VPDC16DX53007974	5VPCB16D753007025	5VPCB16D453006415	5VPCB16D053009506
5VPCB16DX53007780	5VPCB16D753007008	5VPCB16D453006401	5VPCB16D053009490
5VPCB16DX53007777	5VPCB16D753006991	5VPCB16D453006396	5VPCB16D053009456
5VPCB16DX53007763	5VPCB16D753006988	5VPCB16D453006382	5VPCB16D053009439
5VPDC16DX53007750	5VPCB16D753006974	5VPCB16D453006379	5VPCB16D053009327
5VPDC16DX53007747	5VPCB16D753006960	5VPCB16D453006236	5VPCB16D053009294
5VPDC16DX53007716	5VPCB16D753006957	5VPCB16D453006222	5VPCB16D053009229
5VPCB16DX53007486	5VPCB16D753006943	5VPCB16D453006219	5VPCB16D053009215
5VPCB16DX53007472	5VPDC16D753006930	5VPCB16D453006205	5VPCB16D053009201
5VPCB16DX53007469	5VPCB16D753006764	5VPCB16D453006186	5VPCB16D053009196
5VPCB16DX53007455	5VPCB16D753006733	5VPCB16D453006172	5VPCB16D053009182
5VPCB16DX53007441	5VPDC16D753006703	5VPCB16D453006169	5VPCB16D053009151
5VPCB16DX53007438	5VPDC16D753006698	5VPCB16D453006155	5VPCB16D053009103
5VPCB16DX53007424	5VPCB16D753006666	5VPCB16D453006141	5VPCB16D053009098
5VPCB16DX53007410	5VPDC16D753006491	5VPCB16D453006138	5VPCB16D053009070
5VPCB16DX53007407	5VPCB16D753006490	5VPCB16D453006124	5VPCB16D053009067
5VPCB16DX53007312	5VPCB16D753006473	5VPCB16D453006110	5VPCB16D053009036
5VPCB16DX53007309	5VPCB16D753006456	5VPCB16D453006107	5VPCB16D053008940
5VPCB16DX53007293	5VPCB16D753006442	5VPCB16D453006091	5VPCB16D053008923
5VPCB16DX53007276	5VPCB16D753006439	5VPCB16D453006088	5VPCB16D053008906
5VPCB16DX53007262	5VPCB16D753006425	5VPCB16D453006074	5VPCB16D053008873
5VPCB16DX53007259	5VPCB16D753006411	5VPCB16D453006060	5VPCB16D053008856
5VPCB16DX53007245	5VPCB16D753006408	5VPCB16D453006057	5VPCB16D053008727
5VPCB16DX53007231	5VPCB16D753006392	5VPCB16D453005944	5VPCB16D053008694
5VPCB16DX53007228	5VPCB16D753006389	5VPCB16D453005927	5VPCB16D053008663
5VPCB16DX53007049	5VPCB16D753006375	5VPCB16D453005913	5VPDC16D053008518
5VPCB16DX53007021	5VPCB16D753006361	5VPCB16D453005894	5VPDC16D053008485
5VPCB16DX53007018	5VPCB16D753006358	5VPCB16D453005880	5VPCB16D053008436
5VPCB16DX53007004	5VPCB16D753006246	5VPCB16D453005877	5VPCB16D053008405
5VPCB16DX53006998	5VPCB16D753006232	5VPCB16D453005863	5VPDC16D053008390
5VPCB16DX53006984	5VPCB16D753006229	5VPCB16D453005846	5VPDC16D053008387
5VPCB16DX53006970	5VPCB16D753006215	5VPCB16D453005832	5VPCB16D053008386
5VPCB16DX53006967	5VPCB16D753006201	5VPCB16D453005829	5VPDC16D053008373
5VPCB16DX53006953	5VPCB16D753006196	5VPCB16D453005815	5VPDC16D053008261
5VPDC16DX53006937	5VPCB16D753006182	5VPDC16D453005752	5VPDC16D053008258
5VPDC16DX53006906	5VPCB16D753006179	5VPDC16D453005749	5VPDC16D053008244
5VPCB16DX53006807	5VPCB16D753006165	5VPDC16D453005735	5VPDC16D053008227

5VPCB16DX53006743	5VPCB16D753006151	5VPCB16D453005670	5VPCB16D053008226
5VPCB16DX53006726	5VPCB16D753006148	5VPCD16D453005629	5VPCB16D053008212
5VPDC16DX53006713	5VPCB16D753006134	5VPCB16D453005622	5VPCB16D053008209
5VPCB16DX53006693	5VPCB16D753006120	5VPCB16D453005619	5VPCB16D053008193
5VPCB16DX53006676	5VPCB16D753006117	5VPDC16D453004472	5VPCB16D053008145
5VPCB16DX53006662	5VPCB16D753006103	5VPCB16D453004387	5VPCB16D053008114
5VPDC16DX53006503	5VPCB16D753006098	5VPCD16D353009817	5VPCB16D053008095
5VPDC16DX53006498	5VPCB16D753006084	5VPCB16D353009645	5VPCB16D053008081
5VPCB16DX53006466	5VPCB16D753006070	5VPCB16D353009631	5VPCB16D053008078
5VPCB16DX53006452	5VPCB16D753006067	5VPCB16D353009628	5VPDC16D053008051
5VPCB16DX53006449	5VPCB16D753006053	5VPCB16D353009600	5VPDC16D053008048
5VPCB16DX53006421	5VPCB16D753005940	5VPCB16D353009595	5VPCB16D053008033
5VPCB16DX53006418	5VPCB16D753005923	5VPCB16D353009581	5VPDC16D053008017
5VPCB16DX53006404	5VPCB16D753005906	5VPCB16D353009550	5VPDC16D053007983
5VPCB16DX53006399	5VPCB16D753005890	5VPCB16D353009497	5VPDC16D053007966
5VPCB16DX53006385	5VPCB16D753005887	5VPCB16D353009452	5VPCB16D053007772
5VPCB16DX53006242	5VPCB16D753005873	5VPCB16D353009435	5VPCB16D053007769
5VPCB16DX53006239	5VPCB16D753005856	5VPCB16D353009323	5VPDC16D053007742
5VPCB16DX53006225	5VPCB16D753005842	5VPCB16D353009242	5VPDC16D053007739
5VPCB16DX53006211	5VPCB16D753005839	5VPCB16D353009225	5VPCB16D053007481
5VPCB16DX53006208	5VPCB16D753005825	5VPCB16D353009211	5VPCB16D053007478
5VPCB16DX53006192	5VPCB16D753005811	5VPCB16D353009189	5VPCB16D053007464
5VPCB16DX53006189	5VPCB16D753005808	5VPCB16D353009161	5VPCB16D053007450
5VPCB16DX53006175	5VPDC16D753005745	5VPCB16D353009158	5VPCB16D053007447
5VPCB16DX53006161	5VPCB16D753005680	5VPCB16D353009113	5VPCB16D053007433
5VPCB16DX53006158	5VPCB16D753005677	5VPCB16D353009063	5VPCB16D053007416
5VPCB16DX53006144	5VPCD16D653009858	5VPCB16D353009032	5VPCB16D053007397
5VPCB16DX53006130	5VPCB16D653009705	5VPCB16D353009029	5VPCB16D053007349
5VPCB16DX53006127	5VPCB16D653009641	5VPCB16D353008950	5VPCB16D053007285
5VPCB16DX53006113	5VPCB16D653009638	5VPCB16D353008916	5VPCB16D053007254
5VPCB16DX53006094	5VPCB16D653009624	5VPCB16D353008902	5VPCB16D053007240
5VPCB16DX53006080	5VPCB16D653009610	5VPCB16D353008852	5VPCB16D053007237
5VPCB16DX53006077	5VPCB16D653009607	5VPDC16D353008822	5VPCB16D053007030
5VPCB16DX53006063	5VPCB16D653009591	5VPDC16D353008805	5VPCB16D053007027
5VPCB16DX53005947	5VPCB16D653009588	5VPDC16D353008786	5VPCB16D053006993
5VPCB16DX53005916	5VPCB16D653009557	5VPCB16D353008723	5VPCB16D053006976
5VPCB16DX53005902	5VPCB16D653009512	5VPDC16D353008545	5VPCB16D053006962
5VPCB16DX53005897	5VPCB16D653009509	5VPCB16D353008432	5VPCB16D053006959
5VPCB16DX53005883	5VPCB16D653009493	5VPCB16D353008401	5VPCB16D053006945
5VPCB16DX53005866	5VPCB16D653009459	5VPCB16D353008382	5VPDC16D053006932
5VPCB16DX53005852	5VPCB16D653009347	5VPDC16D353008254	5VPCB16D053006833
5VPCB16DX53005849	5VPCB16D653009333	5VPDC16D353008237	5VPCB16D053006735
5VPCB16DX53005835	5VPCB16D653009316	5VPDC16D353008223	5VPCB16D053006721
5VPCB16DX53005821	5VPCB16D653009297	5VPCB16D353008222	5VPCB16D053006718
5VPCB16DX53005818	5VPCB16D653009221	5VPCB16D353008219	5VPDC16D053006705
5VPCB16DX53005804	5VPCB16D653009218	5VPCB16D353008205	5VPCB16D053006685
5VPDC16DX53005755	5VPCB16D653009199	5VPCB16D353008186	5VPCB16D053006671
5VPDC16DX53005741	5VPCB16D653009185	5VPCB16D353008172	5VPCB16D053006668
5VPDC16DX53005738	5VPCB16D653009154	5VPCB16D353008169	5VPCB16D053006640
5VPCB16DX53005673	5VPCB16D653009106	5VPCB16D353008124	5VPCB16D053006637

5VPDC16DX53005657	5VPCB16D653009039	5VPCB16D353008110	5VPCB16D053006492
5VPCB16DX53005625	5VPCB16D653008943	5VPCB16D353008107	5VPCB16D053006489
5VPCD16DX53004386	5VPCB16D653008926	5VPCB16D353008074	5VPCB16D053006461
5VPCB16D953009603	5VPCB16D653008912	5VPCB16D353008060	5VPCB16D053006458
5VPCB16D953009598	5VPCB16D653008909	5VPCB16D353008057	5VPCB16D053006444
5VPCB16D953009584	5VPCB16D653008862	5VPDC16D353008044	5VPCB16D053006430
5VPCB16D953009567	5VPCB16D653008859	5VPCB16D353008026	5VPCB16D053006427
5VPCB16D953009505	5VPCB16D653008845	5VPDC16D353008013	5VPCB16D053006413
5VPCB16D953009455	5VPDC16D653008801	5VPDC16D353007721	5VPCB16D053006394
5VPCB16D953009441	5VPCB16D653008716	5VPDC16D353007718	5VPCB16D053006380
5VPCB16D953009293	5VPCB16D653008697	5VPDC16D353007704	5VPCB16D053006377
5VPCB16D953009245	5VPCB16D653008666	5VPCB16D353007491	5VPCB16D053006234
5VPCB16D953009231	5VPCB16D653008635	5VPCB16D353007488	5VPCB16D053006220
5VPCB16D953009214	5VPCB16D653008604	5VPCB16D353007474	5VPCB16D053006217
5VPCB16D953009150	5VPDC16D653008541	5VPCB16D353007460	5VPCB16D053006203
5VPCB16D953009066	5VPCB16D653008411	5VPCB16D353007457	5VPCB16D053006198
5VPCB16D953009035	5VPCB16D653008408	5VPCB16D353007426	5VPCB16D053006184
5VPCB16D953008922	5VPDC16D653008393	5VPCB16D353007412	5VPCB16D053006170
5VPCB16D953008919	5VPCB16D653008392	5VPCB16D353007409	5VPCB16D053006167
5VPCB16D953008905	5VPCB16D653008389	5VPCB16D353007393	5VPCB16D053006153
5VPCB16D953008872	5VPDC16D653008376	5VPCB16D353007281	5VPCB16D053006136
5VPCB16D953008869	5VPDC16D653008250	5VPCB16D353007278	5VPCB16D053006122
5VPCB16D953008855	5VPDC16D653008233	5VPCB16D353007264	5VPCB16D053006119
5VPCB16D953008841	5VPCB16D653008215	5VPCB16D353007250	5VPCB16D053006105
5VPDC16D953008825	5VPCB16D653008201	5VPCB16D353007247	5VPCB16D053006086
5VPCB16D953008726	5VPCB16D653008196	5VPCB16D353007233	5VPCB16D053006072
5VPCB16D953008693	5VPCB16D653008182	5VPCB16D353007023	5VPCB16D053006069
5VPCB16D953008662	5VPCB16D653008179	5VPCB16D353007006	5VPCB16D053006055
5VPDC16D953008548	5VPCB16D653008151	5VPCB16D353006986	5VPCB16D053005942
5VPDC16D953008520	5VPCB16D653008148	5VPCB16D353006972	5VPCB16D053005939
5VPDC16D953008517	5VPCB16D653008098	5VPCB16D353006969	5VPCB16D053005925
5VPDC16D953008484	5VPDC16D653008054	5VPCB16D353006955	5VPCB16D053005911
5VPCB16D953008449	5VPCB16D653008036	5VPCB16D353006941	5VPCB16D053005908
5VPCB16D953008404	5VPDC16D653007986	5VPDC16D353006939	5VPCB16D053005892
5VPCB16D953008399	5VPDC16D653007972	5VPDC16D353006908	5VPCB16D053005889
5VPCB16D953008385	5VPDC16D653007969	5VPCB16D353006809	5VPCB16D053005875
5VPDC16D953008260	5VPCB16D653007775	5VPCB16D353006762	5VPCB16D053005861
5VPCB16D953008242	5VPCB16D653007761	5VPCB16D353006745	5VPCB16D053005858
5VPCB16D953008211	5VPDC16D653007745	5VPCB16D353006731	5VPCB16D053005844
5VPCB16D953008208	5VPDC16D653007597	5VPCB16D353006728	5VPCB16D053005830
5VPCB16D953008192	5VPCB16D653007484	5VPDC16D353006715	5VPCB16D053005827
5VPCB16D953008189	5VPCB16D653007470	5VPDC16D353006701	5VPCB16D053005813
5VPCB16D953008175	5VPCB16D653007467	5VPCB16D353006695	5VPDC16D053005750
5VPCB16D953008130	5VPCB16D653007453	5VPCB16D353006664	5VPDC16D053005747
5VPCB16D953008127	5VPCB16D653007436	5VPCB16D353006471	5VPCB16D053005682
5VPCB16D953008113	5VPCB16D653007422	5VPCB16D353006468	5VPCB16D053005679
5VPCB16D953008080	5VPCB16D653007419	5VPCB16D353006454	5VPCB16D053005620
5VPCB16D953008077	5VPCB16D653007310	5VPCB16D353006440	5VPDC16D053004470
5VPCB16D053004385			