



Polaris Industries Inc.
Product Development Center
7290 Viking Blvd E
Wyoming, MN 55092
T: 651-408-7579
F: 651-408-7605

C6V-259

(23 pages)

July 12, 2006

National Highway Traffic Safety Administration
Patricia Wallace, Office of Defects Investigation
400 Seventh Street, S.W.
Washington, D.C. 20590
T: (202) 366-5232
F: (202) 366-7882

Dear Ms. Wallace:

573.6 Defect Information Report

573.6.c.1.

Vehicle manufacturer's full name:

Polaris Industries Inc., Victory Motorcycle Division

Address:

2100 Highway 55
Medina, MN 55340-9800

573.6.c.2.

Vehicles potentially containing defect:

Some MY 2006 Vegas, 8-Ball, Kingpin and Kingpin Deluxe Victory motorcycles potentially contain this defect.

Vehicle Identification Numbers:

A list of affected VINs is attached.

Inclusive dates of manufacture:

February 11, 2005 to April 10, 2006.

Basis for recall population:

All MY 2006 Vegas, 8-Ball, Kingpin and Kingpin Deluxe Victory motorcycles manufactured during this time period are affected.

573.6.c.3.

Total number of vehicles potentially containing defect:

A total of 2,913 vehicles may contain this defect.

573.6.c.4.

Percentage of vehicles estimated to actually contain defect:

Victory estimates that 100% of the manufactured units may have this defect.

573.6.c.5.

Brief Summary:

Victory has determined that the material used for the manufacture of the rear axle may not be sufficient for the application in some limited instances. Victory has determined that it is possible that one of the retaining ears of the rear axle may break during the torquing procedure for the rear axle nut.

Detailed description:

The rear axle for the affected machines has a retaining plate and two corresponding retaining slots manufactured on the right side of the axle. When the rear axle nut is tightened on the left side of the machine, the assembly is secured.

In rare instances, Victory has determined that one of the two retaining slots can break off during initial assembly.

While Victory has determined that the remaining retaining slot provides sufficient retention for the rear axle, the redundant nature of the design would be compromised if one retaining slot were to break off.

If both retaining slots were to break off, the rear wheel assembly joint would not be properly secured. There have been no reports of both retaining slots breaking.

573.6.c.6.

Chronology:

Victory has received three warranty claims relating to one retaining slot breaking. Two claims were received on April 6, 2006 and one was received on April 27, 2006. In addition, two instances were observed at our Spirit Lake manufacturing plant. One instance occurred on March 7, 2006 and the other occurred on March 10, 2006.

Initially, the torque applied during assembly was investigated. However, no abnormalities were uncovered during this investigation.

Victory then contracted with an outside consulting firm for analysis of the axle. Their analysis determined that the material specified for the rear axle was the cause of the issue. In all instances the issue occurred while tightening the axle nut or directly after the nut had been tightened.

Victory then performed various lab and road tests to determine what the consequence of having only one retaining slot would be. The conclusion is that the rear wheel assembly remains intact with no abnormal characteristics and the other retaining slot does not break off. However, if an axle with one broken retaining slot was removed and installed so that the remaining retaining slot was loaded against the retaining plate when the axle nut is tightened – there is a possibility that the remaining retaining slot could break while tightening the rear axle nut.

Victory designed a rear axle using the same physical dimensions using a material suitable for the application.

573.6.c.8.

Remedy program:

Victory will conduct a safety recall by which we will require our dealer network to replace the axle on all affected machines using the axle which is made from a different material.

Estimated date on which notifications to Owners will begin:

July 28, 2006

Estimated date on which notification will be completed:

August 4, 2006

573.6.c.10.

Owner letter:

See attached Owner Notification letter.

573.6.c.11.

Manufacturer's campaign number:

V-06-02

Signed: Don L. Good Date: 7-28-06

Don L. Good
Product Compliance Specialist
Polaris Industries Inc.

Attachments

VIN List: Pages 4 – 18

Draft of Consumer Letter: Page 19

Draft of Dealer Bulletin: Pages: 20 - 23

SUBJECT: Recall Campaign - Rear Axle Replacement
2006 Victory Vegas[®], Vegas Eight Ball[™], Kingpin[™], and Kingpin[™] Deluxe models.
Warning and Safety Recall Notice 06V-xxx
Reference: Victory Safety Recall Bulletin V-06-02
PLEASE READ IMMEDIATELY

July 21, 2006

Dear Victory Owner:

DRAFT

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2006 Victory motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

The rear axle may crack or break at the retaining plate groove on the right side on the 2006 models listed above. Axle failure during operation could cause a loss of control, increasing the risk of a crash.

What Victory and your dealer will do:

To correct this possible defect, your authorized Victory dealer will replace the rear axle of your motorcycle. Repairs will be made by any authorized Victory motorcycle dealer at no cost to you. The actual repair will take approximately twenty five minutes to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment. Do not attempt repairs yourself. Repairs must be done only by an authorized Victory motorcycle dealer.

DO NOT OPERATE YOUR MOTORCYCLE UNTIL ALL REPAIRS HAVE BEEN COMPLETED!

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you are having difficulty obtaining the recall repair outlined in this letter, please call our Consumer Service department at (763) 417-8650.

If you no longer own your motorcycle, please call our Consumer Service department at (763) 417-8650 or write to the address below with the name and address of the new owner.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration at 400 Seventh Street S.W., Washington, D.C. 20590 or call the toll-free safety hotline at 1-888-327-4236 (TTY: 1-888-424-9153).

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,



Christopher Wolf
Manager, Service Dealer Development & Warranty

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days. If you are no longer the owner of the Victory motorcycle indicated by this letter, please contact our Consumer Service department @ 763-417-8650 so we may update our records. Or write to us at:

Polaris Industries Inc.
Consumer Service Department
2100 Highway 55
Medina, MN 55340-9962

Ref: V0602



TECHNICAL SERVICE BULLETIN

THE NEW AMERICAN MOTORCYCLE

Date: 7/17/2006

Victory Motorcycle

Bulletin Number: V-06-02

Model Years: 2006

☐ Safety Bulletin ☒ **Safety Recall** ☐ Service Bulletin ☐ Service Alert Fax ☐ Production Update Kit

Distribution: ☐ Owner / Principal ☐ Service Manager ☐ Sales Manager ☐ Parts Manager ☐ Technicians

This Service Bulletin is located at www.polarisdealers.com



- Confidential and Proprietary -

SUBJECT: Rear axle failure on 2006 Vegas[®], Vegas Eight Ball[™] and Kingpin[™]


AFFECTED MODEL(S):

DRAFT

Model(s) Affected	Model Number(s)	Vehicle Identification Numbers (VIN)
2006 Vegas 2006 Vegas Eight Ball 2006 Kingpin 2006 Kingpin Deluxe	V06GB26CA, V06GB26DA, V06GB26LA, V06AB26C, V06AB26D, V06AB26L, V06AB26U V06C126, V06C127, V06CB26L V06CD26C, V06CD26D, V06CD26L	5VPGB26#*6 P - 5VPAB26#*6 P - 5VPCB26#*6 P - 5VPCB26#*6 P - # = May be a C (Canada), D (U.S. 49 State), L (California), or U (United Kingdom) * = Check Digit. This could be either a letter or a number ALWAYS ENTER THE VIN NUMBER IN UNIT INQUIRY TO SEE IF A BULLETIN APPLIES.

IN PROCESS

IN PROCESS



PURPOSE:

Victory has become aware of rear axle failures caused by a material problem on the 2006 models listed above which are equipped with a retainer plate style rear axle. Some rear axles could crack or break at the retainer plate groove during operation, which could cause a loss of control, increasing the risk of a crash.

WHAT YOUR DEALERSHIP SHOULD DO:

1. Contact owners of delivered units immediately and make arrangements to perform this warranty repair.
2. Replace the axle on all affected vehicles in your inventory with new axle P/N 5135743. DO NOT operate or sell an affected vehicle until this bulletin has been completed.
3. File a warranty claim for affected units immediately after completion of this bulletin. Follow warranty claim filing procedures on page 2.

NOTE: Review the instructions provided on page 3 before attempting to remove the axle. There is a possibility that a burr or raised edge may be present on the axle that will prevent removal. You must remove any burrs or file/grind any raised edges prior to attempting axle removal, or the rear wheel bearings may be damaged.

CUSTOMER NOTIFICATION:

A customer Notification letter 06V-xxx (06-xxx in Canada) will be sent to registered owners of motorcycles affected by this bulletin. An example of the letter is shown on page 4. In addition to the notification letter sent by Victory, dealers are required to notify owners of motorcycles sold by their dealership, and to make arrangements to perform this bulletin repair immediately.

The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

PARTS INFORMATION:

PART NUMBER / DESCRIPTION	5135743 / Axle
QUANTITY	1 per affected unit
DIRECT SHIP FROM VICTORY?	Yes, Partial**
TO BE ORDERED BY DEALERS?	YES
AVAILABILITY	Available July 19th
** NOTE: Axles for approximately 25% of your affected inventory will be directly shipped to your dealership to help expedite this repair. Use normal parts channels to order axles for the remainder of your dealership's affected vehicles.	

WARRANTY CLAIM INFORMATION:

A single group claim may be submitted listing the complete (17 digit) Vehicle Identification Number for machines with the same model number. File claim type **SB (Service Bulletin)**. Enter **2203193** in the primary failed parts field. **DO NOT PUT MORE THAN ONE MODEL NUMBER ON A CLAIM.** If replacement of other components are found to be necessary while performing this bulletin, contact Victory Technical Service for approval/authorization.

Service Bulletin #	V-06-02
Claim Type	SB
Labor Allowance	24 minutes
Claim Part #	(Qty 1) 5135743 Axle and (Qty 1) 7170107 Warranty Decal


SERVICE BULLETIN COMPLETION DECAL:

Fill out and attach a Service Bulletin Completion Decal, PN 7170107, as shown. If you require more decals, order them through normal parts ordering channels.

Sincerely,



Christopher Wolf
Manager, Service Dealer Development and Warranty





The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

INSTRUCTIONS FOR AXLE REPLACEMENT:


Removal

1. Secure the motorcycle to a lift table or hoist with the front tire secured in a wheel vise.
2. Loosen rear axle nut about 5 turns.
3. Turn adjuster nuts (A) equal amounts counterclockwise using a 13mm deep well socket, and push tire / axle forward until belt is slackened.
4. Safely lift and support the rear of the motorcycle so the weight is removed from the rear tire. To make alignment easier when installing the new axle in a later step, do not elevate the rear tire more than necessary to remove the weight.
5. Tap axle to the right until retainer plate (B) can be removed.




IMPORTANT!

6. Before removing the axle, inspect it closely in area (C) for any burrs or raised edges that may have formed by contact with the retainer plate. Be sure to check both top and bottom side of the axle. Remove any burrs or raised areas carefully using a file or a small hand grinder.
7. Clean any metal shavings from the axle.
8. Draw axle out LEFT side.



Installation

1. Apply a thin film of Victory All Purpose Grease P/N 2872187 to the entire axle including the threaded portion.
2. Install the axle from left to right through the swingarm and all parts. Install the axle far enough to expose the slot for the retainer plate on the right side. Be sure the brake caliper bracket is engaged in the guide slot of the swingarm.
3. Rotate the axle as required to orient the slot approximately vertical.
4. Install the retainer plate from top to bottom, with the marks facing OUT (so they can be seen for belt alignment.)
5. Install the left side adjustment plate with marks OUT and install the axle nut.
6. Draw or tap the axle to the left until the retainer plate is fully engaged in the swingarm slot on the right side, and tighten the axle nut until lightly seated but do not tighten.
7. Turn axle adjuster nuts clockwise the equal amounts back to their original position.
8. Inspect wheel alignment and belt deflection and adjust as required (refer to appropriate service Manual).
9. Torque axle nut to 88 Nm (65 lb.-ft.).
10. Apply rear brake pedal 2-3 times to position brake pads. Release brake pedal and turn rear wheel by hand. Inspect for smooth, free rotation without binding or brake drag.



The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.

VIN	VIN	VIN	VIN
5VPGB26L763009552	5VPAB26D063001033	5VPCB26D163002149	5VPCB26D563003305
5VPCD26L863009553	5VPAB26D263001034	5VPGB26D263002128	5VPGB26D563003306
5VPCD26LX63009554	5VPAB26D363001043	5VPCB26D263002161	5VPCB26D863003296
5VPCB26D063009724	5VPAB26D463001049	5VPGB26D363002140	5VPGB26D863003297
5VPAB26D063009729	5VPGB26D563001071	5VPCB26D363002153	5VPCB26DX63003302
5VPCB26D263009725	5VPAB26D863001037	5VPGB26D363002154	5VPGB26DX63003303
5VPCB26D363009720	5VPAB26D863001040	5VPCB26D463002131	5VPCB26D063003325
5VPGB26D563009719	5VPAB26D963001032	5VPGB26D463002132	5VPCB26D563003319
5VPAB26D663009718	5VPAB26D963001046	5VPCB26D463002145	5VPCB26D563003322
5VPGB26D663009728	5VPCB26L063001064	5VPGB26D463002146	5VPCB26D663003328
5VPGB26D663009731	5VPCB26L463001052	5VPCB26D463002159	5VPCB26D663003331
5VPCB26D763009722	5VPCB26L563001058	5VPCB26D563002137	5VPGB26D663003332
5VPGB26D863009732	5VPCB26L563001061	5VPGB26D563002138	5VPCB26DX63003316
5VPCB26L763009727	5VPCB26L663001067	5VPCB26D663002129	5VPAB26D063003381
5VPAB26D163009741	5VPCB26L663001070	5VPGB26D663002150	5VPAB26D163003387
5VPCB26D163009747	5VPCB26LX63001055	5VPCB26D663002163	5VPAB26D163003390
5VPGB26D163009751	5VPCB26LX63001072	5VPCB26D763002141	5VPAB26D363003388
5VPCB26D263009756	5VPCB26D063001073	5VPGB26D763002142	5VPAB26D363003391
5VPAB26D363009742	5VPCB26D063001090	5VPCB26D763002155	5VPAB26D563003389
5VPCB26D363009748	5VPCB26D163001079	5VPCB26D863002133	5VPAB26D563003392
5VPGB26D363009749	5VPCB26D163001082	5VPGB26D863002134	5VPAB26D663003384
5VPGB26D563009753	5VPCB26D263001074	5VPCB26D863002147	5VPAB26D863003385
5VPCB26D663009744	5VPCB26D263001088	5VPGB26D863002148	5VPAB26DX63003386
5VPCB26D863009745	5VPCB26D263001091	5VPCB26D963002139	5VPCB26L063003395
5VPCB26D963009754	5VPCB26D363001083	5VPCB26DX63002151	5VPCB26L663003398
5VPGB26D163009796	5VPAB26D363001110	5VPGB26DX63002152	5VPCB26D063003440
5VPGB26D163009801	5VPCB26D463001092	5VPCB26DX63002165	5VPCB26D163003401
5VPGB26D363009797	5VPAB26D563001108	5VPGB26L063002166	5VPCB26D263003407
5VPGB26D363009802	5VPAB26D563001111	5VPGB26L763002164	5VPCB26D263003424
5VPGB26D563009798	5VPCB26D663001076	5VPCB26D063002191	5VPCB26D263003438
5VPGB26D563009803	5VPCB26D663001093	5VPAB26D063002196	5VPCB26D363003433
5VPCB26D663009792	5VPCB26D763001085	5VPCB26D163002183	5VPCB26D763003404
5VPGB26D763009799	5VPAB26D763001109	5VPCB26D163002197	5VPCB26D863003427
5VPGB26D763009804	5VPCB26D863001077	5VPCB26D263002175	5VPCB26D863003430
5VPCB26D863009793	5VPCB26D863001080	5VPCB26D263002189	5VPCB26D963003436
5VPGB26DX63009795	5VPCB26D863001094	5VPAB26D263002202	5VPCB26L463003402
5VPGB26DX63009800	5VPCB26D963001086	5VPCB26D363002167	5VPCB26L563003408
5VPGB26L963009794	5VPCB26DX63001095	5VPGB26D363002168	5VPCB26LX63003405
5VPCB26D163009957	5VPGB26L063001096	5VPAB26D363002192	5VPCB26D963003484
5VPCB26D363009958	5VPGB26L263001097	5VPCB26D363002203	5VPCB26L063003445
5VPCB26D663009954	5VPGB26L463001098	5VPCB26D463002193	5VPCB26L663003482
5VPCB26D863009955	5VPGB26L663001099	5VPAB26D463002198	5VPCB26L863003483
5VPCB26L163009951	5VPAB26D063001145	5VPCB26D563002171	5VPCB26D163003494
5VPCB26L563009953	5VPCB26D163001115	5VPCB26D563002185	5VPCB26D263003486
5VPCB26D063011649	5VPCB26D163001146	5VPCB26D563002199	5VPCB26D363003495
5VPCB26D063011652	5VPCB26D263001141	5VPCB26D663002177	5VPCB26D463003523
5VPCB26D163011644	5VPAB26D363001124	5VPAB26D663002204	5VPCB26D663003491
5VPCB26D163011658	5VPCB26D363001150	5VPCB26D763002169	5VPCB26D763003497

5VPCB26D263011653	5VPAB26D463001133	5VPAB26D763002194	5VPCB26D863003489
5VPCB26D363011645	5VPCB26D463001142	5VPCB26D763002205	5VPCB26D863003492
5VPCB26D463011654	5VPAB26D463001147	5VPCB26D863002181	5VPCB26D963003498
5VPAB26D463011659	5VPAB26D563001139	5VPCB26D863002195	5VPCB26L163003485
5VPCB26D563011646	5VPCB26D563001148	5VPCB26D963002173	5VPCB26L763003488
5VPCB26D663011655	5VPCB26D563001151	5VPCB26D963002187	5VPAB26D163003549
5VPCB26D763011647	5VPAB26D763001112	5VPAB26D963002200	5VPAB26D163003552
5VPCB26D763011650	5VPAB26D763001143	5VPCB26DX63002179	5VPAB26D363003553
5VPCB26D863011656	5VPCB26D763001149	5VPCB26DX63002201	5VPAB26D563003554
5VPCB26D963011648	5VPCB26D763001152	5VPCB26D063002207	5VPAB26D663003546
5VPCB26D963011651	5VPAB26D863001118	5VPAB26D063002215	5VPAB26D763003555
5VPCB26DX63011643	5VPAB26D863001121	5VPAB26D063002229	5VPAB26D863003547
5VPCB26DX63011657	5VPCB26D863001144	5VPAB26D363002208	5VPAB26D863003550
5VPAB26D063011660	5VPAB26D963001127	5VPAB26D363002211	5VPAB26DX63003548
5VPGB26D063011667	5VPAB26D963001130	5VPAB26D363002225	5VPAB26DX63003551
5VPGB26D163011662	5VPCB26D963001153	5VPCB26D363002234	5VPCB26D063003566
5VPGB26D263011668	5VPAB26DX63001136	5VPCB26D463002209	5VPCB26D163003558
5VPGB26D363011663	5VPGB26D063001155	5VPAB26D463002217	5VPCB26D263003567
5VPGB26D463011669	5VPCB26D063001171	5VPAB26D663002221	5VPCB26D363003559
5VPGB26D563011664	5VPGB26D063001186	5VPAB26D763002213	5VPCB26D463003568
5VPGB26D763011665	5VPCB26D163001163	5VPAB26D763002227	5VPCB26D663003569
5VPGB26D963011666	5VPCB26D263001169	5VPAB26D863002219	5VPCB26D863003556
5VPAB26L363011661	5VPCB26D263001172	5VPAB26D963002231	5VPCB26D963003565
5VPGB26D063011720	5VPCB26D363001164	5VPCB26D963002237	5VPCB26DX63003557
5VPCB26D263011717	5VPCB26D463001173	5VPCB26D963002240	5VPCB26DX63003560
5VPGB26D263011721	5VPGB26D463001174	5VPAB26DX63002206	5VPCB26D063003597
5VPCB26D463011718	5VPCB26D463001190	5VPAB26DX63002223	5VPCB26D163003625
5VPGB26D463011719	5VPGB26D563001183	5VPGB26L363002243	5VPCB26D363003626
5VPGB26D463011722	5VPCB26D663001157	5VPGB26L963002246	5VPCB26D463003599
5VPGB26D663011723	5VPCB26D663001160	5VPAB26D063002280	5VPCB26D563003627
5VPCB26D763011714	5VPGB26D663001175	5VPAB26D163002286	5VPCB26D763003595
5VPCB26D963011715	5VPGB26D663001189	5VPCB26D263002256	5VPCB26D763003628
5VPGB26D963011716	5VPCB26D663001191	5VPGB26D263002274	5VPCB26D963003601
5VPGB26D063011751	5VPCB26D763001166	5VPAB26D263002281	5VPCB26DX63003624
5VPGB26D263011752	5VPCB26D863001158	5VPCB26D363002251	5VPAB26D063003669
5VPGB26D963011750	5VPCB26D863001161	5VPCB26D363002265	5VPAB26D063003672
5VPGB26D063000104	5VPGB26D863001176	5VPAB26D363002287	5VPCB26D463003635
5VPGB26D263000105	5VPCB26D863001192	5VPCB26D463002257	5VPAB26D763003670
5VPGB26D363000100	5VPGB26D963001154	5VPAB26D463002279	5VPAB26D963003671
5VPGB26D463000106	5VPCB26D963001167	5VPAB26D463002282	5VPAB26D063003686
5VPGB26D563000101	5VPCB26D963001170	5VPCB26D563002249	5VPAB26D263003673
5VPGB26D663000107	5VPGB26DX63001177	5VPAB26D563002288	5VPAB26D263003687
5VPGB26D763000102	5VPGB26DX63001180	5VPAB26D663002283	5VPAB26D263003690
5VPGB26D863000108	5VPAB26D063001209	5VPCB26D763002253	5VPAB26D463003674
5VPGB26D963000103	5VPCB26D063001218	5VPGB26D763002268	5VPAB26D463003688
5VPGB26DX63000109	5VPCB26D063001221	5VPGB26D763002271	5VPAB26D663003689
5VPCB26D063000117	5VPAB26D163001204	5VPCB26D863002259	5VPAB26D963003685
5VPCB26D063000120	5VPCB26D163001230	5VPCB26D863002262	5VPAB26D163003731
5VPCB26D063000134	5VPGB26D163001231	5VPGB26D863002277	5VPAB26D363003732
5VPCB26D163000126	5VPCB26D263001219	5VPAB26D863002284	5VPAB26D563003733

5VPCB26D263000118	5VPCB26D263001222	5VPCB26D963002254	5VPAB26D763003734
5VPCB26D263000121	5VPAB26D363001205	5VPGB26D963002255	5VPAB26DX63003730
5VPCB26D263000135	5VPAB26D463001195	5VPAB26DX63002285	5VPAB26D063003767
5VPGB26D263000136	5VPCB26D463001223	5VPAB26D163002305	5VPCB26D063003776
5VPCB26D363000127	5VPAB26D563001206	5VPGB26D263002291	5VPCB26D163003768
5VPCB26D363000130	5VPCB26D563001229	5VPAB26D263002300	5VPCB26D163003771
5VPCB26D463000119	5VPAB26D763001207	5VPCB26D363002301	5VPAB26D363003763
5VPCB26D463000122	5VPAB26D763001210	5VPAB26D363002306	5VPCB26D363003772
5VPGB26D463000137	5VPCB26D763001216	5VPGB26D363002316	5VPAB26D563003764
5VPGB26D463000140	5VPAB26D963001208	5VPGB26D463002292	5VPCB26D963003775
5VPCB26D563000128	5VPAB26D963001211	5VPAB26D463002296	5VPAB26D363003830
5VPCB26D563000131	5VPCB26D963001217	5VPCB26D463002307	5VPAB26D563003831
5VPCB26D663000123	5VPCB26D963001220	5VPCB26D463002310	5VPAB26D763003829
5VPGB26D663000138	5VPAB26L163001212	5VPGB26D563002320	5VPAB26D763003832
5VPCB26D763000129	5VPAB26L163001226	5VPAB26D663002297	5VPAB26D963003833
5VPCB26D763000132	5VPAB26L363001213	5VPAB26D663002302	5VPAB26D163003874
5VPCB26D863000124	5VPAB26L563001214	5VPCB26D763002298	5VPAB26D363003844
5VPGB26D863000139	5VPAB26L763001215	5VPAB26D763002308	5VPAB26D563003876
5VPCB26D963000116	5VPAB26L863001224	5VPGB26D763002321	5VPAB26D863003869
5VPCB26D963000133	5VPAB26LX63001225	5VPAB26D863002303	5VPAB26D863003872
5VPCB26DX63000125	5VPAB26L063001265	5VPGB26D863002313	5VPCB26L063003879
5VPAB26D063000156	5VPAB26L163001260	5VPCB26D963002304	5VPCB26L363003875
5VPCB26D063000165	5VPAB26L263001252	5VPAB26D963002309	5VPCB26L663003871
5VPGB26D163000144	5VPAB26L563001262	5VPGB26D963002319	5VPCB26L763003877
5VPAB26D163000148	5VPAB26L863001255	5VPAB26DX63002299	5VPCB26LX63003873
5VPAB26D163000151	5VPCB26D063001283	5VPCB26D063002336	5VPCB26D163003897
5VPCB26D163000160	5VPCB26D163001275	5VPAB26D063002358	5VPAB26D163003910
5VPAB26D263000157	5VPCB26D263001284	5VPAB26D063002361	5VPCB26D363003903
5VPCB26D263000166	5VPCB26D363001276	5VPGB26D163002329	5VPAB26D363003908
5VPGB26D363000145	5VPCB26D463001271	5VPCB26D163002331	5VPCB26D363003920
5VPAB26D363000149	5VPCB26D463001285	5VPCB26D163002345	5VPAB26D563003912
5VPAB26D363000152	5VPCB26D563001277	5VPAB26D163002353	5VPCB26D863003900
5VPCB26D363000158	5VPCB26D563001280	5VPCB26D163002362	5VPAB26D963003914
5VPCB26D363000161	5VPCB26D663001272	5VPCB26D263002337	5VPAB26DX63003906
5VPCB26D463000167	5VPCB26D763001278	5VPCB26D263002340	5VPCB26L063003882
5VPAB26D563000153	5VPCB26D763001281	5VPAB26D263002359	5VPCB26L163003888
5VPCB26D563000159	5VPCB26D863001273	5VPCB26D363002332	5VPCB26L163003891
5VPCB26D563000162	5VPGB26D863001288	5VPAB26D363002354	5VPCB26L663003885
5VPAB26D563000170	5VPGB26D863001291	5VPCB26D363002363	5VPCB26L763003894
5VPGB26D663000141	5VPCB26D963001279	5VPCB26D463002338	5VPAB26D163003938
5VPCB26D663000168	5VPCB26D963001282	5VPCB26D463002341	5VPAB26D163003941
5VPAB26D763000154	5VPCB26DX63001274	5VPCB26D563002333	5VPCB26D263003925
5VPCB26D763000163	5VPCB26L263001289	5VPAB26D563002355	5VPCB26D363003934
5VPAB26D763000171	5VPCB26L263001292	5VPCB26D563002364	5VPAB26D363003939
5VPGB26D863000142	5VPCB26L763001286	5VPGB26D663002326	5VPAB26D363003942
5VPAB26D863000146	5VPCB26L963001290	5VPCB26D663002339	5VPCB26D463003943
5VPCB26D863000169	5VPAB26D063001324	5VPCB26D663002342	5VPCB26D463003960
5VPAB26D963000155	5VPGB26D063001334	5VPCB26D763002334	5VPCB26D563003949
5VPCB26D963000164	5VPGB26D063001348	5VPCB26D763002348	5VPCB26D763003922
5VPAB26D963000172	5VPGB26D063001351	5VPCB26D763002351	5VPCB26D863003928

5VPGB26DX63000143	5VPGB26D163001312	5VPAB26D763002356	5VPCB26D863003931
5VPAB26DX63000147	5VPGB26D163001343	5VPCB26D763002365	5VPAB26D863003936
5VPAB26DX63000150	5VPCB26D263001317	5VPCB26D963002335	5VPCB26D963003937
5VPAB26D063000173	5VPCB26D263001320	5VPAB26D963002357	5VPCB26D963003940
5VPCB26D063000182	5VPAB26D263001325	5VPAB26D963002360	5VPCB26DX63003946
5VPCB26D163000188	5VPGB26D263001349	5VPCB26D963002366	5VPAB26D063003994
5VPCB26D163000191	5VPGB26D363001313	5VPCB26DX63002327	5VPAB26D163003969
5VPCB26D163000207	5VPCB26D363001326	5VPGB26DX63002328	5VPAB26D163003972
5VPAB26D263000174	5VPGB26D363001344	5VPCB26DX63002330	5VPAB26D263003995
5VPCB26D263000183	5VPCB26D463001335	5VPAB26DX63002352	5VPAB26D363003973
5VPCB26D363000189	5VPGB26D463001336	5VPCB26D063002367	5VPCB26D463003988
5VPCB26D363000208	5VPGB26D563001314	5VPCB26D063002370	5VPCB26D463003991
5VPAB26D463000175	5VPGB26D563001331	5VPCB26D263002368	5VPCB26D663003989
5VPCB26D463000184	5VPGB26D563001345	5VPCB26D263002371	5VPCB26D663003992
5VPCB26D663000185	5VPAB26D663001327	5VPGB26D263002372	5VPAB26D663003997
5VPCB26D763000180	5VPAB26D663001330	5VPCB26D263002385	5VPAB26D863003970
5VPAB26D763000204	5VPGB26D663001337	5VPCB26D363002377	5VPAB26D863003998
5VPCB26D863000186	5VPGB26D663001340	5VPCB26D463002369	5VPAB26DX63003971
5VPCB26D963000181	5VPAB26D763001322	5VPCB26D563002381	5VPAB26DX63003999
5VPAB26D963000205	5VPGB26D763001346	5VPCB26D663002373	5VPCB26DX63004000
5VPCB26DX63000187	5VPCB26D863001323	5VPCB26D663002387	5VPAB26D063004014
5VPCB26DX63000190	5VPAB26D863001328	5VPCB26D763002379	5VPAB26D263004015
5VPCB26DX63000206	5VPGB26D863001341	5VPCB26D963002383	5VPAB26D263004032
5VPCB26D063000215	5VPCB26D963001315	5VPCB26DX63002375	5VPAB26D363004041
5VPCB26D063000232	5VPGB26D963001316	5VPCB26DX63002389	5VPAB26D463004016
5VPGB26D063000233	5VPCB26D963001329	5VPAB26D063002392	5VPAB26D463004033
5VPCB26D063000246	5VPCB26D963001332	5VPCB26D063002403	5VPAB26D563004011
5VPCB26D163000210	5VPGB26D963001333	5VPAB26D163002398	5VPAB26D563004042
5VPCB26D163000224	5VPGB26D963001347	5VPCB26D163002409	5VPAB26D663004017
5VPGB26D163000225	5VPGB26D963001350	5VPCB26D163002412	5VPAB26D663004034
5VPCB26D163000238	5VPCB26DX63001338	5VPGB26D163002413	5VPAB26D763004009
5VPCB26D163000241	5VPGB26DX63001339	5VPAB26D263002393	5VPAB26D763004012
5VPCB26D263000216	5VPGB26DX63001342	5VPCB26D263002418	5VPAB26D863004035
5VPCB26D263000247	5VPAB26L663001318	5VPGB26D263002419	5VPAB26D963004013
5VPCB26D363000211	5VPAB26L663001321	5VPCB26D263002421	5VPAB26DX63004036
5VPCB26D363000239	5VPAB26L863001319	5VPGB26D263002422	5VPCB26D063004068
5VPCB26D363000242	5VPCB26D063001364	5VPCB26D363002394	5VPCB26D063004071
5VPCB26D463000217	5VPGB26D063001382	5VPAB26D363002399	5VPCB26D163004063
5VPGB26D463000218	5VPCB26D163001373	5VPAB26D363002404	5VPCB26D163004080
5VPCB26D463000220	5VPGB26D163001374	5VPGB26D363002414	5VPCB26D263004069
5VPGB26D463000221	5VPGB26D263001352	5VPCB26D363002430	5VPCB26D263004072
5VPCB26D463000234	5VPAB26D263001356	5VPCB26D563002400	5VPCB26D563004065
5VPGB26D463000235	5VPCB26D263001379	5VPAB26D563002405	5VPCB26D663004060
5VPCB26D463000248	5VPAB26D363001365	5VPCB26D563002428	5VPCB26D763004066
5VPCB26D563000209	5VPGB26D363001375	5VPAB26D663002395	5VPCB26D963004084
5VPCB26D563000212	5VPAB26D463001357	5VPCB26D663002406	5VPCB26DX63004062
5VPCB26D563000226	5VPAB26D463001360	5VPGB26D663002407	5VPCB26D063004085
5VPGB26D563000227	5VPCB26D563001358	5VPGB26D663002410	5VPCB26D063004104
5VPCB26D563000243	5VPCB26D563001361	5VPCB26D763002415	5VPCB26D263004086
5VPGB26D663000219	5VPAB26D563001366	5VPGB26D763002416	5VPCB26D463004087

5VPCB26D763000213	5VPCB26D663001367	5VPCB26D763002429	5VPCB26D463004090
5VPCB26D763000230	5VPGB26D663001368	5VPCB26D863002391	5VPCB26D663004088
5VPGB26D763000231	5VPCB26D663001370	5VPAB26D863002396	5VPCB26D663004091
5VPCB26D763000244	5VPGB26D663001371	5VPAB26D863002401	5VPCB26D863004089
5VPCB26D863000222	5VPCB26D763001376	5VPGB26D863002408	5VPCB26D963004103
5VPGB26D863000223	5VPGB26D763001377	5VPGB26D863002411	5VPAB26D063004112
5VPCB26D863000236	5VPGB26D763001380	5VPCB26D863002424	5VPAB26D263004113
5VPGB26D863000237	5VPAB26D863001359	5VPCB26D963002397	5VPAB26D663004115
5VPCB26D963000214	5VPAB26D863001362	5VPGB26D963002417	5VPAB26D163004121
5VPCB26D963000228	5VPGB26D863001369	5VPGB26D963002420	5VPAB26D363004119
5VPGB26D963000229	5VPGB26D863001372	5VPAB26DX63002402	5VPAB26D363004122
5VPCB26D963000245	5VPGB26D963001378	5VPGB26D163002458	5VPAB26D463004131
5VPCB26DX63000240	5VPGB26D963001381	5VPGB26D163002461	5VPAB26D563004123
5VPAB26D063000254	5VPCB26DX63001355	5VPGB26D263002436	5VPAB26D663004132
5VPGB26D063000264	5VPAB26DX63001363	5VPGB26D263002467	5VPAB26D863004116
5VPAB26D163000263	5VPCB26D063001395	5VPGB26D263002470	5VPAB26D863004133
5VPGB26D163000273	5VPCB26D263001401	5VPGB26D463002440	5VPAB26DX63004120
5VPCB26D263000250	5VPCB26D563001392	5VPCB26D563002431	5VPAB26DX63004134
5VPAB26D263000255	5VPCB26D863001404	5VPGB26D563002432	5VPAB26L163004126
5VPCB26D363000256	5VPAB26D063001419	5VPGB26D663002438	5VPAB26L363004127
5VPCB26D463000265	5VPAB26D063001422	5VPGB26D663002455	5VPAB26L863004124
5VPGB26D463000266	5VPAB26D163001428	5VPGB26D763002464	5VPCB26L963004125
5VPAB26D563000251	5VPAB26D163001431	5VPGB26D863002473	5VPGB26D063004167
5VPCB26D663000249	5VPGB26D163001438	5VPGB26D963002434	5VPAB26D163004135
5VPAB26D663000257	5VPAB26D163001445	5VPGB26L163002452	5VPCB26D263004153
5VPAB26D663000260	5VPCB26D363001407	5VPGB26L263002444	5VPAB26D363004136
5VPGB26D663000267	5VPCB26D363001410	5VPGB26L663002446	5VPAB26D563004137
5VPGB26D663000270	5VPGB26D363001439	5VPGB26L863002450	5VPAB26D563004140
5VPAB26D763000252	5VPCB26D463001416	5VPGB26L963002442	5VPAB26D763004141
5VPCB26D863000253	5VPAB26D563001433	5VPGB26LX63002448	5VPGB26D863004157
5VPAB26D863000258	5VPAB26D663001425	5VPGB26D063002502	5VPAB26D963004139
5VPAB26D863000261	5VPGB26D663001435	5VPGB26D163002492	5VPAB26L363004161
5VPCB26D963000259	5VPAB26D663001442	5VPGB26D163002508	5VPCB26L563004154
5VPCB26D963000262	5VPAB26D763001434	5VPGB26D163002511	5VPAB26L563004159
5VPCB26DX63000268	5VPGB26D863001436	5VPGB26D263002484	5VPCB26L763004155
5VPGB26DX63000269	5VPCB26D963001413	5VPGB26D263002498	5VPAB26L763004163
5VPCB26DX63000271	5VPGB26DX63001437	5VPGB26D363002476	5VPGB26D663004187
5VPGB26DX63000272	5VPGB26L063001440	5VPGB26D363002512	5VPGB26DX63004189
5VPCB26D263000281	5VPGB26L263001441	5VPGB26D463002504	5VPAB26L063004201
5VPGB26D363000288	5VPGB26L663001443	5VPGB26D563002480	5VPAB26L363004175
5VPCB26D563000274	5VPGB26L863001444	5VPGB26D563002494	5VPAB26L663004171
5VPGB26D563000289	5VPAB26D063001453	5VPGB26D563002513	5VPGB26L663004195
5VPGB26D663000284	5VPCB26D263001446	5VPGB26D663002486	5VPAB26L663004199
5VPGB26D963000280	5VPCB26D463001450	5VPGB26D763002478	5VPAB26LX63004173
5VPCB26DX63000285	5VPAB26D563001447	5VPGB26D763002500	5VPGB26LX63004197
5VPCB26D063000313	5VPAB26D563001464	5VPGB26D763002514	5VPAB26L063004215
5VPCB26D063000327	5VPCB26D663001448	5VPGB26D863002490	5VPCB26L163004233
5VPCB26D163000319	5VPAB26D763001451	5VPGB26D863002506	5VPAB26L463004217
5VPCB26D163000322	5VPAB26D963001449	5VPGB26D963002482	5VPCB26L563004235
5VPAB26D163000330	5VPCB26L163001462	5VPGB26D963002496	5VPAB26L763004213

5VPCB26D263000331	5VPCB26L263001454	5VPGB26DX63002488	5VPAB26L863004219
5VPAB26D263000336	5VPCB26L263001468	5VPCB26D063002532	5VPCB26L863004231
5VPAB26D363000314	5VPCB26L463001469	5VPCB26D263002516	5VPCB26L963004237
5VPCB26D363000323	5VPCB26L663001456	5VPGB26D663002522	5VPCB26L063004255
5VPAB26D363000328	5VPCB26L863001460	5VPCB26D863002519	5VPCB26L463004257
5VPCB26D363000337	5VPCB26L963001452	5VPGB26L063002524	5VPCB26L763004253
5VPCB26D463000315	5VPCB26L963001466	5VPGB26L663002530	5VPCB26L863004259
5VPCB26D463000329	5VPCB26LX63001458	5VPGB26L863002531	5VPCB26LX63004263
5VPAB26D463000340	5VPGB26D063001480	5VPGB26LX63002529	5VPCB26D663004317
5VPAB26D563000332	5VPGB26D063001494	5VPAB26D063002568	5VPCB26D863004318
5VPCB26D563000341	5VPAB26D063001498	5VPAB26D163002563	5VPCB26DX63004319
5VPAB26D663000310	5VPGB26D163001486	5VPGB26D163002573	5VPCB26L363004315
5VPAB26D663000324	5VPGB26D263001478	5VPAB26D263002569	5VPCB26LX63004313
5VPCB26D663000333	5VPAB26D263001504	5VPGB26D363002574	5VPAB26D463004386
5VPAB26D663000338	5VPGB26D263001514	5VPCB26D463002551	5VPAB26D663004387
5VPCB26D763000311	5VPGB26D363001490	5VPCB26D563002557	5VPAB26D863004388
5VPAB26D763000316	5VPGB26D463001479	5VPGB26D563002575	5VPAB26D063004417
5VPCB26D763000325	5VPGB26D463001482	5VPCB26D663002535	5VPAB26D163004412
5VPCB26D763000339	5VPGB26D563001488	5VPAB26D663002560	5VPAB26D263004418
5VPCB26D863000317	5VPAB26D563001500	5VPGB26D663002570	5VPAB26D363004413
5VPCB26D863000320	5VPAB26D663001506	5VPAB26D763002566	5VPAB26D463004419
5VPCB26D963000312	5VPGB26D663001516	5VPGB26D763002576	5VPAB26D563004414
5VPAB26D963000334	5VPGB26D763001492	5VPGB26D863002571	5VPAB26D763004415
5VPCB26DX63000318	5VPAB26D763001496	5VPCB26DX63002537	5VPAB26D963004416
5VPCB26DX63000321	5VPGB26D863001484	5VPCB26DX63002554	5VPCB26D063004457
5VPAB26DX63000326	5VPAB26D863001510	5VPGB26DX63002572	5VPGB26D063004475
5VPCB26DX63000335	5VPAB26D963001502	5VPAB26L063002545	5VPCB26D263004461
5VPAB26D063000349	5VPGB26D963001512	5VPAB26L163002540	5VPGB26D363004471
5VPAB26D063000352	5VPAB26DX63001508	5VPGB26L363002534	5VPCB26D463004459
5VPAB26D163000358	5VPGB26D063001527	5VPAB26L363002541	5VPGB26D563004469
5VPAB26D163000361	5VPAB26D163001543	5VPAB26L663002548	5VPGB26D763004473
5VPCB26D163000367	5VPGB26D263001531	5VPAB26L963002544	5VPAB26D163004507
5VPCB26D163000370	5VPCB26D263001544	5VPCB26D063002594	5VPAB26D163004510
5VPAB26D563000346	5VPGB26D363001523	5VPGB26D063002614	5VPCB26D163004516
5VPAB26D663000355	5VPCB26D363001536	5VPCB26D263002600	5VPAB26D363004508
5VPCB26D663000364	5VPGB26D363001537	5VPGB26D263002615	5VPAB26D563004509
5VPAB26D863000342	5VPGB26D463001529	5VPCB26D363002606	5VPCB26D863004514
5VPCB26D963000343	5VPCB26D563001540	5VPGB26D363002610	5VPCB26D863004528
5VPCB26D063000375	5VPGB26D563001541	5VPCB26D463002579	5VPAB26DX63004506
5VPCB26D063000389	5VPGB26D663001533	5VPCB26D463002582	5VPGB26L063004497
5VPCB26D163000384	5VPGB26D763001525	5VPCB26D563002588	5VPGB26L363004493
5VPCB26D163000398	5VPCB26D763001538	5VPCB26D563002591	5VPGB26L463004499
5VPCB26D163000403	5VPGB26D763001539	5VPGB26D563002608	5VPGB26L763004495
5VPCB26D263000376	5VPCB26D963001542	5VPGB26D563002611	5VPGB26LX63004491
5VPCB26D263000393	5VPGB26DX63001518	5VPCB26D663002597	5VPAB26D163004541
5VPCB26D363000385	5VPGB26DX63001521	5VPGB26D763002612	5VPCB26D163004547
5VPCB26D363000399	5VPGB26DX63001535	5VPCB26D863002603	5VPAB26D263004533
5VPCB26D363000404	5VPCB26L063001520	5VPGB26D963002613	5VPAB26D363004539
5VPCB26D463000377	5VPCB26L063001534	5VPCB26DX63002585	5VPCB26D463004543
5VPCB26D463000380	5VPCB26L163001526	5VPAB26L063002609	5VPAB26D663004535

5VPCB26D463000394	5VPCB26L363001530	5VPAB26L163002599	5VPCB26D863004545
5VPCB26D563000372	5VPCB26L563001528	5VPAB26L163002604	5VPAB26DX63004537
5VPCB26D563000386	5VPCB26L763001532	5VPAB26L363002605	5VPAB26L063004568
5VPCB26D563000405	5VPCB26D063001574	5VPAB26L663002601	5VPAB26L463004556
5VPCB26D663000378	5VPAB26D063001582	5VPAB26L763002607	5VPAB26L663004560
5VPCB26D663000381	5VPCB26D163001566	5VPAB26L863002602	5VPAB26L863004558
5VPCB26D663000395	5VPGB26D163001584	5VPAB26L863002616	5VPAB26LX63004562
5VPCB26D663000400	5VPCB26D263001561	5VPAB26LX63002617	5VPCB26D263004573
5VPCB26D763000373	5VPAB26D263001583	5VPCB26D063002627	5VPCB26D963004571
5VPCB26D763000390	5VPCB26D363001567	5VPCB26D063002630	5VPGB26L063004600
5VPCB26D863000379	5VPCB26D363001570	5VPCB26D163002636	5VPGB26L163004590
5VPCB26D863000382	5VPCB26D463001562	5VPCB26D563002624	5VPGB26L263004596
5VPCB26D863000396	5VPCB26D563001568	5VPCB26D663002633	5VPGB26L363004588
5VPCB26D863000401	5VPCB26D563001571	5VPCB26D763002639	5VPGB26L463004602
5VPCB26D963000374	5VPAB26D563001576	5VPCB26D763002642	5VPGB26L663004584
5VPCB26D963000388	5VPCB26D663001563	5VPCB26DX63002621	5VPGB26L663004598
5VPCB26D963000391	5VPCB26D763001569	5VPAB26L063002657	5VPAB26L963004570
5VPCB26DX63000383	5VPCB26D763001572	5VPAB26L163002618	5VPGB26L963004594
5VPCB26DX63000397	5VPAB26D763001577	5VPAB26L263002658	5VPGB26LX63004572
5VPCB26DX63000402	5VPAB26D763001580	5VPAB26L363002653	5VPAB26L063004618
5VPAB26D063000433	5VPCB26D863001564	5VPAB26L463002645	5VPAB26L263004622
5VPAB26D263000434	5VPCB26D963001573	5VPAB26L563002654	5VPAB26L363004614
5VPAB26D463000435	5VPAB26D963001578	5VPAB26L763002655	5VPCB26L363004637
5VPAB26D663000436	5VPAB26D963001581	5VPAB26L963002656	5VPAB26L763004616
5VPAB26D763000431	5VPCB26DX63001565	5VPAB26LX63002648	5VPCB26L763004639
5VPAB26D963000432	5VPCB26DX63001579	5VPAB26LX63002651	5VPAB26L963004620
5VPAB26D163000456	5VPGB26D063001589	5VPCB26D063002689	5VPAB26LX63004612
5VPCB26D163000465	5VPGB26D063001592	5VPGB26D063002693	5VPGB26D063004640
5VPAB26D263000451	5VPAB26D063001601	5VPAB26D163002675	5VPGB26D263004672
5VPAB26D363000457	5VPGB26D163001598	5VPCB26D263002662	5VPGB26D363004678
5VPAB26D363000460	5VPAB26D163001607	5VPAB26D263002684	5VPGB26D463004642
5VPCB26D363000466	5VPGB26D263001593	5VPGB26D263002694	5VPAB26D463004677
5VPAB26D463000452	5VPAB26D263001602	5VPCB26D363002668	5VPGB26D663004674
5VPCB26D463000461	5VPGB26D363001585	5VPCB26D363002671	5VPGB26DX63004676
5VPAB26D563000458	5VPGB26D463001594	5VPAB26D363002676	5VPCB26L163004653
5VPAB26D663000453	5VPAB26D463001603	5VPCB26D463002677	5VPAB26L163004675
5VPCB26D663000462	5VPGB26D563001586	5VPCB26D463002680	5VPCB26L263004645
5VPCB26D763000437	5VPCB26D563001599	5VPAB26D463002685	5VPAB26L463004671
5VPAB26D763000459	5VPGB26D663001595	5VPGB26D463002695	5VPCB26L563004641
5VPAB26D863000454	5VPAB26D663001604	5VPCB26D563002686	5VPCB26L563004655
5VPCB26D863000463	5VPGB26D763001587	5VPGB26D563002690	5VPAB26L563004663
5VPAB26DX63000455	5VPGB26D763001590	5VPGB26D663002696	5VPCB26L663004647
5VPCB26DX63000464	5VPGB26D863001596	5VPAB26D763002678	5VPCB26L863004651
5VPCB26D063000473	5VPCB26D863001600	5VPAB26D763002681	5VPAB26L863004673
5VPAB26D063000495	5VPAB26D863001605	5VPGB26D763002691	5VPCB26LX63004649
5VPCB26D163000479	5VPGB26D963001588	5VPCB26D863002665	5VPGB26D063004704
5VPGB26D163000483	5VPGB26D963001591	5VPAB26D863002687	5VPGB26D463004706
5VPAB26D163000487	5VPGB26DX63001597	5VPGB26D863002697	5VPGB26D563004682
5VPAB26D163000490	5VPAB26DX63001606	5VPCB26D963002674	5VPGB26D563004701
5VPGB26D163000497	5VPGB26D063001611	5VPAB26D963002679	5VPCB26D663004687

5VPCB26D263000474	5VPCB26D063001624	5VPAB26D963002682	5VPCB26D663004690
5VPAB26D263000496	5VPGB26D063001625	5VPGB26D963002692	5VPGB26D663004707
5VPGB26D363000484	5VPCB26D163001616	5VPCB26DX63002683	5VPGB26D763004702
5VPAB26D363000488	5VPGB26D163001617	5VPAB26DX63002688	5VPCB26D863004691
5VPAB26D363000491	5VPGB26D163001634	5VPAB26L463002659	5VPCB26DX63004689
5VPGB26D363000498	5VPAB26D163001641	5VPCB26D063002711	5VPCB26DX63004692
5VPCB26D463000475	5VPGB26D263001609	5VPAB26D063002716	5VPGB26D163004727
5VPCB26D563000467	5VPGB26D263001626	5VPGB26D163002699	5VPGB26D463004723
5VPCB26D563000470	5VPAB26D363001608	5VPCB26D163002717	5VPGB26D663004724
5VPGB26D563000485	5VPGB26D363001618	5VPCB26D163002720	5VPGB26D763004733
5VPAB26D563000489	5VPCB26D363001620	5VPAB26D463002718	5VPGB26D863004725
5VPAB26D563000492	5VPGB26D363001621	5VPAB26D463002721	5VPGB26DX63004726
5VPGB26D563000499	5VPAB26D363001642	5VPCB26D563002705	5VPGB26L363004736
5VPCB26D663000476	5VPCB26D463001612	5VPCB26D663002714	5VPGB26L763004738
5VPCB26D763000468	5VPGB26D463001613	5VPAB26D663002719	5VPAB26D563004770
5VPCB26D763000471	5VPGB26D463001627	5VPAB26D663002722	5VPGB26D863004773
5VPGB26D763000486	5VPGB26D463001630	5VPAB26D963002715	5VPAB26D963004769
5VPAB26D763000493	5VPGB26D563001619	5VPGB26DX63002698	5VPGB26D063004797
5VPCB26D863000477	5VPGB26D563001622	5VPCB26DX63002702	5VPGB26D263004798
5VPCB26D863000480	5VPAB26D563001643	5VPCB26D063002725	5VPGB26D463004799
5VPGB26D863000481	5VPGB26D663001614	5VPGB26D063002726	5VPGB26D763004800
5VPGB26D863000500	5VPGB26D663001631	5VPCB26D063002739	5VPGB26D963004796
5VPCB26D963000469	5VPGB26D763001623	5VPAB26D063002747	5VPGB26D163004842
5VPCB26D963000472	5VPCB26D763001636	5VPCB26D163002748	5VPGB26D363004843
5VPAB26D963000494	5VPGB26D863001615	5VPGB26D263002730	5VPGB26D563004844
5VPCB26DX63000478	5VPCB26D863001628	5VPCB26D263002743	5VPGB26D763004845
5VPGB26DX63000482	5VPGB26D863001629	5VPAB26D263002751	5VPGB26D963004846
5VPGB26DX63000501	5VPGB26D963001610	5VPCB26D363002735	5VPGB26D063004895
5VPCB26D063000506	5VPCB26D963001640	5VPGB26D363002736	5VPAB26D063004899
5VPCB26D063000523	5VPCB26DX63001632	5VPCB26D363002752	5VPAB26D063004904
5VPCB26D063000537	5VPGB26DX63001633	5VPAB26D363002757	5VPGB26D163004887
5VPCB26D163000515	5VPAB26D063001646	5VPCB26D463002727	5VPGB26D263004896
5VPCB26D163000529	5VPGB26D163001651	5VPGB26D463002728	5VPAB26D263004905
5VPGB26D163000533	5VPCB26D163001664	5VPAB26D463002749	5VPGB26D363004891
5VPCB26D263000507	5VPGB26D163001665	5VPGB26D563002740	5VPCD26D363004897
5VPCB26D263000510	5VPCB26D163001678	5VPAB26D563002744	5VPAB26D363004900
5VPCB26D263000524	5VPCB26D163001681	5VPAB26D563002761	5VPAB26D463004906
5VPCB26D363000502	5VPAB26D263001647	5VPCB26D663002731	5VPGB26D563004889
5VPCB26D363000516	5VPCB26D263001656	5VPGB26D663002732	5VPAB26D563004901
5VPGB26D363000520	5VPGB26D263001657	5VPCB26D663002745	5VPGB26D563004908
5VPGB26D363000534	5VPCB26D363001648	5VPAB26D663002753	5VPGB26D763004893
5VPCB26D463000508	5VPGB26D363001666	5VPCB26D763002723	5VPAB26D763004902
5VPCB26D463000511	5VPCB26D363001679	5VPGB26D763002724	5VPGB26D763004909
5VPCB26D463000525	5VPCB26D363001682	5VPCB26D763002737	5VPGB26D863004885
5VPCB26D563000503	5VPGB26D463001658	5VPGB26D763002738	5VPAB26D963004903
5VPGB26D563000518	5VPCB26D463001660	5VPAB26D763002759	5VPCB26L963004898
5VPCB26D663000509	5VPGB26D463001661	5VPAB26D763002762	5VPCD26D063004923
5VPCB26D663000512	5VPCB26D563001652	5VPCB26D863002729	5VPAB26D163004930
5VPCB26D663000526	5VPGB26D563001653	5VPCB26D963002741	5VPGB26D163004940
5VPCB26D763000504	5VPGB26D563001667	5VPGB26D963002742	5VPAB26D263004922

5VPGB26D763000519	5VPCB26D563001683	5VPAB26D963002746	5VPGB26D363004910
5VPCB26D763000521	5VPAB26D663001649	5VPCB26DX63002733	5VPAB26D363004928
5VPCB26D763000535	5VPGB26D663001659	5VPGB26DX63002734	5VPAB26D363004931
5VPCB26D863000513	5VPGB26D663001662	5VPCB26DX63002750	5VPGB26D363004938
5VPCB26D863000527	5VPAB26D763001644	5VPAB26DX63002755	5VPGB26D363004941
5VPCB26D863000530	5VPGB26D763001654	5VPCB26D163002765	5VPCD26D463004925
5VPGB26D863000531	5VPCB26D763001684	5VPGB26D163002797	5VPGB26D563004911
5VPCB26D963000505	5VPGB26D863001663	5VPCB26D163002801	5VPAB26D563004929
5VPCB26D963000522	5VPAB26D963001645	5VPGB26D163002802	5VPAB26D563004932
5VPCB26D963000536	5VPGB26D963001655	5VPCB26D263002774	5VPGB26D563004942
5VPCB26DX63000514	5VPCB26D963001668	5VPCB26D363002783	5VPAB26D663004924
5VPCB26DX63000528	5VPGB26D963001669	5VPCB26D463002789	5VPGB26D663004934
5VPGB26DX63000532	5VPGB26DX63001650	5VPCB26D463002792	5VPGB26D763004912
5VPCB26D063000540	5VPCB26DX63001680	5VPCB26D563002798	5VPAB26DX63004926
5VPGB26D063000541	5VPAB26L063001671	5VPGB26D563002799	5VPGB26DX63004936
5VPCB26D063000554	5VPGB26L663001670	5VPGB26D663002794	5VPGB26D063004945
5VPCB26D163000546	5VPGB26L763001676	5VPAB26D663002803	5VPAB26D163004958
5VPGB26D163000547	5VPGB26L963001677	5VPCB26D763002768	5VPCD26D163004977
5VPCB26D263000538	5VPGB26D063001687	5VPCB26D763002771	5VPGB26D263004946
5VPGB26D263000539	5VPCB26D263001690	5VPCB26D863002777	5VPAB26D363004962
5VPCB26D463000542	5VPCB26D363001696	5VPCB26D863002780	5VPGB26D463004947
5VPGB26D463000543	5VPGB26D363001702	5VPGB26D863002800	5VPAB26D463004954
5VPAB26D463000550	5VPAB26D363001723	5VPAB26D863002804	5VPAB26D563004963
5VPCB26D463000556	5VPGB26D463001708	5VPCB26D963002786	5VPGB26D663004979
5VPCB26D563000548	5VPGB26D463001711	5VPCB26DX63002795	5VPGB26D763004943
5VPGB26D563000549	5VPGB26D563001720	5VPGB26DX63002796	5VPAB26D763004964
5VPCB26D563000551	5VPAB26D563001724	5VPGB26L063002782	5VPAB26D863004956
5VPCB26D863000544	5VPGB26D763001699	5VPGB26L463002770	5VPGB26D963004944
5VPGB26D863000545	5VPGB26D763001721	5VPGB26L563002776	5VPAB26D963004965
5VPCB26D963000553	5VPCB26D863001693	5VPGB26L863002769	5VPAB26DX63004960
5VPGB26D063000586	5VPCB26D963001685	5VPGB26L963002781	5VPGB26L363004980
5VPGB26D463000574	5VPGB26D963001686	5VPGB26LX63002787	5VPGB26L763004948
5VPGB26D563000583	5VPGB26D963001705	5VPCB26D063002837	5VPGB26L763004982
5VPCB26D663000557	5VPGB26D963001722	5VPCB26D063002840	5VPGB26L963004949
5VPGB26D663000589	5VPAB26L163001694	5VPCB26D163002815	5VPCB26D063005009
5VPCB26DX63000559	5VPAB26L663001688	5VPAB26D163002823	5VPCB26D263004993
5VPGB26DX63000577	5VPAB26L663001691	5VPGB26D163002847	5VPCD26D263005023
5VPGB26DX63000580	5VPAB26L863001689	5VPAB26D263002829	5VPCB26D363004999
5VPGB26D163000595	5VPAB26L863001692	5VPAB26D263002832	5VPCB26D363005005
5VPCB26D163000613	5VPGB26D063001740	5VPGB26D263002842	5VPCD26D363005015
5VPAB26D163000618	5VPCB26D063001767	5VPAB26D363002838	5VPCB26D363005022
5VPAB26D163000621	5VPCB26D163001731	5VPAB26D363002841	5VPCD26D563005016
5VPCB26D263000605	5VPAB26D163001753	5VPGB26D363002848	5VPCB26D663004995
5VPGB26D263000606	5VPCB26D263001737	5VPAB26D463002833	5VPCB26D663005001
5VPGB26D363000601	5VPGB26D263001741	5VPCB26D563002834	5VPCB26D763005007
5VPCB26D363000614	5VPAB26D263001745	5VPAB26D563002839	5VPCB26D963004991
5VPAB26D363000619	5VPCB26D363001729	5VPGB26D563002849	5VPCB26D963005008
5VPAB26D363000622	5VPCB26D363001732	5VPCB26D663002843	5VPCB26DX63004997
5VPGB26D463000607	5VPGB26D363001733	5VPGB26D663002844	5VPCB26DX63005003
5VPGB26D463000610	5VPCB26D463001738	5VPCB26D763002818	5VPCD26DX63005013

5VPCB26D463000623	5VPGB26D463001739	5VPCB26D763002821	5VPCD26L563005010
5VPCB26D563000615	5VPGB26D463001742	5VPCB26D763002852	5VPGB26D163005053
5VPGB26D663000592	5VPAB26D563001755	5VPAB26D863002835	5VPGB26D363005054
5VPGB26D763000598	5VPAB26D663001747	5VPGB26D863002845	5VPGB26D663005047
5VPCB26D763000602	5VPCB26D763001734	5VPAB26D963002830	5VPGB26D663005050
5VPGB26D763000603	5VPGB26D763001735	5VPCB26DX63002828	5VPCD26D663005056
5VPCB26D763000616	5VPAB26D863001751	5VPCB26DX63002831	5VPCB26D763005055
5VPAB26D763000624	5VPGB26D963001736	5VPAB26DX63002836	5VPCD26D863005057
5VPCB26D863000608	5VPAB26D963001743	5VPGB26DX63002846	5VPCD26D963005049
5VPGB26D863000609	5VPAB26D963001757	5VPGB26L463002851	5VPCB26DX63005048
5VPCB26D863000611	5VPCB26DX63001730	5VPAB26D063002876	5VPGB26DX63005052
5VPCB26D863000625	5VPAB26DX63001749	5VPCB26D263002855	5VPCD26DX63005061
5VPGB26D963000604	5VPAB26L163001761	5VPAB26D263002877	5VPGB26L563005046
5VPCB26D963000617	5VPAB26L363001759	5VPAB26D263002880	5VPCD26D063005067
5VPCB26D963000620	5VPAB26L363001762	5VPAB26D263002894	5VPCB26D163005066
5VPCB26DX63000612	5VPAB26L563001763	5VPCB26D363002864	5VPGB26D163005098
5VPCB26DX63000626	5VPAB26L763001764	5VPAB26D463002878	5VPGB26D263005062
5VPCB26D063000635	5VPAB26LX63001760	5VPAB26D663002879	5VPCD26D363005063
5VPCB26D163000627	5VPCB26D063001770	5VPAB26D763002874	5VPGB26D363005099
5VPCB26D163000644	5VPCB26D063001798	5VPCB26D863002858	5VPCD26D463005069
5VPAB26D163000649	5VPCB26D063001803	5VPCB26D863002861	5VPCD26D563005064
5VPAB26D163000652	5VPCB26D163001793	5VPAB26D863002883	5VPCB26D563005068
5VPCB26D263000636	5VPCB26D263001771	5VPCB26D963002867	5VPGB26D963005074
5VPCB26D363000628	5VPCB26D263001785	5VPAB26D963002875	5VPGB26DX63005097
5VPGB26D363000646	5VPCB26D263001799	5VPAB26DX63002884	5VPGB26D663005114
5VPAB26D363000653	5VPCB26D263001804	5VPCB26L063002893	5VPGB26D863005115
5VPCB26D463000637	5VPCB26D363001777	5VPCB26L563002873	5VPAB26L563005117
5VPCB26D563000629	5VPCB26D363001794	5VPCB26L563002887	5VPAB26L763005118
5VPCB26D563000632	5VPCB26D463001769	5VPCB26L563002890	5VPAB26L763005121
5VPGB26D563000647	5VPCB26D463001805	5VPGB26L863002853	5VPGB26D063005156
5VPCB26D663000638	5VPAB26D563001772	5VPGB26LX63002854	5VPGB26D163005165
5VPCB26D663000641	5VPCB26D563001781	5VPCB26LX63002870	5VPGB26D263005157
5VPGB26D763000648	5VPCB26D563001795	5VPAB26D063002926	5VPGB26D263005160
5VPAB26D763000655	5VPCB26D563001800	5VPCB26D163002913	5VPGB26D363005152
5VPAB26D863000650	5VPCB26D663001773	5VPCB26D263002919	5VPGB26D463005158
5VPCB26D963000634	5VPCB26D663001787	5VPCB26D263002922	5VPGB26D463005161
5VPAB26DX63000651	5VPCB26D663001790	5VPAB26D263002927	5VPGB26D563005153
5VPGB26D063000684	5VPCB26D763001779	5VPAB26D263002930	5VPGB26D563005167
5VPGB26D163000662	5VPCB26D763001796	5VPCB26D463002923	5VPGB26D663005159
5VPGB26D163000676	5VPCB26D763001801	5VPAB26D463002928	5VPGB26D663005162
5VPGB26D263000668	5VPCB26D863001791	5VPAB26D463002931	5VPGB26D763005154
5VPGB26D263000671	5VPCB26D863001807	5VPCB26D663002910	5VPGB26D763005168
5VPGB26D263000685	5VPCB26D963001783	5VPAB26D663002929	5VPGB26D863005163
5VPGB26D363000680	5VPCB26D963001797	5VPAB26D663002932	5VPGB26D963005155
5VPAB26D463000659	5VPCB26D963001802	5VPCB26D763002916	5VPGB26DX63005164
5VPGB26D463000686	5VPAB26D963001810	5VPAB26D863002933	5VPGB26D063005206
5VPGB26D563000678	5VPCB26DX63001775	5VPAB26D963002925	5VPCD26D163005174
5VPGB26D563000681	5VPCB26DX63001789	5VPAB26DX63002934	5VPCD26D163005207
5VPGB26D663000687	5VPCB26DX63001792	5VPCB26L163002904	5VPGB26D563005203
5VPGB26D663000690	5VPCB26L063001811	5VPCB26L463002895	5VPCD26D563005209

5VPGB26D763000665	5VPAB26L263001784	5VPCB26L663002901	5VPGB26D763005204
5VPGB26D763000682	5VPCB26L263001809	5VPCB26L763002907	5VPGB26D963005205
5VPGB26D863000674	5VPAB26L363001776	5VPCB26LX63002898	5VPAB26D063005230
5VPGB26D863000688	5VPAB26L563001780	5VPCB26D063002949	5VPAB26D163005222
5VPGB26D863000691	5VPAB26L663001786	5VPCB26D063002952	5VPAB26D263005228
5VPGB26D963000683	5VPAB26L763001778	5VPGB26D063002970	5VPAB26D463005232
5VPGB26DX63000689	5VPAB26L963001782	5VPCB26D163002958	5VPAB26D563005224
5VPGB26DX63000692	5VPAB26LX63001774	5VPCB26D163002961	5VPCD26D763005213
5VPGB26D063000717	5VPAB26LX63001788	5VPGB26D263002954	5VPAB26D963005226
5VPGB26D063000720	5VPGB26D063001835	5VPCB26D263002967	5VPAB26D063005258
5VPGB26D163000693	5VPAB26D163001817	5VPGB26D263002968	5VPAB26D063005261
5VPGB26D163000726	5VPAB26D163001820	5VPGB26D263002971	5VPAB26D163005253
5VPGB26D263000699	5VPGB26D363001828	5VPGB26D363002963	5VPAB26D263005259
5VPGB26D363000694	5VPGB26D363001831	5VPCB26D463002937	5VPAB26D263005262
5VPGB26D463000705	5VPAB26D463001813	5VPCB26D463002940	5VPAB26D363005254
5VPGB26D563000695	5VPAB26D563001819	5VPGB26D463002969	5VPAB26D463005263
5VPGB26D563000714	5VPAB26D563001822	5VPGB26D463002972	5VPAB26D563005255
5VPGB26D663000723	5VPGB26D563001829	5VPCB26D563002946	5VPAB26D763005256
5VPGB26D963000702	5VPGB26D563001832	5VPCB26D663002955	5VPAB26D963005257
5VPGB26DX63000708	5VPAB26D663001814	5VPGB26D763002951	5VPAB26D963005260
5VPGB26DX63000711	5VPAB26D763001823	5VPCB26D763002964	5VPAB26DX63005252
5VPGB26D263000735	5VPGB26D863001825	5VPGB26D763002965	5VPAB26D063005292
5VPGB26D363000744	5VPGB26D863001839	5VPGB26D863002957	5VPAB26D163005298
5VPGB26D463000753	5VPGB26D963001834	5VPGB26D863002960	5VPAB26D163005303
5VPGB26D563000759	5VPAB26DX63001816	5VPCB26D863002973	5VPAB26D463005294
5VPGB26D563000762	5VPGB26DX63001826	5VPGB26D963002966	5VPAB26D563005286
5VPGB26D763000732	5VPGB26L063001812	5VPCB26DX63002943	5VPAB26D663005300
5VPGB26D863000738	5VPGB26L163001818	5VPCB26DX63002974	5VPAB26D763005290
5VPGB26D863000741	5VPGB26L263001830	5VPGB26L163002953	5VPAB26D863005296
5VPGB26D963000747	5VPCB26L363001821	5VPCB26L463002959	5VPAB26D963005288
5VPGB26D963000750	5VPGB26L363001836	5VPCB26L463002962	5VPAB26DX63005302
5VPGB26DX63000756	5VPCB26L463001827	5VPGB26L663002950	5VPAB26D163005334
5VPGB26D063000765	5VPCB26L563001853	5VPCB26L963002956	5VPAB26D263005343
5VPGB26D063000782	5VPGB26L663001815	5VPCB26D063002983	5VPAB26D363005335
5VPGB26D163000774	5VPGB26L863001833	5VPCB26D063003003	5VPAB26D463005330
5VPGB26D163000788	5VPCB26L963001824	5VPCB26D063003017	5VPAB26D663005331
5VPAB26D163000800	5VPAB26D263001857	5VPCB26D163002989	5VPAB26D763005337
5VPAB26D363000796	5VPAB26D263001860	5VPCB26D163002992	5VPAB26D763005340
5VPGB26D463000767	5VPGB26D263001870	5VPAB26D163002997	5VPAB26D863005332
5VPGB26D463000770	5VPAB26D363001866	5VPCB26D163003009	5VPAB26D963005338
5VPGB26D463000784	5VPAB26D463001858	5VPCB26D163003012	5VPAB26D963005341
5VPGB26D563000776	5VPAB26D463001861	5VPAB26D263002975	5VPAB26DX63005333
5VPAB26D563000802	5VPGB26D463001871	5VPCB26D263002984	5VPCB26L263005357
5VPGB26D763000780	5VPGB26D663001869	5VPCB26D263002998	5VPCB26L363005349
5VPAB26D763000798	5VPGB26D663001872	5VPCB26D263003004	5VPCB26L563005353
5VPGB26D863000772	5VPAB26D863001863	5VPCB26D363003013	5VPCB26L763005354
5VPGB26D863000786	5VPGB26D863001873	5VPAB26D463002976	5VPCB26LX63005347
5VPGB26D963000778	5VPAB26DX63001864	5VPCB26D463002985	5VPCB26D063005379
5VPAB26D963000804	5VPCB26L063001856	5VPCB26D463003005	5VPCB26D363005375
5VPGB26L063000790	5VPCB26L163001865	5VPCB26D563002977	5VPCB26D663005368

5VPGB26L463000792	5VPCB26L663001859	5VPCB26D563002980	5VPCB26D663005371
5VPGB26L863000794	5VPCB26L663001862	5VPAB26D563002999	5VPCB26D763005377
5VPGB26D063000815	5VPGB26D063001883	5VPCB26D563003014	5VPCB26D863005369
5VPCB26D063000828	5VPAB26D063001887	5VPCB26D663002986	5VPCB26D963005378
5VPGB26D063000829	5VPAB26D063001890	5VPAB26D663003000	5VPCB26DX63005373
5VPCB26D063000831	5VPGB26D163001875	5VPCB26D663003006	5VPAB26D163005415
5VPGB26D063000832	5VPAB26D163001879	5VPCB26D763002995	5VPAB26D263005410
5VPCB26D063000845	5VPAB26D163001882	5VPCB26D763003001	5VPAB26D363005416
5VPGB26D163000824	5VPGB26D163001889	5VPCB26D763003015	5VPAB26D463005411
5VPCB26D163000837	5VPGB26D163001892	5VPAB26D863002978	5VPAB26D563005417
5VPCB26D163000840	5VPAB26D263001888	5VPAB26D863002981	5VPAB26D663005412
5VPAB26D263000806	5VPAB26D263001891	5VPCB26D863002987	5VPAB26D763005418
5VPGB26D263000833	5VPGB26D263001898	5VPCB26D863002990	5VPAB26D863005413
5VPCB26D263000846	5VPGB26D363001876	5VPCB26D863003007	5VPAB26DX63005414
5VPGB26D363000839	5VPGB26D563001877	5VPCB26D863003010	5VPAB26D063005437
5VPGB26D463000817	5VPGB26D563001880	5VPCB26D963003016	5VPAB26D163005429
5VPGB26D463000820	5VPAB26D563001884	5VPAB26DX63002979	5VPAB26D163005432
5VPAB26D463000841	5VPGB26D663001886	5VPAB26DX63002982	5VPCB26D163005441
5VPCB26D463000847	5VPAB26D663001893	5VPCB26DX63002988	5VPAB26D163005463
5VPGB26D563000812	5VPAB26D763001885	5VPAB26DX63003002	5VPAB26D363005433
5VPCB26D563000825	5VPGB26D763001895	5VPCB26DX63003008	5VPCB26D363005439
5VPGB26D563000826	5VPGB26D963001901	5VPCB26DX63003011	5VPAB26D363005464
5VPGB26D663000818	5VPGB26DX63001874	5VPCB26L063002991	5VPAB26D563005434
5VPGB26D663000821	5VPAB26DX63001878	5VPCB26L463002993	5VPAB26D563005465
5VPCB26D663000834	5VPAB26DX63001881	5VPCB26L663002994	5VPAB26D663005460
5VPGB26D663000835	5VPGB26D163001908	5VPGB26L863002996	5VPAB26D763005435
5VPAB26D663000842	5VPGB26D163001911	5VPCB26D063003020	5VPAB26D763005466
5VPGB26D763000827	5VPGB26D263001903	5VPCB26D063003034	5VPAB26D863005430
5VPGB26D763000830	5VPCB26D263001916	5VPCB26D063003048	5VPAB26D863005461
5VPCB26D763000843	5VPGB26D263001917	5VPCB26D063003051	5VPAB26D963005436
5VPGB26D863000836	5VPGB26D263001920	5VPCB26D163003026	5VPAB26DX63005431
5VPGB26D963000814	5VPAB26D263001938	5VPCB26D163003043	5VPCB26DX63005440
5VPGB26DX63000823	5VPAB26D263001941	5VPCB26D163003057	5VPAB26DX63005459
5VPAB26DX63000844	5VPGB26D363001909	5VPCB26D163003060	5VPAB26DX63005462
5VPGB26L463000808	5VPGB26D363001912	5VPCB26D263003018	5VPAB26D063005499
5VPGB26L463000811	5VPCB26D363001925	5VPCB26D263003035	5VPCB26L563005501
5VPGB26L663000809	5VPGB26D363001926	5VPCB26D263003052	5VPCB26L763005502
5VPCB26D063000862	5VPGB26D463001904	5VPCB26D363003027	5VPCB26L963005503
5VPAB26D063000867	5VPGB26D463001918	5VPCB26D363003030	5VPCB26LX63005476
5VPCB26D063000876	5VPGB26D463001921	5VPCB26D363003044	5VPGB26D063005545
5VPCB26D163000854	5VPCB26D463001934	5VPCB26D463003019	5VPCB26D163005519
5VPCB26D163000868	5VPAB26D463001939	5VPCB26D463003022	5VPCB26D163005522
5VPCB26D163000885	5VPAB26D463001942	5VPCB26D463003036	5VPGB26D263005546
5VPAB26D263000871	5VPGB26D663001905	5VPCB26D563003028	5VPCB26D363005523
5VPCB26D263000880	5VPCB26D763001913	5VPCB26D563003031	5VPGB26D363005524
5VPCB26D363000872	5VPGB26D763001914	5VPCB26D663003023	5VPGB26D463005547
5VPAB26D363000877	5VPAB26D763001935	5VPCB26D663003040	5VPCB26D663005550
5VPCB26D363000886	5VPGB26D863001906	5VPCB26D663003054	5VPCB26D863005517
5VPCB26D463000850	5VPCB26D863001919	5VPCB26D763003032	5VPCB26D863005520
5VPCB26D463000864	5VPCB26D863001922	5VPCB26D763003046	5VPCB26D863005548

5VPAB26D463000869	5VPGB26D863001923	5VPCB26D863003024	5VPGB26D963005544
5VPCB26D463000878	5VPGB26D963001915	5VPCB26D863003038	5VPCB26DX63005521
5VPCB26D463000881	5VPCB26D963001928	5VPCB26D863003055	5VPCB26DX63005549
5VPCB26D563000856	5VPCB26D963001931	5VPCB26D963003047	5VPCB26L063005518
5VPCB26D563000887	5VPAB26D963001936	5VPCB26D963003050	5VPCB26L763005516
5VPCB26D663000848	5VPGB26DX63001907	5VPCB26DX63003039	5VPCB26D063005561
5VPCB26D663000851	5VPGB26DX63001910	5VPCB26DX63003042	5VPGB26D063005576
5VPAB26D663000873	5VPGB26DX63001924	5VPAB26D063003073	5VPCB26D163005567
5VPCB26D663000879	5VPCB26DX63001937	5VPAB26D163003079	5VPGB26D163005571
5VPCB26D663000882	5VPCB26DX63001940	5VPAB26D163003082	5VPAB26D163005592
5VPCB26D763000860	5VPCB26L163001929	5VPCB26D263003066	5VPCB26D263005559
5VPCB26D763000874	5VPCB26L163001932	5VPAB26D263003074	5VPCB26D263005562
5VPCB26D763000888	5VPCB26L363001933	5VPCB26D263003097	5VPCB26D363005568
5VPCB26D863000849	5VPCB26L863001927	5VPGB26D263003098	5VPGB26D363005569
5VPCB26D863000852	5VPCB26L863001930	5VPCB26D363003075	5VPGB26D363005572
5VPCB26D863000866	5VPCB26D063001946	5VPAB26D363003083	5VPAB26D363005593
5VPCB26D863000883	5VPGB26D063001947	5VPCB26D463003084	5VPCB26D463005563
5VPCB26D963000858	5VPCB26D163001969	5VPAB26D563003070	5VPGB26D563005573
5VPCB26DX63000853	5VPCB26D163001972	5VPCB26D563003093	5VPAB26D563005594
5VPCB26DX63000870	5VPAB26D163001977	5VPAB26D663003076	5VPCB26D663005564
5VPAB26DX63000875	5VPAB26D163001980	5VPCB26D663003099	5VPGB26D763005574
5VPCB26DX63000884	5VPCB26D263001950	5VPCB26D763003063	5VPAB26D763005595
5VPCB26D063000893	5VPGB26D263001951	5VPAB26D763003071	5VPCB26D863005565
5VPCB26D063000909	5VPCB26D263001964	5VPGB26D763003100	5VPCB26D963005560
5VPCB26D163000899	5VPAB26D263001986	5VPCB26D863003069	5VPGB26D963005575
5VPCB26D163000904	5VPCB26D363001956	5VPCB26D863003072	5VPCB26DX63005566
5VPCB26D163000921	5VPGB26D363001957	5VPAB26D863003077	5VPGB26DX63005570
5VPGB26D163000922	5VPCB26D363001973	5VPAB26D863003080	5VPAB26D063005597
5VPCB26D263000894	5VPAB26D363001978	5VPCB26D963003078	5VPAB26D163005639
5VPCB26D263000913	5VPAB26D363001981	5VPCB26D963003081	5VPGB26D263005630
5VPGB26D263000914	5VPCB26D463001948	5VPCB26D963003095	5VPGB26D663005629
5VPCB26D363000905	5VPGB26D463001949	5VPGB26D963003096	5VPAB26D963005596
5VPCB26D363000919	5VPGB26D563001944	5VPCB26DX63003087	5VPAB26DX63005638
5VPCB26D463000895	5VPCB26D563001960	5VPCB26DX63003090	5VPAB26DX63005641
5VPCB26D463000900	5VPGB26D563001961	5VPAB26D063003137	5VPAB26D163005642
5VPCB26D563000906	5VPCB26D563001974	5VPAB26D063003140	5VPAB26D363005643
5VPCB26D663000896	5VPAB26D563001979	5VPCB26D163003124	5VPCD26D863005673
5VPCB26D663000901	5VPAB26D563001982	5VPAB26D163003129	5VPCD26D963005679
5VPCB26D663000915	5VPAB26D663001943	5VPCB26D263003133	5VPGB26L063005651
5VPGB26D663000916	5VPCB26D663001952	5VPAB26D263003138	5VPGB26L263005652
5VPCB26D763000891	5VPGB26D663001953	5VPAB26D263003141	5VPGB26L463005653
5VPCB26D763000907	5VPCB26D663001966	5VPGB26D363003109	5VPGB26L663005654
5VPCB26D763000910	5VPCB26D763001958	5VPCB26D363003139	5VPAB26D263005715
5VPCB26D863000897	5VPGB26D763001959	5VPCB26D463003103	5VPCD26D563005713
5VPCB26D863000902	5VPCB26D763001975	5VPGB26D463003121	5VPAB26L263005723
5VPGB26D863000920	5VPAB26D763001983	5VPCB26D563003112	5VPGB26L363005711
5VPCB26D963000892	5VPCB26D863001967	5VPGB26D563003127	5VPAB26L663005725
5VPCB26D963000908	5VPCB26D863001970	5VPAB26D563003134	5VPAB26L963005721
5VPCB26D963000911	5VPCB26D963001962	5VPCB26D663003118	5VPAB26LX63005727
5VPGB26D963000912	5VPCB26DX63001954	5VPCB26D763003130	5VPCB26L063005759

5VPCB26DX63000898	5VPGB26DX63001955	5VPAB26D763003135	5VPCB26L363005755
5VPCB26DX63000903	5VPCB26DX63001968	5VPCB26D863003136	5VPCB26L463005747
5VPCB26DX63000917	5VPCB26DX63001971	5VPGB26D963003115	5VPCB26D063005818
5VPGB26DX63000918	5VPAB26DX63001976	5VPGB26D963003132	5VPCB26D963005820
5VPCB26D063000926	5VPCB26L063001985	5VPCB26DX63003106	5VPCB26D963005834
5VPGB26D063000927	5VPGB26L363001965	5VPAB26DX63003131	5VPCB26L163005804
5VPGB26D063000930	5VPCB26L963001984	5VPGB26D063003147	5VPCB26L863005802
5VPCB26D063000943	5VPGB26LX63001963	5VPGB26D063003150	5VPCB26D263005853
5VPCB26D163000935	5VPAB26D163001994	5VPCB26D163003155	5VPCB26D363005845
5VPCB26D163000949	5VPCB26D263002001	5VPGB26D263003148	5VPCB26D363005859
5VPGB26D263000928	5VPAB26D363001995	5VPGB26D263003151	5VPCB26D463005837
5VPGB26D263000931	5VPCB26D363002007	5VPCB26D263003164	5VPCB26D663005855
5VPCB26D263000944	5VPCB26D363002010	5VPGB26D463003149	5VPCB26D763005847
5VPCB26D363000936	5VPAB26D463001990	5VPCB26D763003158	5VPCB26D863005839
5VPCB26D463000945	5VPCB26D463002016	5VPCB26D763003161	5VPCB26DX63005843
5VPCB26D563000937	5VPAB26D663001991	5VPAB26D863003144	5VPCB26DX63005857
5VPCB26D563000940	5VPAB26D863001992	5VPGB26D863003154	5VPCB26D063005866
5VPCB26D663000929	5VPCB26D863001998	5VPCB26D863003167	5VPCB26D163005889
5VPCB26D663000932	5VPCB26D863002004	5VPGB26D963003146	5VPCB26D263005884
5VPCB26D663000946	5VPCB26D963002013	5VPAB26DX63003145	5VPCB26D363005862
5VPCB26D763000938	5VPAB26DX63001993	5VPAB26D063003199	5VPCB26D363005893
5VPCB26D763000941	5VPCB26DX63002019	5VPAB26D063003204	5VPCB26D463005868
5VPCB26D863000933	5VPCB26L463001987	5VPAB26D163003177	5VPCB26D463005885
5VPCB26D863000947	5VPCB26L663001988	5VPAB26D163003180	5VPCB26D763005895
5VPCB26D863000950	5VPCB26L863001989	5VPAB26D263003205	5VPCB26D863005887
5VPCB26D963000939	5VPGB26D163002024	5VPCB26D363003173	5VPCB26DX63005891
5VPCB26D963000942	5VPGB26D263002033	5VPAB26D363003178	5VPCB26D063005897
5VPCB26DX63000934	5VPGB26D363002025	5VPAB26D363003181	5VPAB26D363005917
5VPCB26DX63000948	5VPGB26D363002039	5VPAB26D363003200	5VPCB26D463005899
5VPCB26DX63000951	5VPGB26D463002034	5VPCB26D463003179	5VPAB26D863005914
5VPCB26D163000952	5VPGB26D663002049	5VPCB26D463003182	5VPAB26D163005947
5VPCB26D363000953	5VPGB26D663002052	5VPAB26D463003206	5VPAB26D163005950
5VPCB26D463000959	5VPGB26D763002027	5VPAB26D563003201	5VPGB26D163005960
5VPCB26D463000962	5VPGB26D763002030	5VPAB26D663003174	5VPAB26D263005942
5VPCB26D563000954	5VPGB26D863002022	5VPAB26D663003207	5VPAB26D263005956
5VPCB26D763000955	5VPGB26D863002036	5VPAB26D663003210	5VPGB26D263005966
5VPCB26D963000956	5VPGB26D963002028	5VPAB26D763003183	5VPAB26D363005948
5VPCB26DX63000965	5VPGB26D963002031	5VPAB26D763003202	5VPAB26D463005943
5VPGB26D063001009	5VPGB26DX63002037	5VPCB26D863003170	5VPAB26D563005952
5VPGB26D063001012	5VPGB26DX63002040	5VPAB26D863003175	5VPGB26D563005962
5VPAB26D163001025	5VPCB26D063002062	5VPAB26D863003208	5VPAB26D663005944
5VPCB26D263000992	5VPCB26D163002071	5VPCB26D963003176	5VPAB26D663005958
5VPGB26D263000993	5VPCB26D263002077	5VPAB26D963003184	5VPGB26D663005968
5VPGB26D263001013	5VPCB26D263002080	5VPAB26D963003203	5VPCB26D663005970
5VPAB26D263001017	5VPGB26D363002087	5VPCB26DX63003185	5VPAB26D863005945
5VPAB26D263001020	5VPGB26D363002090	5VPAB26DX63003209	5VPCB26D863005971
5VPCB26D363000998	5VPGB26D563002088	5VPCB26D063003213	5VPAB26D963005940
5VPGB26D363000999	5VPGB26D763002058	5VPCB26D063003227	5VPAB26D963005954
5VPCB26D363001004	5VPCB26D763002074	5VPCB26D163003219	5VPGB26D963005964
5VPGB26D363001005	5VPGB26D963002059	5VPCB26D163003222	5VPAB26DX63005946

5VPAB26D363001026	5VPGB26DX63002085	5VPCB26D163003253	5VPAB26D163006001
5VPGB26D463000994	5VPCB26L063002084	5VPCB26D463003229	5VPAB26D263006007
5VPGB26D463001000	5VPGB26L163002094	5VPCB26D463003232	5VPAB26D263006010
5VPGB26D463001014	5VPCB26L463002086	5VPCB26D563003238	5VPGB26D263006020
5VPAB26D463001018	5VPCB26L563002078	5VPCB26D663003216	5VPAB26D363006002
5VPAB26D463001021	5VPCB26L563002081	5VPCB26DX63003235	5VPAB26D363006016
5VPGB26D563001006	5VPCB26L563002095	5VPCB26DX63003252	5VPAB26D463006008
5VPAB26D563001030	5VPGB26L563002096	5VPCB26D063003258	5VPAB26D463006011
5VPGB26D663001015	5VPGB26L663002091	5VPCB26D063003261	5VPGB26D463006021
5VPAB26D663001019	5VPCB26L763002079	5VPCB26D063003292	5VPAB26D563006017
5VPAB26D663001022	5VPCB26L763002082	5VPCB26D163003267	5VPGB26D663006019
5VPGB26D763000990	5VPCB26L963002083	5VPCB26D163003270	5VPAB26D763006004
5VPAB26D763001031	5VPCB26LX63002089	5VPGB26D163003271	5VPAB26D763006018
5VPCB26D863000995	5VPCB26LX63002092	5VPCB26D263003262	5VPAB26D863006013
5VPGB26D863000996	5VPGB26LX63002093	5VPGB26D263003277	5VPAB26D963006005
5VPCB26D863001001	5VPAB26D563002114	5VPCB26D263003293	5VPAB26DX63006014
5VPGB26D863001002	5VPGB26D563002124	5VPGB26D363003255	5VPAB26D063006037
5VPGB26D863001016	5VPGB26D763002125	5VPCB26D363003268	5VPAB26D163006029
5VPAB26D863001023	5VPGB26D863002117	5VPCB26D463003263	5VPAB26D163006032
5VPGB26D963000991	5VPGB26D863002120	5VPCB26D563003269	5VPAB26D263006038
5VPCB26D963001007	5VPGB26D963002126	5VPCB26D663003264	5VPAB26D363006033
5VPGB26D963001008	5VPAB26DX63002108	5VPGB26D663003279	5VPGB26D563006044
5VPCB26D963001010	5VPAB26DX63002111	5VPCB26D763003256	5VPAB26D663006026
5VPGB26D963001011	5VPGB26D063002127	5VPGB26D763003274	5VPGB26D863006040
5VPGB26DX63000997	5VPGB26D063002130	5VPCB26D863003265	5VPCB26D963006045
5VPGB26DX63001003	5VPCB26D063002143	5VPCB26D063003308	5VPAB26DX63006031
5VPAB26DX63001024	5VPGB26D063002144	5VPCB26D263003309	5VPGB26DX63006041
5VPCB26L563001027	5VPCB26D063002157	5VPCB26D363003299	5VPAB26D763006066
5VPCB26L763001028	5VPCB26D163002135	5VPGB26D463003300	5VPAB26D963006067
5VPCB26L963001029	5VPGB26D163002136	5VPCB26D463003313	5VPAB26D863006142
			5VPAB26D163006290

EXAMPLE OF CONSUMER LETTER 06V-xxx

Subject: Recall Campaign - Rear Axle Replacement

2006 Victory Vegas®, Vegas Eight Ball™, Kingpin™, and Kingpin™ Deluxe models.

Warning and Safety Recall Notice 06V-xxx

Reference: Victory Safety Recall Bulletin V-06-02

PLEASE READ IMMEDIATELY

Dear Victory Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2006 Victory motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

The rear axle may crack or break at the retaining plate groove on the right side on the 2006 models listed above. Axle failure during operation could cause a loss of control, increasing the risk of a crash.

What Victory and your dealer will do:

To correct this possible defect, your authorized Victory dealer will replace the rear axle of your motorcycle. Repairs will be made by any authorized Victory motorcycle dealer at no cost to you. The actual repair will take approximately twenty five minutes to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment. Do not attempt repairs yourself. Repairs must be done only by an authorized Victory motorcycle dealer.


DO NOT OPERATE YOUR MOTORCYCLE UNTIL ALL REPAIRS HAVE BEEN COMPLETED!

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you are having difficulty obtaining the recall repair outlined in this letter, please call our Consumer Service department at (763) 417-8650. If you no longer own your motorcycle, please call our Consumer Service department at (763) 417-8650 or write to the address below with the name and address of the new owner.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration at 400 Seventh Street S.W., Washington, D.C. 20590 or call the toll-free safety hotline at 1-888-327-4236 (TTY: 1-888-424-9153).

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,



Christopher Wolf
Manager, Service Dealer Development & Warranty

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days. If you are no longer the owner of the Victory motorcycle indicated by this letter, please contact our Consumer Service department @ 763-417-8650 so we may update our records.

Or write to us at:

Polaris Industries Inc.
Consumer Service Department
2100 Highway 55
Medina, MN 55340-9962

The information contained within this bulletin is confidential and protected by U.S. and international copyright laws, and is the property of Polaris Industries Inc. This service bulletin is provided for the sole use of authorized Polaris dealers and distributors. This service bulletin is not to be distributed, duplicated, or copied, digitally or otherwise, without the written consent of Polaris Industries Inc. © 2006 Polaris Sales Inc.