



**SALEEN**

Corporate Office

76 Fairbanks, Irvine, CA 92618, USA

April 28, 2006

**To: Dealer Principal, Sales Manager, and Service Manager**

**Subject: 2005-06 S281 Mustang Front Brake Hoses Recall Campaign**

**Applied Vehicles: 2005-06 Saleen S281 (with 14" or 15" brake upgrade)**

**Applied Serial Numbers: Vehicles built between 05-0010 and 06-1152**

**Introduction**

Saleen, Inc. has determined that a noncompliance which relates to motor vehicle safety exists in certain 2005 and 2006 Saleen S281 vehicles with upgraded Saleen brake systems. These vehicles have front stainless steel braided brake lines which may fail, possibly resulting in a crash.

**Vehicle Sales Hold**

If you have Saleen vehicles that fall within the above noted serial numbers, do not sell or test drive these vehicles until they are correctly repaired.

**Parts Availability**

A repair kit containing all parts to correctly repair the affected vehicles is currently available from Saleen. The part number is 10-2605-B14196\*.

**Repair Instructions**

Interim repair instructions to correctly repair the affected vehicles will be provided to your dealership on 5/1/06.

**Recall Campaign Bulletin**

Saleen will issue a recall campaign bulletin shortly after you receive the interim repair instructions.

Saleen sincerely apologizes for any inconvenience this situation may present. However the safety of our customers is a top priority in this matter.

If you have any questions, please contact Saleen through one of the following methods:

- Email Scott Kennedy ([skennedy@saleen.com](mailto:skennedy@saleen.com))
- Fax Saleen Warranty (949.457.0859)
- Call Saleen Techline (949.597.3819)