



Mack Trucks, Inc.

Safety Recall ALERT

SEP 25 PM 1:59
NATION

Date: September 18, 2006 **Number:** SRA-500-001
To: All U.S. & Canadian Distributors
Attention: Service Manager, Warranty Manager, Parts Manager, Dealer Principal
From: Regulatory Affairs Department
Subject: Safety Recall, SC0316, Brake Cam Lube

Safety Recall Summary:

On certain Mack model vehicles (CHN, CXN, and CXP) manufactured from May 8, 2006 through June 7, 2006, there exists the potential that steer and drive axle brake cams may have not been greased and therefore may be subject to corrosion. If the brake cam journals corrode and are left untreated, the brakes may drag.

The number of vehicles affected is approximately 1,102 (946 US, 87 Canada and 69 Export).

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Repair Instructions are tentatively scheduled for release no later than September 18, 2006.
- Vehicle list is posted on the Trucks Dealer Portal.
- Owner Notices are scheduled to be mailed on September 25, 2006.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.