

**GM SERVICE AND PARTS OPERATIONS
DCS1663
URGENT - DISTRIBUTE IMMEDIATELY**

Date: October 16, 2006

Subject: Upcoming Safety Recall 06133
Fuel Line and Fuse Block

Models: 2007 Chevrolet Aveo Sedan Equipped with 1.6L Engine

To: All Chevrolet Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Service Manager,
Used Car Manager, Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a safety recall involving certain 2007 Chevrolet Aveo sedan vehicles equipped with a 1.6L engine.

In a severe frontal crash test, the fuel line in the engine compartment developed a fracture. In addition, the crash damage caused four short circuits in the fuse block, the combination of which allowed the fuel pump to continue running and fuel leaked onto the ground. If these conditions occurred in an actual crash, a vehicle fire could occur if a sufficient amount of fuel leaked and an ignition source were present.

To correct this condition, dealers are to replace the fuse block and install a new section of fuel line that has been redesigned.

Approximately 18,000 vehicles are involved and GM is working with its suppliers to obtain the required parts as quickly as possible. Customer notification is scheduled to begin in November 2006.

GM Vehicle Inquiry System (GMVIS) information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE

GM SERVICE AND PARTS OPERATIONS