

**DETROIT DIESEL**

**CORPORATION**



Attention Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Detroit Diesel Corporation (DDC) has decided that a defect which relates to motor vehicle safety exists within the low-pressure natural gas regulator gasket on Series 50G engines in 2002-2004 Orion V and 2002-2005 Orion VII transit buses.

Coolant impinging on alternator terminals could occur and result in a fire within the engine compartment.

Records available to us indicate that your vehicle is equipped with one of these affected engines. DDC will repair your engine at no charge to you by replacing the low-pressure fuel regulator gasket to prevent the possibility of a potential fire and engine damage. We estimate that it will take approximately **2.4 hours** to repair your engine. Please contact your local Authorized Detroit Diesel Repair Facility to arrange a service date.

If you have any questions about this recall campaign, you may call 313-592-3708. If you believe that DDC has failed or is unable to remedy the defect without charge within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you had this reprogramming done before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information, contact Warranty Administration at Detroit Diesel Corporation, 13400 Outer Drive West, Detroit, MI 48239 or call (313) 592-5791.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your continued satisfaction with our products.

**DETROIT DIESEL CORPORATION  
CAMPAIGN BULLETIN 06C-3  
SERVICE ADMINISTRATION CAMPAIGN COORDINATOR (BX-5)**