

October 12, 2006

DEFECT NOTIFICATION

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act of U.S.A.

Prévost Car Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2004-2005 H3-45 VIP equipped with ISS and in certain 2004-2005 XLII Vehicles equipped with ISS. Prévost Car Inc., as coach manufacturer, has recently noticed that:

On the above-mentioned vehicles, material that does not meet Prévost Car requirements may have been installed on the independent front suspension. Overheating of the bell crank and idler arm mounting spindles during the forging process has significantly weakened the material, therefore, requiring replacement. In certain heavy loading conditions these defective parts could break, resulting in a loss of steering control which could result in a crash.

For more information on this recall or technical assistance on how to perform this safety recall, please contact your service manager or the nearest service center.

Model	Serial Numbers
H3-45 VIP equipped with ISS Model Year : 2004 - 2005	From 2PCV3349641014793 up to 2PCV3349851010116 incl.
XLII Vehicles equipped with ISS Model Year : 2004 - 2005	From 2PCY3349741028215 up to 2PCY3349951028539 incl.

CORRECTIVE ACTIONS:

You must refer to the enclosed Safety Recall no. 06-07 and perform the stated procedure. Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

REPORTING REQUIREMENT:

In order to verify and document the corrective action taken on your vehicle(s) pursuant to the requirements of the Federal Motor Vehicle Safety Regulations, we are enclosing a "**SAFETY RECALL CERTIFICATION**" sheet. When the vehicle(s) is (are) repaired, this (these) sheet(s) must be completed and returned to PRÉVOST CAR INC. head office.

LABOR & PARTS REIMBURSEMENT:

Prévost Car Inc. will reimburse you parts and labor incurred.


Federal laws require that you be informed of your right to notify the Department of Transportation if you are unable to have the defect remedied without charge. The address for this purpose is:

National Highway Traffic Safety Administration
Washington, DC 20590
USA
Auto Safety Hotline: 1-888-327-4236.

If any assistance is required, please contact your local distributor or the PRÉVOST CAR INC. after sales service department.

We regret any inconvenience which this situation may cause you. However, we are concerned about your safety; rest assured that PRÉVOST CAR INC. is making all efforts to remedy the defect as quickly as possible in the interest of motor vehicle safety.

Truly yours,



Josyane Côté, Eng.
Technical Publications Manager.