



COUNTRY COACH

Mr. George Person
Chief, Recall Management Office
National Highway Traffic Safety Adm.
400 7th Street, S.W.
Washington, D.C. 20590

10 August 2006

Dear Mr. Person:

The mailing of the Customer and Dealer Notifications for Recall 06V-285 began and was completed on August 8th. As required, copies of the final notifications are being faxed for your files. Should you require original copies please contact Karen McDonnell at kmcdonnall@countrycoach.com.

Please feel free to contact me at 541-998-3720 x8382 should you have any questions.

Sincerely,

Dick Sabath
Senior Manager, Compliance Administration
Country Coach Inc.

Enclosures (2) Customer Notification, 06V-285
Dealer Notification, 06V-285

2006 AUG 16 11:57

RECEIVED

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448



COUNTRY COACH

VIA: CERTIFIED MAIL, RETURN RECEIPT REQUESTED,
AND FIRST CLASS MAIL

August 7, 2006

RE: VEHICLE SAFETY DEFECT OWNER NOTIFICATION, 06V-285

Dear Country Coach Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

DESCRIPTION OF SAFETY DEFECT:

Prevost Car Inc. has decided that certain bus shells converted to motor homes by Country Coach Inc. may have a safety defect in the exhaust system of the Detroit Diesel Series 60 Motor Home engine. The turbocharger could fail, allowing lubricating oil to enter the exhaust system. This can result in a fire in the engine compartment.

MODELS AFFECTED:

Model Year: 2001

VIN Range: 2PCW33495Y1027187

Model Year: 2005

VIN Range: 2PCW3349941028322 – 2PCW3349X51028377

Model Year: 2006

VIN Range: 2PCW339251028390 – 2PCW3349151028686

Model Year: 2007

VIN Range: 2PCW3349X51028721 – 2PCW3349861028791

Not all units within these VIN ranges are affected. Please refer to the attached Listing for specific units.

The attached Detroit Diesel Corporation notification directs that all necessary repairs to be made by an authorized Detroit Diesel distributor. All reimbursements for labor and parts will be processed through the Detroit Diesel Corporation. If your vehicle is equipped with one of the affected engines, Detroit Diesel Corporation will reprogram the ECM to prevent the possibility of a turbocharger failure. It is estimated that this will take 0.5 hours. In addition, certain model year engines will need to have a barometric processor sensor and pigtail harnesses installed. The estimated time for this repair is approximately 1.0 hours. Please contact your nearest Detroit Diesel Corporation as soon as possible to arrange a service date. When you take your motor home in to be serviced present this letter. If you need assistance in locating the nearest Detroit Diesel Corporation service facility, please contact Country Coach's customer service department at 1-800-452-8015.

THE WORLD'S FINEST MOTORCOACHES

135 East First Avenue | PO Box 400 | Junction City, OR 97448

You may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of a problem associated with this recall. For more information regarding this contact Detroit Diesel Corporation at 313-592-5791.

Country Coach bus conversion dealers have been notified of this recall. If your dealer or the service facility fails to remedy the noncompliance on the agreed upon service date or within three (3) days of the scheduled service date, please contact Detroit Diesel Corporation at 313-592-5791 for further assistance.

If after contacting both your dealer/service facility and Prevost Car Inc. you are not satisfied that the noncompliance has been remedied within a reasonable time at no cost to you, you may wish to contact the National Highway Traffic Safety Administration at the following address or call the Auto Safety Hotline's toll free number:

Administrator
National Highway Traffic Safety Administration
400 7th Street, S.W.
Washington D.C. 40990

Or call the Vehicle Safety Hotline's toll free number at 1-888-327-4236 (TTY: 1-800-424-9153)

Or go to <http://www.safercar.gov>

Federal regulations requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days after receipt of the original notification.

If you no longer own this motor home, please complete and return the Vehicle Owner Reply Card in the self-addressed postage paid envelope included in this package.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



Dick Sabath
Senior Manager, Compliance Administration

Enclosures (2)