

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date April 28th, 2009
Calendar Quarter 2

Date in (yyyy-mm-dd) format

Manufacturer Prevost
Report Author Dominique Gagnon
Phone 418-331-5432 x 235
E-mail dominique.gagnon@prevost.com

NHTSA Recall Number	Canada DOT recall Number	Prevost Recall #	Description	Date notification to purchasers began	Date notification to purchasers was completed	Safety Recall Quarterly Report ...		April 28th 2009									Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For Internal use only: Nb of years reporting the recall...	Comments	
						From...	Through...	Total Number of Vehicles Involved			Total Number Inspected & Remedied			Completion Rate (%), per country							
								USA	Canada	Total	USA	Canada	Total	USA	Canada	Total					
1	D1V-035	01-086	SR01-03	Front Axle Transversal Radius Rod Attachment Assembly	2001-02-16	2001-02-16	2001-02-16	2009-04-28	241	158	400	130	95	225	54%	60%	56%	0%	0%	8.3	Renotification to customers sent April 2008.
2	05V-107	05-073	SR05-07	Insp. & Repl. Power Steer. Hoses	2005-03-09	2005-03-09	2005-03-09	2009-04-28	472	189	661	301	140	441	64%	74%	67%	0%	0%	4.2	
3	05V-516	05-374	SR05-14A	Windshield Wiper Motor	2005-11-03	2005-11-03	2005-11-03	2009-04-28	122	53	175	96	37	133	79%	70%	76%	0%	0%	3.5	
4	06V-214	06-252	SR06-07A	Bell Crank And Idler Arm Mounting Spindle	2006-06-09	2006-06-09	2006-06-09	2009-04-28	413	35	448	349	28	377	85%	80%	84%	0%	0%	2.9	
5	06V-243	06-251	SR06-10	Bendix SR-7 Spring Brake Valve	2006-11-03	2006-11-03	2006-11-03	2009-04-28	8	1	9	8	0	8	75%	0%	67%	0%	0%	2.5	
6	08V-007	08-008	SR07-10	ZF Trans. Gear Shifter Defect	2008-01-21	2008-01-21	2008-01-09	2009-04-28	385	82	467	172	21	193	45%	26%	41%	0%	0%	1.3	
7	07V-371	07-284	SR07-11	Bendix SR-7 Internal Check Valve Replacement	2007-09-20	2007-09-20	2007-09-20	2009-04-28	673	164	837	494	125	619	73%	76%	74%	0%	0%	1.6	
8	08V-448	08-356	SR08-12	Replacing Weakened Bolts On Roof Escape Hatch	2008-10-20	2008-10-20	2008-10-20	2009-04-28	118	72	190	89	51	140	75%	71%	74%	0%	0%	0.5	
9	08V-597	08-405	SR08-21	Passenger Seats Pedestal Ass. Fixing Screws	2008-12-15	2008-12-15	2008-12-15	2009-04-28	58	23	81	23	6	29	40%	26%	36%	0%	0%	0.4	
10	08V-610	08-430	SR08-22A	Power Steering Hose	SR0822 sent out 2009-03-09	SR0822revA to be sent out 2009-04-29	2009-03-09	2009-04-28	455	182	638	124	13	137	27%	7%	21%	0%	0%	0.1	Revised Campaign to be sent out to customers April 29th 2009.
11	09V-061	n/a, US recall only	SR09-04	REPLAC. LOWER A-ARMS FD. BOLTS	2009-02-20	2009-02-20	2009-02-20	2009-04-28	22	0	22	9	n/a	9	41%	n/a	41%	0%	0%	0.2	Recall only applicable to USA

Comments:

April 28th 2009: no comment

Feb 11th 2009: Please observe that Canada DOT recall number for Prevost Safety recall SR08-22 is 08-430 and not 08-428.