



**Workhorse Custom Chassis**  
P.O. Box 110, 922 South State Route 32  
Union City, IN 47390 USA

navistar.com

A NAVISTAR COMPANY

## SAFETY RECALL 60601-C

JANUARY 2009

### RECALL REMINDER – 2<sup>ND</sup> NOTICE

Dear Workhorse Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

This is a safety recall **follow-up** notification to the initial notice mailed in August 2006. Workhorse's records indicate the vehicle identified on the enclosed Authorization for Recall Service card has not yet had the repair performed. If the repair has been performed, please fill out and return mail the card so you will not be contacted again about this recall.

Workhorse has decided that a defect which relates to motor vehicle safety exists in certain model year 2004, 2005, and 2006 W20, W22, W24, P32, W18, W52, and FE20 chassis models equipped with a GM L18 (8.1 liter) engine.

#### **REASON FOR THIS RECALL**

The clip that retains the engine's fuel rail pulse damper may fracture. Clip fracture could result in inadequate damper support which may cause pressurized fuel to leak onto the engine.

#### **RISK TO MOTOR VEHICLE SAFETY**

A fuel leak may cause a fire possibly resulting in property damage, personal injury, or death.

#### **ACTIONS YOU SHOULD TAKE**

Please contact your Workhorse dealer to schedule an appointment to have your vehicle repaired. Your nearest dealer may be located by calling 1-800-448-7825 or by visiting <http://www.navistar.com>.

The repair will involve replacement of the fuel rail pulse damper retaining clip. Dealers currently have parts and instructions to repair your vehicle. This repair will be performed free of charge and may take approximately 60 minutes to complete.

#### **IF YOU DO NOT OWN THIS VEHICLE**

If you do not own the vehicle identified on the enclosed Authorization for Recall Service card, please fill out and return mail the card so that you will not be contacted again about this recall.

#### **IF YOU NEED ASSISTANCE**

If you believe that Workhorse has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9152) or go to <http://www.safercar.gov>.

#### **LESSOR REQUIREMENTS**

Federal regulations require that any vehicle lessor receiving this Recall Notice forward a copy of it to the lessee within ten days.

#### **REIMBURSEMENT ELIGIBILITY**

If you have previously paid for the repair of this defect you may be entitled to recovery of those expenses. Contact Workhorse at 877-946-7731 to determine your eligibility.

Workhorse requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**Workhorse Custom Chassis, LLC**