



U.S. Department
of Transportation

400 Seventh Street, SW
Washington, DC 20590

**National Highway
Traffic Safety
Administration**

FEB - 5 2007

MR. WILLIAM COLEMAN
RECALL ADMINISTRATOR
BLUE BIRD BODY COMPANY
P.O. BOX 937 CORPORATE
FORT VALLEY, GA 31030

NVS-215kjs
07V-021

Subject: WINDSHIELD WIPER CIRCUIT FAILURE

Dear MR. COLEMAN:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
BLUE BIRD/VISION/2007-2008

NHTSA Campaign Number: 07V-021

Mfg's Report Date: January 25, 2007

Components:
VISIBILITY:WINDSHIELD WIPER/WASHER:SWITCH/WIRING

Potential Number of Units Affected: 882

Summary:
CERTAIN 2007 AND 2008 MY BLUE BIRD VISION SCHOOL BUSES MANUFACTURED BETWEEN OCTOBER 16, 2006, AND JANUARY 18, 2007. CONTINUOUS RESETTING OF THE CIRCUIT BREAKER WHEN THE WIPER/WASHER IS OPERATING IN THE "WASH/WIPE" MODE MAY CAUSE FAILURE IN THE WIRING CIRCUIT RESULTING IN POWER BEING APPLIED TO GROUND WHICH COULD CAUSE THE CIRCUIT BREAKER TO OVERHEAT AND FAIL RESULTING IN A STALLED WIPER.