



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 3, 2007

GARETT CAROLUS
TECHNICAL MANAGER
KEYSTONE RV COMAPNY
2642 HACKBERRY DRIVE
GOSHEN IN 46526

NVS-215dgl
07V-332

Subject: COOKING RANGE/OVEN THERMOSTAT VALVE/SUBURBAN

Dear MR. CAROLUS:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
KEYSTONE/NRG/2007

NHTSA Campaign Number: 07V-332

Mfg's Report Date: June 21, 2007

Components: EQUIPMENT:RECREATIONAL VEHICLE

Potential Number of Units Affected: 16

Summary:

ON CERTAIN TRAVEL TRAILERS EQUIPPED WITH SUBURBAN THREE BURNER MATCH LIGHT GAS RANGES, THE OVEN THERMOSTAT CONTROL VALVE CAN ALLOW GAS FLOW TO THE OVEN BURNER WHEN THE OVEN CONTROL KNOB IS PUSHED IN AND NOT FULLY IN THE CORRECT POSITION TO LIGHT THE PILOT.

Consequence:

IF THE OVEN CONTROL KNOB WAS DEPRESSED FOR SOME TIME BEFORE LIGHTING THE PILOT LIGHT, THE EXCESS GAS IN THE OVEN COULD CAUSE A FLASH AT THE OPENING OF THE OVEN, POSSIBLY RESULTING IN PERSONAL INJURY.

Remedy:

KEYSTONE IS WORKING WITH SUBURBAN TO REPLACE THE OVEN THERMOSTAT CONTROL FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING AUGUST 2007. OWNERS MAY CONTACT SUBURBAN AT 1-423-775-2131 OR KEYSTONE AT 574-537-3925.

Notes:

KEYSTONE RV RECALL NO. 07-089. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

Please provide the following additional information and be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

You are required to provide an estimated date including month, day, and year, when you will send notifications to dealers and distributors as soon as it becomes available.

As stated in your report, Suburban will be handling the remedy and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.6 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Suburban's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement